


Treys Pte Ltd

Business reg. no. 200300905N

 18 Boon Lay Way, #03-108 TradeHub21, Singapore 609966
 Tel : +65 6513 0381 Fax : +65 6465 5015 Email : sales@treys.sg

GMDSS SHORE-BASED MAINTENANCE SERVICE AGREEMENT FOR MAINTENANCE OF GMDSS EQUIPMENT

Between **PT. PAN MARINE WIRA PAWITRA**
(Owner / Ship Management)

And **TREYS PTE LTD**
(Service Company)

For vessel **CB. PAN MARINE 14**

This agreement is valid for the above mentioned company covering **SHORE-BASED MAINTENANCE, GMDSS A1, A2 & A3.**

Referring to the Amendments to the 1974 Convention of the SOLAS GMDSS Regulation concerning radio communication for the Global Maritime Distress and Safety system (SOLAS 88 Regulation IV/15) and as also stated in the IMO Resolution A702 (17).

If there is a defect on the GMDSS products listed in Appendix 1 to the agreement, TREYS PTE LTD shall use one of the possibilities listed below to solve the problem on the usual conditions:

1. forward a replacement to the vessel,
2. arrange repair through the Marine Service Network,
3. send a technician to the vessel from the authorized agent.

The primary method of solving the problem will be to replace the unit, however, with the possibility of a follow-up by a technician.

This agreement shall be valid for 1 years with effect from successful commissioning or upon re-issue of the agreement.

for

Irawan Setiawan
Treys Pte Ltd

Yundi Armada
PT. Pan Marine Wira Pawitra

Date issue : April, 24th 2018
Expired Date : April, 23th 2019

Date : April, 24th 2018
Place : Jakarta - Indonesia

Enclosure
Appendix 1 -

Name/call sign of ship
List of equipment
Area of operation
Method of maintenance

**Treys Pte Ltd**

Business reg no 200300905N

18 Boon Lay Way, #03-108 TradeHub21 Singapore 609966
Tel : +65 6513 0381 Fax : +65 6465 5015 Email : sales@treys.sg**GMDSS SHORE-BASED MAINTENANCE CONTRACT**

Contract validity *	24 APRIL 2018 TO 23 APRIL 2019		
Owner	PAN MARITIME WIRA PAWITRA		
Ship name	CB PAN MARINE 14		
Call sign	YDB 4153	MMSI	525010183

* Contract will be deemed void with immediate effect if ship's flag/ owner/ management is changed

Description	Type
PRIMARY SYSTEMS	
VHF radio installation:	SAMYUNG STR 6000 A
DSC encoder	AS ABOVE
DSC watch keeping receiver	AS ABOVE
Radiotelephony	AS ABOVE
MF/HF radio installation:	SAMYUNG SRG 3150DN
DSC encoder	AS ABOVE
DSC watch keeping receiver	AS ABOVE
Radio telephony	AS ABOVE
Inmarsat Ship Earth Station	-
Remote Distress / Alarm Panel	-
DUPLICATION SYSTEMS:	
VHF radio installation:	ICOM IC M304
DSC encoder	AS ABOVE
DSC watch keeping receiver	AS ABOVE
Radiotelephony	AS ABOVE
Inmarsat Ship Earth Station	-
Remote Distress / Alarm Panel	-
EQUIPMENT FOR RECEPTION OF MSI:	
Navtex receiver	SAMYUNG SNX 300
EGC receiver (Built-in)	
EPIRB:	KANNAD MARINE
RADAR TRANSPONDER	KANNAD MARINE
PORTABLE TWO-WAY RADIO	SAMYUNG STV160

SEA AREAS:
X A1
X A2
X A3
A4
MAINTENANCE:
X Duplication of equipment
X Shore-based maintenance
At sea electronic maintenance