



PT. MULIA SAFETY SERVICE

**INFLATABLE LIFERAFT - FIRE EXTINGUISHER & SYSTEM
LIFEBOAT - FUMIGASI - SHIPPING AGENCY - NDT & UT**



Date of Inspection :	Name of Ship :	Certificate No.
SEPTEMBER 04, 2026	KM. BAHTERA SEVA - III	091/HRU/MSS-TGU/IX/2026
Name of Owner :		
BANK RAKYAT INDONESIA		

Certificate Hydrostatic Release Unit (HRU)

Dengan ini menyatakan bahwa Sertifikasi Hydrostatic Release Unit (HRU) tersebut telah dilakukan Service and Inspection oleh PT Mulia Safety Service sesuai dengan ketentuan pabrik pembuat dan telah memenuhi persyaratan **The International Safety of Life at Sea (SOLAS 74/96)** dan atau sesuai dengan **Amandemen SOLAS'83**

*This is to Certify that above named Hydrostatic Release Unit (HRU) has been Service and Inspected by PT Mulia Safety Service in accordance to the requirements of manufacturer, and complying fully to **The International Safety of Life at Sea (SOLAS 74/96) Conform to The Amandemen SOLAS'83***

No.	Merk	Type	Serial Number	Notife Body No / Year	Expired Date HRU	Remarks
1	SEAMATE	Ve-1	ECO575/7870	-	09 - 2027	Good
2	SEAMATE	Ve-1	ECO575/7871	-	09 - 2027	Good

Testing Record / Pressure Test : 0,4 kg/cm which is equivalent to the operational water depth of 1,5 – 4.0 mtr

Expired Date	SEPTEMBER 04, 2027
---------------------	---------------------------

**SERVICE COMPANY
PT MULIA SAFETY SERVICE**



**ARIF BUDIYANTO
SERVICE ENGINEER**



PT. MULIA SAFETY SERVICE



Head Office : Bumi Wanamukti H1/19, Sambiroto, Tembalang, Semarang 50276

Branch : Batam - Banten - Jakarta - Tegal - Semarang - Jepara - Surabaya - Makassar - Ambon - Luwuk

Telp/Fax : 02925150543 - Call & WA : 0811274443 - Email : cs@muliaservice.id, www.muliaservice.id



CERTIFICATE OF RE-INSPECTION

Certificate No.: 403/ILR/MSS-TGU/IX/2026

This is to certify that the liferaft detailed below has been surveyed, controlled and tested in compliance with requirement from :
and the manufacturer and in accordance with IMO Resolution : A.761 (18)

Inflatable Liferaft

Identification :	Type : KHA-15	Capacity : 15 PERSONS	Serial No. : 10825	Date Of Manufacture : DEC 2018
	Merk : SHANGHAI YOU LONG RUBBER	Length of painter : 25 m/inside 1 m/outside		Max. Stowage Height : 18 m

Cylinders :	Serial Number :	Contents CO ₂ :	Contents N ₂ :	Latest Hyd. Test :
	043992	8.640 KG	1.850 KG	-
	043925	8.640 KG	1.850 KG	-

Equipment :	Unit :	Type :	Serial No. :	Expiry Date :
Emergency Pack :		SOLAS "A" PACK	10825	05 - 2028
EPIRB :		-	-	-
HRU test :		-	-	-
Radar Reflector :		N/A	N/A	N/A
First Aid Kit :		BOX	N/A	09 - 2027

Tests :	NAP-test :	Gas inflation test :	Floor Seam test :	Load test davit launched :
	Yes/No: NO	Yes/No: NO	Yes/No: NO	Yes/No: NO
	Latest Test* : -	Latest Test* : -	Latest Test* : -	Latest Test* : -

*Latest test date (month / year)

Verification :	Date Of Service : SEPT 04, 2026	Service station name and No : PT. MULIA SAFETY SERVICE	Next Service Date : SEPT 04, 2027
----------------	---	--	---

National Marine authority ID No.	Remarks/modification : INFLATABLE LIFERAFT IN GOOD CONDITION
-------------------------------------	--

This inflatable liferaft requires servicing 12 month from the latest inspection date in accordance with the SOLAS regulation.

Name of ship : KM. BAHTERA SEVA - III
Name Of Ship/Owner : BANK RAKYAT INDONESIA
IMO Number : 9897626
International call signal : YB 7703





PT. MULIA SAFETY SERVICE

Head Office : Bumi Wanamukti H1/19, Sambiroto, Tembalang, Semarang 50276

Branch : Tanjung Uban - Banten - Jakarta - Tegal - Semarang - Surabaya - Makassar - Ambon - Luwuk

Telp/Fax : 02925150543 - Call & WA : 0811274443 - Email : cs@muliaservice.id, www.muliaservice.id



LIFERAFT SERVICE REPORT

in Accordance ti IMO Resolution MSC.388(94) Amendment to Resolution A.761(18)

Certificate No. 403/ILR/MSS-TGU/IX/2026

GENERAL PARTICULARS			
Name of Ship	: KM. BAHTERA SEVA - III	Port of Registry	: INDONESIA / MAKASSAR
IMO-No.	: 9897626	Call Sign	: YB 7703
Class	: BKI	MMSI No	: 525500394
Gross Tonnage	: 150	Date of Service	: SEPTEMBER 04, 2026
Kind of Service			
☒ Annual ☐ 5 Yearly ☐ Repair			
Remarks:			
LIFERAFT IN GOOD CONDITION			

Liferaft Mark :	SHANGHAI YOULONG RUBBER	TYPE of Liferaft :	KHA-15
Serial Number :	10825	Capacity :	15 PERSONS
MFG Date :	DECEMBER 2018	Customer :	BANK RAKYAT INDONESIA

CHECKLIST ITEM	OK/ RN/ NA	CHECKLIST ITEM	OK/ RN/ NA	CHECKLIST ITEM	OK/ RN/ NA
* CONTAINER SHELL	-	Inflation Valve, Hose	NA	Repair Kit	OK
Labels/Marking	RN	"T/Y" Piece Connector	OK	Leak Stoppers	OK
Handling Beckets	RN	Protection Pads	OK	Sponges	OK
* Gasket/Strap/Packing List	OK	CO2 Cylinder (s)	OK	Bailers	OK
Painter Line	OK	Operating Cable & Conduit	OK	Spare Sea Anchor	OK
ID Container	NA	Operating Head	OK	Torch, Signaling	OK
* Valise Fabric/ Plastic	NA			Spare Batteries	RN
Eyelets	OK	SURVEY OF INTERIOR		Whistle	OK
Painter Line Pockets	OK	Bouyancies, Fabric	OK	Fishing Kit	OK
Bursting Band	OK	Safety Relief Valves	OK	Can Opener (s)	OK
Strapping	RN	Grabline & patches/loops	OK	Paddles	OK
		Thwart, Fabric	OK	Spare Bulb for Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valve	OK	Drinking Vessel	OK
Bouyancies Fabric	OK	Arches, Fabric	OK	Seasickness Bags	OK
Inlet Valves	OK	Center Column, Fabric	OK	Signal Mirror	OK
Deflation Plugs/ Valves	OK	Light Battery	RN	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	NA
Boarding Ramp	OK	Topping up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridie/ Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (s)	OK	EMERGENCY PACK	
Outer Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration (15 Pack)	OK
Recto Reflective Tape	OK	Inner Floor, Fabric	OK	Exp. Date 05 - 2028	OK
Seam and Taping	OK	Topping up Valves	OK	Drinking Water (45 Pack)	OK
Rain Water Catchment	OK	Deflation Up Valves	OK	Exp. Date 05 - 2028	OK
Exterior Lighting System	OK	Emergency pack Loops/Patch	OK	Smoke Signal (2 PCS)	OK
Arch Deflation Valve	OK	Aerial Socket/Tie-Tapes	OK	Exp. Date 08 - 2029	RN
Entrance Sleeves	OK	Floor Reds	OK	Parachute Signal (4 PCS)	OK
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Exp. Date 08 - 2029	RN
Righting Strap	OK	Knife Sheath	OK	Red hand Flares (6 PCS)	OK
Stabilishing Pockets	OK	Sea Anchor	OK	Exp. Date 08 - 2029	RN
Cylinder Pockets (s)	OK	ACCESSORY BAG		First Aid Kit (1 PCS)	OK
Sea - Cell	OK	Bellows or Pump	OK	Exp. Date 09 - 2027	RN
Painter Lashing/Stowage	OK	Light Stick	NA	Anti Seasickness (90 TAB)	OK

(DKF) Load Test Davit Launch and Raft	NA	Glue for Repair Kit	OK	Exp. Date 09 - 2027	RN
RN = Renew, NA = Not Applicable					

RAFT AND CYLINDER TEST									
PRESSURE TEST	Start			Finish			Pressure Drop (mmHg)	Safety Valves	
	Time	Temp (°C)	Pressure (mmHg)	Time	Temp (°C)	Pressure (mmHg)		Blow off (mmHg)	Reseat (mmHg)
Upper Buoyancy	09.15	29 °C	103	10.15	29 °C	102	1	114	103
Lower Buoyancy	09.30	29 °C	104	10.30	29 °C	103	1	110	104
Floor	-								
Canopy	-								
GAS CYLINDER TEST	Cyl No:	Mfg. Date	Change Date	Weight Of Cyl. Kg	Weight Of CO2 Kg	Weight Of N2 Kg	Total W. kg		
Cylinder No. 1	043992	-	-	-	8.640	1.850	12.680		
Cylinder No. 2	043925	-	-	-	8.640	1.850	12.680		
DAVID LAUNCHABLE RAFT		REMARK	Res A 761 (18)		REMARK		DATE		
Load Test	Date:	-	WP - TEST		YES		09 - 2026		
Suspension Strap/Patches		-	FS - TEST		NO		-		
Shackle		-	NAP - TEST		NO		-		
Steering Line with Patches		-	GI - TEST		NO		-		
Bowsing Line with Patches		-							
Container Line Incl. Pocket		-							
Pocket for Steering/Bowsing Line		-							
Remarks:									

Frequency of test

Servicing Intervals	Test Methods
End of first year	WP test
End of second year	WP test
End of third year	WP test
End of fourth year	WP test
End of fifth year	GI Test
End of sixth year	WP test
End of seventh year	WP test
End of eighth year	WP test
End of ninth year	WP test
End of tenth year	GI test + FS
End of fourteenth year	NAP test + FS
Fifteenth year	GI test + NAP + FS
Sixteenth to nineteenth year	NAP test + FS
Twentieth year	GI test + NAP + FS
Twenty-first to twenty-fourth year	NAP test + FS
Twenty fifth year onwards	GI test + NAP + FS

Keterangan:

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam

 KEPALA SEKSI SYAHBANDAR KANTOR UNIT PENYELENGGARA PELABUHAN KELAS I TANJUNG UBAN ASTRA DEWI WAHYUDI, S.M. NIP. 19750413 200912 1 001	 Approved by LR class & BKI class	
	Surveyor	: ARIF BUDIYANTO
	Next Inspection Date	: SEPTEMBER 04, 2027

Catatan:

- Syahbandar berhak tidak menandatangani *service report* ini apabila *service station* tidak melampirkan **SPK aktif terkait liferaft** yang diterbitkan oleh BTKP



PT. MULIA SAFETY SERVICE

Head Office : Bumi Wanamukti H1 No.19, Sambiroto, Tembalang, Semarang, Jawa Tengah - 50276
Branch : Batam - Banten - Jakarta - Tegal - Semarang - Jepara - Surabaya - Makassar - Ambon - Luwuk
Telp/Fax : 02925150543 - Call & WA : 0811274443 - Email : ptmssgeneral@gmail.com, cs@muliaservice.id,
www.muliaservice.id



Lloyd's
Register

CERTIFICATE OF RE-INSPECTION

Date Of Service	Name of Vessel	Flag	IMO NO	Certificate No.
SEPT 04, 2026	KM. BAHTERA SEVA - III	INDONESIA	9897626	209/FFE/MSS-TGU/IX/2026
Next Service Date	Place Of Service	Name of Owner		
SEPT 04, 2027	ANAMBAS - INDONESIA	BANK RAKYAT INDONESIA		

We hereby certify that the systems and equipment specified below have been inspected and serviced

The Chart reference states the quantity and the letter code of relevant enclosed Serviced Charts

☐	CO2 System & Pilot CO2 System	Chart:	-		
☐	Foam System	☐ CO2 Cylinder For Turbin Compressor	Chart:	-	
☐	Dry Powder System	☐ Smoke Sampling System	Chart:	-	
☒	Portable Fire Extinguishers	Chart:	B1		
☐	Fire Alarm System	☐ CO2 Gulley Duct	Chart:	-	
☐	Gas Detector	☐ Portable	☐ Fixed	Chart:	-
☐	Lifeboat Air System	☐ Medical Oxygen	Chart:	-	
☐	Breathing Apparatus	☐ Escape Sets	☐ EEBD	Chart:	-
☐	Immersion Suit	☐ BA Compressor	- Air Quality	Chart:	-
☐	Other Systems and Equipment	- Foam Applicator	Chart:	-	
☐	Other Systems and Equipment	- Water Mist System	Chart:	-	
☐	Summary Of Actions	Chart:	-		

Comments to all Service Charts are summarised on Service Charts - "Summary Of Actions"

This certificate is valid only when the Certificate and define Service Charts are duly signed and stamped by PT MULIA SAFETY SERVICE

The above equipment requires servicing 24 months from the latest inspection date in accordance with the flagstate authority regulation.

SERVICE COMPANY
PT. MULIA SAFETY SERVICE



ARIF BUDIYANTO
SERVICE ENGINEER



PT. MULIA SAFETY SERVICE

Head Office : Bumi Wanamukti H1/19, Sambiroto, Tembalang, Semarang 50276

Branch : Tanjung Uban - Banten - Jakarta - Tegal - Semarang - Surabaya - Makassar - Ambon - Luwuk

Telp/Fax : 02925150543 - Call & WA : 0811274443 - Email : cs@muliaservice.id, www.muliaservice.id



FIRE EXTINGUISHER (CHART B1) SERVICE REPORT

in Accordance ti IMO Resolution A.951(23)

Certificate No. 209/FFE/MSS-TGU/IX/2026

GENERAL PARTICULARS	
Name of Ship : KM. BAHTERA SEVA - III	Nationality / Port of Registry : INDONESIA / MAKASSAR
IMO-No. : 9897626	CallSign : YB 7703
Class : BKI	MMSI No : 525500394
Gross Tonnage : 150	Date of Service : SEPTEMBER 04, 2026
Kind of Service ☒ Annual ☐ 5 Yearly ☐ Repair	
Remarks: ALL CYLINDERS PORTABLE FIRE EXTINGUISHER HAS BEEN GOOD CONDITION	

Fire Extinguisher Type

☐ Water ☒ CO2 ☐ Foam ☒ Dry Powder ☒ AFFF

Description of

No	Checklist item	Y/N/NA	Remarks
Annual inspection			
1	Checked for proper location, charging pressure, and condition;	Y	
2	Checking safety clip and indicating devices	Y	
3	Checking the pressure indicating devices	Y	
4	Visual inspection for corrosion, dent, and damage	Y	
5	Checking the weight	Y	
6	Checking for the hose and nozzles	Y	
7	Checking of operation instruction	Y	
Inspection at recharge			
1	Checking the water and foam charge	N	
2	Checking for powder charge	N	
3	Checking for gas cartridge	N	
Inspection after discharge (5 and 10 years intervals)			
1	Checking air passages and operating mechanism	N	
2	Operating mechanism	N	
3	Gas cartridge	N	
4	O ring washers and hose diaphragms	N	
5	Checking powder body	N	
Inspection after recharge			
1	Water and foam	N	
2	Reassemble	Y	
3	Maintenance label	Y	
4	Mounting of extinguishers	Y	
5	Report	Y	

Other Service Item Code:

☐ 1 Inspection

☐ 2 Refilling

☐ 3 Check Content

☐ 4 Check Weight

5 New Supply/FFE

6 Repaired

7 Repainted

8 Hydrostatic Test

Description of Type :

DP : Dry Powder

FAB : Foam AB

N2 : Nitrogen

W : Water Gas

FAF : Foam AFFF

CO2 : Carbon Dioxide

FAP : Foam Applicator

BCF : Halon 1211

FP : Foam Protein

Serial Number	Type	Manu- facture	Manu- facture Date	Capacity	Latest Hydro-test Date	Gross Weight (Kg)	Test Pressure (Bar)	Other Service Item Code
1	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
2	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
3	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
4	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
5	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
6	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
7	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
8	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
9	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
10	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
11	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
12	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
13	DP	APARINDO	-	9,0 KG	-	-	-	1,3,4
14	CO2	YATISA	-	9,0 KG	-	-	-	1,3,4
15	CO2	YATISA	-	9,0 KG	-	-	-	1,3,4
16	CO2	YATISA	-	9,0 KG	-	-	-	1,3,4
17	FAF	YATISA	-	9,0 LTR	-	-	-	1,3,4
18	FAF	YATISA	-	9,0 LTR	-	-	-	1,3,4
19	FAFt	YATISA	-	25,0 LTR	-	-	-	1,3,4
20	FAFt	YATISA	-	50,0 LTR	-	-	-	1,3,4

Material replacement

 MENGETAHAI KEPALA SEKSI KAHBANDARAN KANTOR UNIT PENYELENGGARA PELABUHAN KELAS I TANJUNG UBAN ASTRA DEDI MAHYUDI, S.M NIP. 19750413 200912 1 001		 (tanda tangan surveyor dan Stempel perusahaan)	
Surveyor		ARIF BUDIYANTO	
Next of Service		SEPTEMBER 04, 2027	

Catatan:

- Syahbandar berhak tidak menandatangani *service report* ini apabila *service station* tidak melampirkan **SPK aktif terkait PMK** yang diterbitkan oleh BTKP



PT. MULIA SAFETY SERVICE



Head Office : Bumi Wanamukti H1/19, Sambiroto, Tembalang, Semarang 50276
Branch : Batam - Banten - Jakarta - Tegal - Semarang - Jepara - Surabaya - Makassar - Ambon - Luwuk
Telp/Fax : 02925150543 - Call & WA : 0811274443 - Email : cs@muliaservice.id, www.muliaservice.id



CERTIFICATE OF RE-INSPECTION

Certificate No.: 404/ILR/MSS-TGU/IX/2026

This is to certify that the liferaft detailed below has been surveyed, controlled and tested in compliance with requirement from :
and the manufacturer and in accordance with IMO Resolution : A.761 (18)

Inflatable Liferaft

Identification :	Type : KHA-15	Capacity : 15 PERSONS	Serial No. : 10826	Date Of Manufacture : DEC 2018
	Merk : SHANGHAI YOULONG RUBBER	Length of painter : 25 m/inside 1 m/outside		Max. Stowage Height : 18 m

Cylinders :	Serial Number :	Contents CO ₂ :	Contents N ₂ :	Latest Hyd. Test :
	043393	8.640 KG	1.850 KG	-
	043926	8.640 KG	1.850 KG	-

Equipment :	Unit :	Type :	Serial No :	Expiry Date :
Emergency Pack :		SOLAS "A" PACK	10826	05 - 2028
EPIRB :		-	-	-
HRU test :		-	-	-
Radar Reflector :		N/A	N/A	N/A
First Aid Kit :		BOX	N/A	09 - 2027

Tests :	NAP-test :	Gas inflation test :	Floor Seam test :	Load test davit launched :
Yes/No: NO	Yes/No: NO	Yes/No: NO	Yes/No: NO	Yes/No: NO
Latest Test* : -	Latest Test* : -	Latest Test* : -	Latest Test* : -	Latest Test* : -

*Latest test date (month / year)

Verification :	Date Of Service : SEPT 04, 2026	Service station name and No : PT. MULIA SAFETY SERVICE	Next Service Date : SEPT 04, 2027
----------------	---	--	---

National Marine authority ID No.	Remarks/modification : INFLATABLE LIFERAFT IN GOOD CONDITION
-------------------------------------	--

This inflatable liferaft requires servicing 12 month from the latest inspection date in accordance with the SOLAS regulation.

Name of ship : **KM. BAHTERA SEVA - III**
Name Of Ship/Owner : **BANK RAKYAT INDONESIA**
IMO Number : **9897626**
International call signal : **YB 7703**

SERVICE COMPANY
PT. MULIA SAFETY SERVICE





PT. MULIA SAFETY SERVICE

Head Office : Bumi Wanamukti H1/19, Sambiroto, Tembalang, Semarang 50276

Branch : Tanjung Uban - Banten - Jakarta - Tegal - Semarang - Surabaya - Makassar - Ambon - Luwuk

Telp/Fax : 02925150543 - Call & WA : 0811274443 - Email : cs@muliaservice.id, www.muliaservice.id



LIFERAFT SERVICE REPORT

in Accordance to IMO Resolution MSC.388(94) Amendment to Resolution A.761(18)

Certificate No. 404/ILR/MSS-TGU/IX/2026

GENERAL PARTICULARS			
Name of Ship	: KM. BAHTERA SEVA - III	Port of Registry	: INDONESIA / MAKASSAR
IMO-No.	: 9897626	Call Sign	: YB 7703
Class	: BKI	MMSI No	: 525500394
Gross Tonnage	: 150	Date of Service	: SEPTEMBER 04, 2026
Kind of Service			
☒ Annual ☐ 5 Yearly ☐ Repair			
Remarks:			
LIFERAFT IN GOOD CONDITION			

Liferaft Mark :	SHANGHAI YOULONG RUBBER	TYPE of Liferaft :	KHA-15
Serial Number :	10826	Capacity :	15 PERSONS
MFG Date :	DECEMBER 2018	Customer :	BANK RAKYAT INDONESIA

CHECKLIST ITEM	OK/ RN/ NA	CHECKLIST ITEM	OK/ RN/ NA	CHECKLIST ITEM	OK/ RN/ NA
* CONTAINER SHELL	-	Inflation Valve, Hose	NA	Repair Kit	OK
Labels/Marking	RN	"T/Y" Piece Connector	OK	Leak Stoppers	OK
Handling Becketts	RN	Protection Pads	OK	Sponges	OK
* Gasket/Strap/Packing List	OK	CO2 Cylinder (s)	OK	Bailers	OK
Painter Line	OK	Operating Cable & Conduit	OK	Spare Sea Anchor	OK
ID Container	NA	Operating Head	OK	Torch, Signaling	OK
* Valise Fabric/ Plastic	NA			Spare Batteries	RN
Eyelets	OK	SURVEY OF INTERIOR		Whistle	OK
Painter Line Pockets	OK	Bouyancies, Fabric	OK	Fishing Kit	OK
Bursting Band	OK	Safety Relief Valves	OK	Can Opener (s)	OK
Strapping	RN	Grabline & patches/loops	OK	Paddles	OK
		Thwart, Fabric	OK	Spare Bulb for Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valve	OK	Drinking Vessel	OK
Bouyancies Fabric	OK	Arches, Fabric	OK	Seasickness Bags	OK
Inlet Valves	OK	Center Column, Fabric	OK	Signal Mirror	OK
Deflation Plugs/ Valves	OK	Light Battery	RN	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	NA
Boarding Ramp	OK	Topping up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridle/ Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (s)	OK	EMERGENCY PACK	
Outer Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration (15 Pack)	OK
Recto Reflective Tape	OK	Inner Floor, Fabric	OK	Exp. Date 05 - 2028	OK
Seam and Taping	OK	Topping up Valves	OK	Drinking Water (45 Pack)	OK
Rain Water Catchment	OK	Deflation Up Valves	OK	Exp. Date 05 - 2028	OK
Exterior Lighting System	OK	Emergency pack Loops/Patch	OK	Smoke Signal (2 PCS)	OK
Arch Deflation Valve	OK	Aerial Socket/Tie-Tapes	OK	Exp. Date 08 - 2029	RN
Entrance Sleeves	OK	Floor Reds	OK	Parachute Signal (4 PCS)	OK
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Exp. Date 08 - 2029	RN
Righting Strap	OK	Knife Sheath	OK	Red hand Flares (6 PCS)	OK
Stabilising Pockets	OK	Sea Anchor	OK	Exp. Date 08 - 2029	RN
Cylinder Pockets (s)	OK	ACCESSORY BAG		First Aid Kit (1 PCS)	OK
Sea - Cell	OK	Bellows or Pump	OK	Exp. Date 09 - 2027	RN
Painter Lashing/Stowage	OK	Light Stick	NA	Anti Seasickness (90 TAB)	OK

(DKF) Load Test Davit Launch and Raft	NA	Glue for Repair Kit	OK	Exp. Date 09 - 2027	RN
RN = Renew, NA = Not Applicable					

RAFT AND CYLINDER TEST									
PRESSURE TEST	Start			Finish			Pressure	Safety Valves	
	Time	Temp (°C)	Pressure (mmHg)	Time	Temp (°C)	Pressure (mmHg)	Drop (mmHg)	Blow off (mmHg)	Reseat (mmHg)
Upper Buoyancy	09.15	29 °C	103	10.15	29 °C	102	1	114	103
Lower Buoyancy	09.30	29 °C	104	10.30	29 °C	103	1	110	104
Floor	-								
Canopy	-								
GAS CYLINDER TEST	Cyl No:	Mfg. Date	Change Date	Weight Of Cyl. Kg	Weight Of CO2 Kg	Weight Of N2 Kg	Total W. kg		
Cylinder No. 1	043393	-	-	-	8.640	1.850	12.680		
Cylinder No. 2	043926	-	-	-	8.640	1.850	12.680		
DAVID LAUNCHABLE RAFT		REMARK	Res A 761 (18)		REMARK		DATE		
Load Test	Date:	-	WP - TEST		YES		09 - 2026		
Suspension Strap/Patches		-	FS - TEST		NO		-		
Shackle		-	NAP - TEST		NO		-		
Steering Line with Patches		-	GI - TEST		NO		-		
Bowsing Line with Patches		-							
Container Line Incl. Pocket		-							
Pocket for Steering/Bowsing Line		-							
Remarks:									

Frequency of test

Servicing Intervals	Test Methods
End of first year	WP test
End of second year	WP test
End of third year	WP test
End of fourth year	WP test
End of fifth year	GI Test
End of sixth year	WP test
End of seventh year	WP test
End of eighth year	WP test
End of ninth year	WP test
End of tenth year	GI test + FS
End of fourteenth year	NAP test + FS
Fifteenth year	GI test + NAP + FS
Sixteenth to nineteenth year	NAP test + FS
Twentieth year	GI test + NAP + FS
Twenty-first to twenty-fourth year	NAP test + FS
Twenty fifth year onwards	GI test + NAP + FS

Keterangan:

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam

 KEPALA SEKSI KESYAHBANDARAN KANTOR UNIT PENYELENGGARA PELABUHAN KELAS I TANJUNG UBAN ASTRA DEDYAHYUDI, S.M. NIP. 19750413 200912 1 000		 Tanda tangan surveyor dan stempel perusahaan Surveyor : ARIF BUDIYANTO Next Inspection Date : SEPTEMBER 04, 2027	
--	--	--	--

Catatan:

- Syahbandar berhak tidak menandatangani *service report* ini apabila *service station* tidak melampirkan **SPK aktif terkait liferaft** yang diterbitkan oleh BTKP