



www.pump-generalsupply.com

PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

No. Reg. BTKP : 0624/BTKP/SPK-P/XII/2025

CERTIFICATE OF RE-INSPECTION

This is to certify that the liferaft detailed below has been surveyed, controlled and tested in compliance with requirements from :
and the manufacturer and in accordance with IMO Resolution: A. 761 (18)

Inflatable Liferaft

Mark :	SHANGHAI YOULONG RUBBER		Name Of Ship:	PAN MARINE 19	Certificate No. :	001/PUMP/ILR/II/2026.1
Identification :	Type : KHK-100 Fabric type : NR	Capacity : 100 PERSON Length of painter : 28 m/inside	Serial No : 0020 1 m/outside	Date of manufacture : Agu-13 Max stowage height : 18 m		

Cylinders :	Serial No :	Contents CO ₂ :	Contents N ₂ :	Latest hyd. test :
	751073	8,60 Kg	0,60 Kg	--
	751128	8,60 Kg	0,60 Kg	--
	751148	8,60 Kg	0,60 Kg	--
	751103	8,60 Kg	0,60 Kg	--

Equipment :	Unit :	Type :	Serial No :	Expiry date :
Emergency pack :		NON SOLAS	--	--
First aid kit :		LOCAL	--	01-2027

Tests :	NAP-test :	Gas inflation test :	Floor seam test :	Load test davit-launched :
	Yes/no : NO	Yes/no : YES	Yes/no : NO	Yes/no : NO
	Latest test*:	Latest test*:	Latest test*:	Latest test*:

Verification :	Date of inspection :	Servicing station name and number :	Date issued to ship :
	23 JANUARY 2026	PT. PRATHAMA USAHA MANDIRI PERKASA	22 JANUARY 2027

Owner:	Remarks / modification :
PT. PAN MARITIME WIRA PAWITRA	RAFT IN GOOD CONDITION

This inflatable liferaft requires servicing 12 months from the latest inspection date in accordance with the SOLAS regulation.

PT. PRATHAMA USAHA
MANDIRI PERKASA

HARRY GUNAWAN, S
SURVEYOR

Approved By,
KABID STATUS, HUKUM DAN SERTIFIKASI KAPAL

RAWAT P GULTOM, S.T., M.Si
NIP. 19710312 199803 1 001

Cilegon Office : Kampung Tengkurak No. 4 RT.04/RW.02, Desa Warnakarta, Kecamatan Bojonegara, Kabupaten Serang, Provinsi Banten, Indonesia
Main Office : Jl. Gajah Mada, Ruko Graha Tirta Indah Blok C No. 1, Tiban, Patam Lestari, Sekupang, Batam, Kepulauan Riau, 29427, Indonesia
Branch : Tj. Balai Karimun, Pekanbaru, Surabaya, Bali | **Website** : www.pump-generalsupply.com
Mobile Phone : +62 877 7407 7759 | **Email** : inquiry@pump-generalsupply.com / indah@pump-generalsupply.com



www.pump-generalsupply.com

PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

SURVEY AND TEST REPORT

Service No. : 001/PUMP/ILR/1/2026.1

LIFERAFT MARK : SHANGHAI YOU LONG RUBBER TYPE : KHK-100 MFG. DATE : 08 - 2013
SERIAL NUMBER : 0020 SIZE : 100 PERSON NEXT INSPECTION : 22 JANUARY 2027
NAME OF SHIP : PAN MARINE 19 CUST : PT. PAN MARITIME WIRA PAWITRA

RAFT INSPECTION

OBJECT	REMARKS	OBJECT	REMARKS	OBJECT	REMARKS
CONTAINER SHELL	REPAINTED	" T / Y " Piece Connector	OK	Repair Kit / Glue	OK
Labels / Markings	RN	Protection Pads	OK	Leak Stoppers	OK
Handling Becketts	OK	CO 2 Cylinder (s) 4 Cyl	Refill	Sponges	OK
Gasket / Strap / Packing List	OK	Operating Cable & Conduit	OK	Bailers	OK
Painter Line	OK	Operating Head	OK	Spare Sea Anchor	OK
ID Container	RN			Torch, Signalling	OK
Valise Fabric / Plastic	RN	SURVEY OF INTERIOR		Spare Batteries (4)	RN
Eyelets	OK	Buoyancies, Fabric	OK	Whistle	OK
Pockets	OK	Safety Relief Valves	--	Fishing Kit	OK
Bursting Band / Strapping	RN	Grabline & Patches / Loops	OK	Can Opener (s)	OK
Weak Link	OK	Thwart, Fabric	--	Paddles	OK
		Deflation Plugs / Valves	OK	Spare Bulb for Torch	OK
SURVEY OF EXTERIOR		Arches, Fabric	OK	Drinking Vessel	OK
Buoyancies, Fabric	OK	Center Column Fabric	--	Seasickness Bags	OK
Inlet Valves	OK	Light Battery	--	Signal Mirror	OK
Deflation Plugs / Valves	--	Interior Lighting System	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Topping Up Valves	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Inner Canopy, Fabric	--	Thermal Protective Aids	OK
Boarding Ladders	OK	Rainwater Catchment	OK	Radar Reflector	OK
Towing Bridle / Patch	OK	Viewing Port (s)	OK	Dye Marker	--
Lifeline and Patches	OK	Aerial Sleeve	OK		
Outer Canopy Fabric	OK	Inner Floor, Fabric	OK	EMERGENCY PACK (NON SOLAS)	
Rectro Reflective Tape	OK	Topping Up Valves	OK	Food Ration	--
Seam and Taping	OK	Deflation Up Valves	OK	Exp. Date :	
Rain Water Catchment	OK	Emergency Pack Loops / Patch	OK	Drinking Water	--
Exterior Lighting System	OK	Aerial Sockets / Tie - Tapes	OK	Exp. Date :	
Arch Deflation Valve	--	Floor Reeds	OK	Parachute Signal	--
Entrance Sieves	OK	Rescue Line and Quoit	OK	Exp. Date :	
Outer Floor, Fabric	OK	Knife Sheath	OK	Red Hand Flares	--
Righting Strap	OK	Sea Anchor	OK	Exp. Date :	
Stabilising Pockets	OK			Smoke Signal	--
Cylinder Pockets (s)	OK	ACCESSORY BAG		Exp. Date :	
Sea - Cell	OK	Bellows or Pump	OK	First Aid Kit	RN
Painter Lashing / Stowage	--	EPIRB	--	Exp. Date : 01-2027	
Inflation Valve, Hose.	--	Light Stick	--	Anti-Seasickness Tablets	RN

RAFT AND CYLINDER TEST

PRESSURE TEST	Start			Finish			Pressure Drops mm Hg	Safety Valves	
	Time	Temp. °C	Pressure mm Hg	Time	Temp. °C	Pressure mm Hg		Blow off mm Hg	Reset mm Hg
Upper Buoyancy	8.00	28	125	9.00	29	124	2	145	125
Lower Buoyancy	8.00	28	126	9.00	29	125	1	145	125
Floor	8.00	28	30	9.00	29	29	1	145	125
Canopy	--	--	--	--	--	--	--	--	--
GAS CYLINDER TEST	Cylinder No.	Mfg. Date	Change Date	Weight Of Cyl. (Kg)	Weight Of CO2 (Kg)	Weight Of N2 (Kg)	Total W. (Kg)	Hydrostatic Release Unit	
	Cylinder No. 1	751073	08-2012	--	8.60	0.60	29.70	Serial No. :	
	Cylinder No. 2	751128	08-2012	--	8.60	0.60	29.10		
	Cylinder No. 3	751148	08-2012	--	8.60	0.60	28.25		
	Cylinder No. 2	751103	08-2012	--	8.60	0.60	29.50	Exp / Test :	

RES : A. 761 (18)	REMARKS	DATE	SIGN
WP - TEST Date:			
FS - TEST Date:			
NAP - TEST Date:			
GI - TEST Date:	YES	23/01/2026	
REMARKS :	RAFT IN GOOD CONDITION		
	RAWAT P. GULTOM, S.T., M.Si NIP. 19710312 199603 1 001		
	Date : 23 JANUARY 2026		

Cilegon Office : Kampung Tengkurak No. 4 RT.04/RW.02, Desa Warnakarta, Kecamatan Bojonegara, Kabupaten Serang, Provinsi Banten, Indonesia
Main Office : Jl. Gajah Mada, Ruko Graha Tirta Indah Blok C No. 1, Tiban, Patam Lestari, Sekupang, Batam, Kepulauan Riau, 29427, Indonesia
Branch : Tj. Balai Karimun, Pekanbaru, Surabaya, Bali | Website : www.pump-generalsupply.com
Mobile Phone : +62 877 7407 7759 | Email : inquiry@pump-generalsupply.com / indah@pump-generalsupply.com



www.pump-generalsupply.com

PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

No. Reg. BTKP : 0624/BTKP/SPK-P/XII/2025

CERTIFICATE OF RE-INSPECTION

This is to certify that the liferaft detailed below has been surveyed, controlled and tested in compliance with requirements from :
and the manufacturer and in accordance with IMO Resolution: A. 761 (18)

Inflatable Liferaft

Mark :	SHANGHAI YOULONG RUBBER		Name Of Ship:	PAN MARINE 19	Certificate No. :	001/PUMP/ILR/I/2026.2
Identification :	Type :	Capacity :	Serial No :	Date of manufacture :		
	KKH-100	100 PERSON	0022	Agu-13		
	Fabric type :	Length of painter :		Max stowage height :		
	NR	28 m/inside	1 m/outside	18 m		

Cylinders :	Serial No :	Contents CO ₂ :	Contents N ₂ :	Latest hyd. test :
	751105	8,60 Kg	0,60 Kg	--
	751081	8,60 Kg	0,60 Kg	--
	751110	8,60 Kg	0,60 Kg	--
	751026	8,60 Kg	0,60 Kg	--

Equipment :	Unit :	Type :	Serial No :	Expiry date :
Emergency pack :		NON SOLAS	--	--
First aid kit :		LOCAL	--	01-2027

Tests :	NAP-test :	Gas inflation test :	Floor seam test :	Load test davit-launched :
Yes/no :	NO	Yes/no : YES	Yes/no : NO	Yes/no : NO
Latest test*:		Latest test*:	Latest test*:	Latest test*:

Verification :	Date of inspection :	Servicing station name and number :	Date issued to ship :
	23 JANUARY 2026	PT. PRATHAMA USAHA MANDIRI PERKASA	22 JANUARY 2027

Owner:	Remarks / modification :
PT. PAN MARITIME WIRA PAWITRA	RAFT IN GOOD CONDITION

This inflatable liferaft requires servicing 12 months from the latest inspection date in accordance with the SOLAS regulation.

**PT. PRATHAMA USAHA
MANDIRI PERKASA**

HARRY GUNAWAN. S
SURVEYOR

Approved By,
KABID STATUS HUKUM DAN SERTIFIKASI KAPAL

RAWAT P GULTOM, S.T., M.Si
NIP. 19710312 199803 1 001

Cilegon Office : Kampung Tengkurak No. 4 RT.04/RW.02, Desa Warnakarta, Kecamatan Bojonegara, Kabupaten Serang, Provinsi Banten, Indonesia
Main Office : Jl. Gajah Mada, Ruko Graha Tirta Indah Blok C No. 1, Tiban, Patam Lestari, Sekupang, Batam, Kepulauan Riau, 29427, Indonesia
Branch : Tj. Balai Karimun, Pekanbaru, Surabaya, Bali | **Website :** www.pump-generalsupply.com
Mobile Phone : +62 877 7407 7759 | **Email :** inquiry@pump-generalsupply.com / indah@pump-generalsupply.com



PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

www.pump-generalsupply.com

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES | MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

SURVEY AND TEST REPORT Service No. : 001/PUMP/ILR/I/2026.2


LIFERAFT MARK : SHANGHAI YOU LONG RUBBER TYPE : KHK-100 MFG. DATE : 08 - 2013
SERIAL NUMBER : 0022 SIZE : 100 PERSON NEXT INSPECTION : 22 JANUARY 2027
NAME OF SHIP : PAN MARINE 19 CUST : PT. PAN MARITIME WIRA PAWITRA

RAFT INSPECTION

OBJECT	REMARKS	OBJECT	REMARKS	OBJECT	REMARKS
CONTAINER SHELL	REPAINTED	" T / Y " Piece Connector	OK	Repair Kit / Glue	OK
Labels / Markings	RN	Protection Pads	OK	Leak Stoppers	OK
Handling Becketts	OK	CO 2 Cylinder (s) 4 Cyl	Refill	Sponges	OK
Gasket / Strap / Packing List	OK	Operating Cable & Condukt	OK	Bailers	OK
Painter Line	OK	Operating Head	OK	Spare Sea Anchor	OK
ID Container	RN			Torch, Signalling	OK
Valise Fabric / Plastic	RN	SURVEY OF INTERIOR		Spare Batteries (4)	RN
Eyelets	OK	Buoyancies, Fabric	OK	Whistle	OK
Pockets	OK	Safety Relief Valves	--	Fishing Kit	OK
Bursting Band / Strapping	RN	Grabline & Patches / Loops	OK	Can Opener (s)	OK
Weak Link	OK	Thwart, Fabric	--	Paddles	OK
		Deflation Plugs / Valves	OK	Spare Bulb for Torch	OK
SURVEY OF EXTERIOR		Arches, Fabric	OK	Drinking Vessel	OK
Buoyancies, Fabric	OK	Center Column Fabric	--	Seasickness Bags	OK
Inlet Valves	OK	Light Battery	--	Signal Mirror	OK
Deflation Plugs / Valves	--	Interior Lighting System	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Topping Up Valves	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Inner Canopy, Fabric	--	Thermal Protective Aids	OK
Boarding Ladders	OK	Rainwater Catchment	OK	Radar Reflector	OK
Towing Bridle / Patch	OK	Viewing Port (s)	OK	Dye Marker	--
Lifeline and Patches	OK	Aerial Sleeve	OK		
Outer Canopy Fabric	OK	Inner Floor, Fabric	OK	EMERGENCY PACK (NON SOLAS)	
Rectro Reflective Tape	OK	Topping Up Valves	OK	Food Ration	--
Seam and Taping	OK	Deflation Up Valves	OK	Exp. Date :	
Rain Water Catchment	OK	Emergency Pack Loops / Patch	OK	Drinking Water	--
Exterior Lighting System	OK	Aerial Sockets / Tie - Tapes	OK	Exp. Date :	
Arch Deflation Valve	--	Floor Reeds	OK	Parachute Signal	--
Entrance Sleeves	OK	Rescue Line and Quoit	OK	Exp. Date :	
Outer Floor, Fabric	OK	Knife Sheath	OK	Red Hand Flares	--
Righting Strap	OK	Sea Anchor	OK	Exp. Date :	
Stabilising Pockets	OK			Smoke Signal	--
Cylinder Pockets (s)	OK	ACCESSORY BAG		Exp. Date :	
Sea - Cell	OK	Bel lows or Pump	OK	First Aid Kit	RN
Painter Lashing / Stowage	--	EPIRB	--	Exp. Date : 01-2027	
Inflation Valve, Hose.	--	Light Stick	--	Anti-Seasickness Tablets	RN

RAFT AND CYLINDER TEST

PRESSURE TEST	Start			Finish			Pressure Drops mm Hg	Safety Valves	
	Time	Temp. °C	Pressure mm Hg	Time	Temp. °C	Pressure mm Hg		Blow off mm Hg	Reset mm Hg
Upper Buoyancy	9.00	29	127	10.00	29	125	2	145	125
Lower Buoyancy	9.00	29	125	10.00	29	124	1	145	125
Floor	9.00	29	30	10.00	29	29	1	145	125
Canopy	--	--	--	--	--	--	--	--	--
GAS CYLINDER TEST	Cylinder No.	Mfg. Date	Change Date	Weight Of Cyl. (Kg)	Weight Of CO2 (Kg)	Weight Of N2 (Kg)	Total W. (Kg)	Hydrostatic Release Unit	
	Cylinder No. 1	751105	08-2012	--	8.60	0.60	28.20	Serial No. :	
	Cylinder No. 2	751081	08-2012	--	8.60	0.60	28.50		
	Cylinder No. 3	751110	08-2012	--	8.60	0.60	29.45		
	Cylinder No. 2	751026	08-2012	--	8.60	0.60	29.00		Exp / Test :

RES : A. 761 (18)		REMARKS	DATE	Mengetahui KABO STATUS HUKUM DAN SERTIFIKASI KAPAL		SIGN	
WP - TEST	Date:					SURVEYOR : HARRY GUNAWAN. S	
FS - TEST	Date:						
NAP - TEST	Date:						
GI - TEST	Date:	YES	23/01/2026				
REMARKS :		RAFT IN GOOD CONDITION		Date : 23 JANUARY 2026		PT PRATHAMA USAHA MANDIRI PERKASA SUNGAI CILONG	



www.pump-generalsupply.com

PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

No. Reg. BTKP : 0624/BTKP/SPK-P/XII/2025

CERTIFICATE OF RE-INSPECTION

This is to certify that the liferaft detailed below has been surveyed, controlled and tested in compliance with requirements from :
and the manufacturer and in accordance with IMO Resolution: A. 761 (18)

Inflatable Liferaft

Mark :	SHANGHAI YOULONG RUBBER		Name Of Ship:	PAN MARINE 19	Certificate No. :	001/PUMP/ILR/I/2026.3
Identification :	Type : KHK-100 Fabric type : NR	Capacity : 100 PERSON Length of painter : 28 m/inside	Serial No : 0023 1 m/outside	Date of manufacture : Agu-13 Max stowage height : 18 m		

Cylinders :	Serial No :	Contents CO ₂ :	Contents N ₂ :	Latest hyd. test :
	751054	8,60 Kg	0,60 Kg	--
	751101	8,60 Kg	0,60 Kg	--
	751122	8,60 Kg	0,60 Kg	--
	751191	8,60 Kg	0,60 Kg	--

Equipment :	Unit :	Type :	Serial No :	Expiry date :
Emergency pack :		NON SOLAS	--	--
First aid kit :		LOCAL	--	01-2027

Tests :	NAP-test :	Gas inflation test :	Floor seam test :	Load test davit-launched :
Yes/no :	NO	Yes/no : YES	Yes/no : NO	Yes/no : NO
Latest test*:		Latest test*:	Latest test*:	Latest test*:

Verification :	Date of inspection :	Servicing station name and number :	Date issued to ship :
	23 JANUARY 2026	PT. PRATHAMA USAHA MANDIRI PERKASA	22 JANUARY 2027


Owner: PT. PAN MARITIME WIRA PAWITRA	Remarks / modification : RAFT IN GOOD CONDITION
--	---

This inflatable liferaft requires servicing 12 months from the latest inspection date in accordance with the SOLAS regulation.

PT. PRATHAMA USAHA MANDIRI PERKASA

HARRY GUNAWAN. S
SURVEYOR

Approved By,
KABID STATUS HUKUM DAN SERTIFIKASI KAPAL



RAWAT P GULTOM, S.T., M.Si
NIP. 19710312 199803 1 001

Cilegon Office : Kampung Tengkurak No. 4 RT.04/RW.02, Desa Warnakarta, Kecamatan Bojonegara, Kabupaten Serang, Provinsi Banten, Indonesia
Main Office : Jl. Gajah Mada, Ruko Graha Tirta Indah Blok C No. 1, Tiban, Patam Lestari, Sekupang, Batam, Kepulauan Riau, 29427, Indonesia
Branch : Tj. Balai Karimun, Pekanbaru, Surabaya, Bali | Website : www.pump-generalsupply.com
Mobile Phone : +62 877 7407 7759 | Email : inquiry@pump-generalsupply.com / indah@pump-generalsupply.com



PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

www.pump-generalsupply.com

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

SURVEY AND TEST REPORT Service No. : 001/PUMP/ILR/I/2026.3

LIFERAFT MARK :	SHANGHAI YOULONG RUBBER	TYPE :	KHK-100	MFG. DATE :	08 - 2013
SERIAL NUMBER :	0023	SIZE :	100 PERSON	NEXT INSPECTION :	22 JANUARY 2027
NAME OF SHIP :	PAN MARINE 19	CUST :	PT. PAN MARITIME WIRA PAWITRA		

RAFT INSPECTION

OBJECT	REMARKS	OBJECT	REMARKS	OBJECT	REMARKS
CONTAINER SHELL	REPAINTED	" T / Y " Piece Connector	OK	Repair Kit / Glue	OK
Labels / Markings	RN	Protection Pads	OK	Leak Stoppers	OK
Handling Beackets	OK	CO 2 Cylinder (s)	4 Cyl Refill	Sponges	OK
Gasket / Strap / Packing List	OK	Operating Cable & Conduilt	OK	Bailers	OK
Painter Line	OK	Operating Head	OK	Spare Sea Anchor	OK
ID Container	RN			Torch, Signalling	OK
Valise Fabric / Plastic	RN	SURVEY OF INTERIOR		Spare Batteries (4)	RN
Eyelets	OK	Buoyancies, Fabric	OK	Whistle	OK
Pockets	OK	Safety Relief Valves	--	Fishing Kit	OK
Bursting Band / Strapping	RN	Grabline & Patches / Loops	OK	Can Opener (s)	OK
Weak Link	OK	Thwart, Fabric	--	Paddies	OK
		Deflation Plugs / Valves	OK	Spare Bulb for Torch	OK
SURVEY OF EXTERIOR		Arches, Fabric	OK	Drinking Vessel	OK
Buoyancies, Fabric	OK	Center Colomn Fabric	--	Seasickness Bags	OK
Inlet Valves	OK	Light Battery	--	Signal Mirror	OK
Deflation Plugs / Valves	--	Interior Lighting System	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Topping Up Valves	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Inner Canopy, Fabric	--	Thermal Protective Aids	OK
Boarding Ladders	OK	Rainwater Catchment	OK	Radar Reflector	OK
Towing Bridle / Patch	OK	Viowing Port (s)	OK	Dye Marker	--
Lifeline and Patches	OK	Aerial Sleeve	OK	EMERGENCY PACK (NON SOLAS)	
Outer Canopy Fabric	OK	Inner Floor, Fabric	OK	Food Ration	--
Retro Reflective Tape	OK	Topping Up Valves	OK	Exp. Date :	
Seam and Taping	OK	Deflation Up Valves	OK	Drinking Water	--
Rain Water Catchment	OK	Emergency Pack Loops / Patch	OK	Exp. Date :	
Exterior Lighting System	OK	Aerial Sockets / Tie - Tapes	OK	Parachute Signal	--
Arch Deflation Valve	--	Floor Reeds	OK	Exp. Date :	
Entrance Sleeves	OK	Rescue Line and Quoit	OK	Red Hand Flares	--
Outer Floor, Fabric	OK	Knife Sheath	OK	Exp. Date :	
Righting Strap	OK	Sea Anchor	OK	Smoke Signal	--
Stabilising Pockets	OK	ACCESSORY BAG		Exp. Date :	
Cylinder Pockets (s)	OK	Belows or Pump	OK	First Aid Kit	RN
Sea - Cell	OK	EPIRB	--	Exp. Date :	01-2027
Painter Lashing / Stowage	--	Light Stick	--	Anti-Seasickness Tablets	RN
Inflation Valve, Hose.	--				

RAFT AND CYLINDER TEST

PRESSURE TEST	Start			Finish			Pressure Drops mm Hg	Safety Valves	
	Time	Temp. °C	Pressure mm Hg	Time	Temp. °C	Pressure mm Hg		Blow off mm Hg	Reseat mm Hg
Upper Buoyancy	10.00	29	125	11.00	29	123	2	145	125
Lower Buoyancy	10.00	29	125	11.00	29	124	1	145	125
Floor	10.00	29	30	11.00	29	29	1	145	125
Canopy	--	--	--	--	--	--	--	--	--
GAS CYLINDER TEST	Cylinder No.	Mfg. Date	Change Date	Weight Of Cyl. (Kg)	Weight Of CO2 (Kg)	Weight Of N2 (Kg)	Total W. (Kg)	Hydrostatic Release Unit	
	Cylinder No. 1	751054	08-2012	--	8.60	0.60	29.10	Serial No :	
	Cylinder No. 2	751101	08-2012	--	8.60	0.60	28.90		
	Cylinder No. 3	751122	08-2012	--	8.60	0.60	29.40		
	Cylinder No. 2	751191	08-2012	--	8.60	0.60	29.30	Exp / Test :	

RES : A. 761 (18)		REMARKS	DATE	Mengetahui KABID STATUS HUKUM DAN BERTIPKASI KAPAL	SIGN
WP - TEST	Date:				SURVEYOR : HARRY GUNAWAN, S.T.M.P. STAMP
FS - TEST	Date:				
NAP - TEST	Date:				
GI - TEST	Date:	YES	23/01/2026		
REMARKS :		RAFT IN GOOD CONDITION			
				RAWAT P GULTOM, S.T., M.Si NIP. 197103121998031001	Date : 26 JANUARY 2026

Cilegon Office : Kampung Tengkurak No. 4 RT.04/RW.02, Desa Warnakarta, Kecamatan Bojonegara, Kabupaten Serang, Provinsi Banten, Indonesia
Main Office : Jl. Gajah Mada, Ruko Graha Tirta Indah Blok C No. 1, Tiban, Patam Lestari, Sekupang, Batam, Kepulauan Riau, 29427, Indonesia
Branch : Tj. Balai Karimun, Pekanbaru, Surabaya, Bali | Website : www.pump-generalsupply.com
Mobile Phone : +62 877 7407 7759 | Email : inquiry@pump-generalsupply.com / indah@pump-generalsupply.com



PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

www.pump-generalsupply.com

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

No. Reg. BTKP : 0624/BTKP/SPK-P/XII/2025

CERTIFICATE OF RE-INSPECTION

This is to certify that the liferaft detailed below has been surveyed, controlled and tested in compliance with requirements from :
and the manufacturer and in accordance with IMO Resolution: A. 761 (18)

Inflatable Liferaft

Mark :	SHANGHAI YOULONG RUBBER		Name Of Ship:	PAN MARINE 19	Certificate No. :	001/PUMP/ILR/I/2026.4
Identification :	Type :	Capacity :	Serial No :	Date of manufacture :		
	KKH-100	100 PERSON	0025	Agu-13		
	Fabric type :	Length of painter :		Max stowage height :		
	NR	28 m/inside	1 m/outside	18 m		

Cylinders :	Serial No :	Contents CO ₂ :	Contents N ₂ :	Latest hyd. test :
	821216	8,60 Kg	0,60 Kg	--
	821239	8,60 Kg	0,60 Kg	--
	821209	8,60 Kg	0,60 Kg	--
	821237	8,60 Kg	0,60 Kg	--

Equipment :	Unit :	Type :	Serial No :	Expiry date :
Emergency pack :		NON SOLAS	--	--
First aid kit :		LOCAL	--	01-2027

Tests :	NAP-test :	Gas inflation test :	Floor seam test :	Load test davit-launched :
Yes/no :	NO	Yes/no : YES	Yes/no : NO	Yes/no : NO
Latest test*:		Latest test*:	Latest test*:	Latest test*:

Verification :	Date of inspection :	Servicing station name and number :	Date issued to ship :
	23 JANUARY 2026	PT. PRATHAMA USAHA MANDIRI PERKASA	22 JANUARY 2027

Owner:	Remarks / modification :
PT. PAN MARITIME WIRA PAWITRA	RAFT IN GOOD CONDITION

This inflatable liferaft requires servicing 12 months from the latest inspection date in accordance with the SOLAS regulation.

**PT. PRATHAMA USAHA
MANDIRI PERKASA**

HARRY GUNAWAN. S
SURVEYOR



Approved By,

KABID STATUS HUKUM DAN SERTIFIKASI KAPAL

RAWAT P GULTOM, S.T., M.Si
NIP. 19710312 199803 1 001

Cilegon Office : Kampung Tengkurak No. 4 RT.04/RW.02, Desa Warnakarta, Kecamatan Bojonegara, Kabupaten Serang, Provinsi Banten, Indonesia
Main Office : Jl. Gajah Mada, Ruko Graha Tirta Indah Blok C No. 1, Tiban, Patam Lestari, Sekupang, Batam, Kepulauan Riau, 29427, Indonesia
Branch : Tj. Balai Karimun, Pekanbaru, Surabaya, Bali | **Website :** www.pump-generalsupply.com
Mobile Phone : +62 877 7407 7759 | **Email :** inquiry@pump-generalsupply.com / indah@pump-generalsupply.com



PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

www.pump-generalsupply.com

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

SURVEY AND TEST REPORT

Service No. : 001/PUMP/ILR/1/2026.4

LIFERAFT MARK : SHANGHAI YOU LONG RUBBER TYPE : KHK-100 MFG. DATE : 08 - 2013
SERIAL NUMBER : 0025 SIZE : 100 PERSON NEXT INSPECTION : 22 JANUARY 2027
NAME OF SHIP : PAN MARINE 19 CUST : PT. PAN MARITIME WIRA PAWITRA

RAFT INSPECTION

OBJECT	REMARKS	OBJECT	REMARKS	OBJECT	REMARKS
CONTAINER SHELL	REPAINTED	" T / Y " Piece Connector	OK	Repair Kit / Glue	OK
Labels / Markings	RN	Protection Pads	OK	Leak Stoppers	OK
Handling Becketts	OK	CO 2 Cylinder (s)	4 Cyl	Sponges	OK
Gasket / Strap / Packing List	OK	Operating Cable & Conduitt	OK	Bailers	OK
Painter Line	OK	Operating Head	OK	Spare Sea Anchor	OK
ID Container	RN			Torch, Signalling	OK
Valise Fabric / Plastic	RN	SURVEY OF INTERIOR		Spare Batteries (4)	RN
Eyelets	OK	Buoyancies, Fabric	OK	Whistle	OK
Pockets	OK	Safety Relief Valves	-	Fishing Kit	OK
Bursting Band / Strapping	RN	Grabline & Patches / Loops	OK	Can Opener (s)	OK
Weak Link	OK	Thwart, Fabric	-	Paddles	OK
		Deflation Plugs / Valves	OK	Spare Bulb for Torch	OK
SURVEY OF EXTERIOR		Arches, Fabric	OK	Drinking Vessel	OK
Buoyancies, Fabric	OK	Center Column Fabric	-	Seasickness Bags	OK
Inlet Valves	OK	Light Battery	-	Signal Mirror	OK
Deflation Plugs / Valves	-	Interior Lighting System	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Topping Up Valves	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Inner Canopy, Fabric	-	Thermal Protective Aids	OK
Boarding Ladders	OK	Rainwater Catchment	OK	Radar Reflector	OK
Towing Bridle / Patch	OK	Viewing Port (s)	OK	Dye Marker	-
Lifeline and Patches	OK	Aerial Sleeve	OK		
Outer Canopy Fabric	OK	Inner Floor, Fabric	OK	EMERGENCY PACK (NON SOLAS)	
Rectro Reflective Tape	OK	Topping Up Valves	OK	Food Ration	-
Seam and Taping	OK	Deflation Up Valves	OK	Exp. Date :	
Rain Water Catchment	OK	Emergency Pack Loops / Patch	OK	Drinking Water	-
Exterior Lighting System	OK	Aerial Sockets / Tie - Tapes	OK	Exp. Date :	
Arch Deflation Valve	-	Floor Reeds	OK	Parachute Signal	-
Entrance Sleeves	OK	Rescue Line and Quoit	OK	Exp. Date :	
Outer Floor, Fabric	OK	Knife Sheath	OK	Red Hand Flares	-
Righting Strap	OK	Sea Anchor	OK	Exp. Date :	
Stabilising Pockets	OK			Smoke Signal	-
Cylinder Pockets (s)	OK	ACCESSORY BAG		Exp. Date :	
Sea - Cell	OK	Bellows or Pump	OK	First Aid Kit	RN
Painter Lashing / Stowage	-	EPIRB	-	Exp. Date :	01-2027
Inflation Valve, Hose.	-	Light Stick	-	Anti-Seasickness Tablets	RN

RAFT AND CYLINDER TEST

PRESSURE TEST	Start			Finish			Pressure Drops mm Hg	Safety Valves	
	Time	Temp. °C	Pressure mm Hg	Time	Temp. °C	Pressure mm Hg		Blow off mm Hg	Reset mm Hg
Upper Buoyancy	10.00	29	125	11.00	29	123	2	145	125
Lower Buoyancy	10.00	29	125	11.00	29	124	1	145	125
Floor	10.00	29	30	11.00	29	29	1	145	125
Canopy	-	-	-	-	-	-	-	-	-
GAS CYLINDER TEST	Cylinder No.	Mfg. Date	Change Date	Weight Of Cyl. (Kg)	Weight Of CO2 (Kg)	Weight Of N2 (Kg)	Total W. (Kg)	Hydrostatic Release Unit	
	Cylinder No. 1	821216	08-2012	-	8.60	0.60	28.70	Serial No. :	
	Cylinder No. 2	821239	08-2012	-	8.60	0.60	28.80		
	Cylinder No. 3	821209	08-2012	-	8.60	0.60	29.10		
	Cylinder No. 2	821237	08-2012	-	8.60	0.60	29.20	Exp / Test :	

RES : A. 761 (18)	REMARKS	DATE	Mengetahui	SIGN
WP - TEST Date:			KABID STATUS HUKUM DAN SERTIFIKASI KAPAL	
FS - TEST Date:				SURVEYOR : HARRY GUNAWAN. S
NAP - TEST Date:				
GI - TEST Date:	YES	23/01/2026		
REMARKS :	RAFT IN GOOD CONDITION			
			RAWAT P GULTOM, S.T., M.Si NIP. 19710312 199803 1 001	Date : 23 JANUARY 2026

Cilegon Office : Kampung Tengkurak No. 4 RT.04/RW.02, Desa Warnakarta, Kecamatan Bojonegara, Kabupaten Serang, Provinsi Banten, Indonesia
Main Office : Jl. Gajah Mada, Ruko Graha Tirta Indah Blok C No. 1, Tiban, Patam Lestari, Sekupang, Batam, Kepulauan Riau, 29427, Indonesia
Branch : Tj. Balai Karimun, Pekanbaru, Surabaya, Bali | Website : www.pump-generalsupply.com
Mobile Phone : +62 877 7407 7759 | Email : inquiry@pump-generalsupply.com / indah@pump-generalsupply.com



www.pump-generalsupply.com

PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

No. Reg. BTKP : 0622/BTKP/SPK-P/XII/2025


CERTIFICATE of Inspection

Year	Month	Day	Type and name of ship / unit :	FLAG :	Certificate No. :
2026	01	23	PAN MARINE 19	INDONESIA	001/PUMP/FE/I/26
PLACE OF SERVICE			Classification Society :	Name of Owner:	
BANTEN			BKI	PT. PAN MARITIME WIRA PAWITRA	

*We Hereby Certify That The Fire Extinguisher Set Detailed Below Have Been Inspected, Serviced, Refilled
In Our Service Station/On Board The Vessel
And Tested According To Requirement From IMO Regulation, SOLAS And Manufacturer.*



FIRE EXTINGUISHER



CO2 SYSTEM

This Certificate is valid when service sheets are attached and been signed stamped by PT. PRATHAMA USAHA MANDIRI PERKASA

Date Inspection : 23 JANUARY 2026

Next Inspection : 22 JANUARY 2027


**PT. PRATHAMA USAHA
MANDIRI PERKASA**



ABIMAYU NOVA
SURVEYOR

Approved By,

KABID STATUS HUKUM DAN SERTIFIKASI KAPAL



RAWAT P GULTOM, S.T., M.Si
NIP. 19710312 199803 1 001



PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

www.pump-generalsupply.com

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

INSPECTION CERTIFICATE FIRE EXTINGUISHER PORTABLE

Year 2026	Month 01	Day 23	Type and name of ship / unit : PAN MARINE 19	FLAG : INDONESIA	Certificate No. : 001/PUMP/FE/I/2026
PLACE OF SERVICE BANTEN PORT			Classification Society : BKI	Name of ship / owner PT. PAN MARITIME WIRA PAWITRA	

*We Hereby Certify That The Systems And Equipment Specified Below Have Been Inspected, Serviced, Refilled
In Our Service Station/On Board The Vessel
And Tested According To Requirement From IMO Regulation, SOLAS And Manufacturer.*

Description of type :			Description of working codes :	
DP	: Dry Powder	FAB	: Foam AB	1 = Inspection
W	: Water Gass	FAF	: Foam AFFF	2 = Refilling
CO2	: Carbon Dioxide	FAP	: Foam Application	3 = Service
BCF	: Halon 1211	FP	: Foam Protein	4 = Check Weight
				5 = Check Content
				6 = New Extingh
				7 = Repainted
				8 = Hydrostatic test
				9 = Repaired
				10 = Repainted

No.	Type Of Fire Extinguisher	Working Code	Volume	Quantity	Remark
1	Dry Powder	1	3,0 Kgs	9 Cylinder	Good Condition
2	Dry Powder	6	6,0 Kgs	1 Cylinder	Good Condition
3	CO2 Portable	1	7,0 Kgs	2 Cylinder	Good Condition
4	Foam AFFF	1	9,0 Ltrs	3 Cylinder	Good Condition
5	Foam AFFF	1	50,0 Ltrs	1 Cylinder	Good Condition
			Total	16 Cylinder	Good Condition

Date Inspection : 23 January 2026

Next Inspection : 22 January 2027

**PT. PRATHAMA USAHA
MANDIRI PERKASA**


ABIMAYU NOVA
SURVEYOR

Cilegon Office : Kampung Tengkurak No. 4 RT.04/RW.02, Desa Warnakarta, Kecamatan Bojonegara, Kabupaten Serang, Provinsi Banten, Indonesia
Main Office : Jl. Gajah Mada, Ruko Graha Tirta Indah Blok C No. 1, Tiban, Patam Lestari, Sekupang, Batam, Kepulauan Riau, 29427, Indonesia
Branch : Tj. Balai Karimun, Pekanbaru, Surabaya, Bali | Website : www.pump-generalsupply.com
Mobile Phone : +62 877 7407 7759 | Email : inquiry@pump-generalsupply.com / indah@pump-generalsupply.com



www.pump-generalsupply.com

PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

CERTIFICATE of Inspection

Year :	Month :	Day :	Type and name of ship/unit :	Flag :	Certificate No. :
2026	01	23	PAN MARINE 19	INDONESIA	001/PUMP/BA/1/2026
Place of service :			Classification Society :	Name Of Shipp / Owner :	
BANTEN			BKI	PT. PAN MARITIME WIRA PAWITRA	

*We hereby certify that the systems and equipment specified below have been inspected, serviced, refilled.
and tested according to requirement from IMO regulation, SOLAS and manufacturer.
The quantity of equipment and working code enclosed in Service Report back of this page.*

 EMERGENCY ESCAPE BREATHING DEVICE
 SELF CONTAINED BREATHING APPARATUS
 MEDICAL OXYGEN

This certificate is valid when service sheets are attached and been signed stamped by PT. PRATHAMA USAHA MANDIRI PERKASA


Date Inspection : 23 JANUARY 2026
Next Inspection : 22 JANUARY 2027

PT. PRATHAMA USAHA
MANDIRI PERKASA


PT. PRATHAMA
USAHA MANDIRI PERKASA
CILIGON
ABIMAYU NOVA
SURVEYOR

Approved By,

KABID STATUS HUKUM DAN SERTIFIKASI KAPAL



RAWAT P GULTOM, S.T., M.Si
NIP. 19710312 199803 1 001



PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

www.pump-generalsupply.com

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

EMERGENCY ESCAPE BREATHING DEVICE SERVICE REPORT

Vessel Name : PAN MARINE 19 Owner : PT. PAN MARITIME WIRA PAWITRA
Certificate No. : 001/PUMP/EEBD/I/2026 Nationality : INDONESIA
Date : 23 JANUARY 2026

Type of Set	EEBD	EEBD	EEBD	EEBD
Merk	HUAYAN	HUAYAN	HUAYAN	HUAYAN
Seri Number	N/A	N/A	N/A	N/A
Date Manufacture	--	--	--	--
Face Mask / Hood	OK	OK	OK	OK
Air Hose / Tube	OK	OK	OK	OK
Demand Valve	OK	OK	OK	OK
Reducing Valve	OK	OK	OK	OK
Height Pressure Hose	OK	OK	OK	OK
Pressure Gauge	OK	OK	OK	OK
Test Gauge	OK	OK	OK	OK
Whistle Unit	OK	OK	OK	OK
Harness / Frame	OK	OK	OK	OK

Description of Work :

- | | | |
|----------------|------------------|--------------------|
| 1 : Inspection | 4 : Serviced | 7 : Check Contents |
| 2 : Refilling | 5 : Rejected | |
| 3 : Hydrotest | 6 : Check Weight | |

NO	Cylinder Number	Type Gas Cylinder	Last Tested	Tested Pressure	Working Pressure (Bar)	Workdone
1	11041	AIR	--	210 Bar	200 Bar	1
2	10541	AIR	--	210 Bar	200 Bar	1
3	10941	AIR	--	210 Bar	200 Bar	1
4	18741	AIR	--	210 Bar	200 Bar	1

This EEBD requires service 12 month from the latest inspection.

Date Inspection : 23 JANUARY 2026

Next Inspection: 22 JANUARY 2027

PT. PRATHAMA USAHA
MANDIRI PERKASA


PT. PRATHAMA USAHA MANDIRI PERKASA
ABIMAYU NOVA
SURVEYOR



PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

www.pump-generalsupply.com

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

SELF CONTAINED BREATHING APPARATUS SERVICE REPORT

Vessel Name : PAN MARINE 19 Owner : PT. PAN MARITIME WIRA PAWITRA
Certificate No. : 001/PUMP/SCBA/I/2026 Nationality : INDONESIA
Date : 23 JANUARY 2026

Type	SCBA	SCBA	SCBA	SCBA
Merk	FENZY	HIPROTECT	N/A	KAWASAKI
Seri Number	092647	144164	42836	59769
Date Manufacture	N/A	N/A	N/A	N/A

Description of Work :

- | | | |
|----------------|------------------|--------------------|
| 1 : Inspection | 4 : Serviced | 7 : Check Contents |
| 2 : Refilling | 5 : Rejected | |
| 3 : Hydrotest | 6 : Check Weight | |

NO	Cylinder Number	Type Gas Cylinder	Last Tested	Tested Pressure	Working Pressure (Bar)	Workdone
1	092647	AIR	--	350 Bar	300 Bar	1
2	144164	AIR	--	350 Bar	300 Bar	1
3	42836	AIR	--	350 Bar	300 Bar	1
4	59769	AIR	--	350 Bar	300 Bar	1

This SCBA requires service 12 month from the latest inspection.

Date Inspection : **23 JANUARY 2026**

Next Inspection: **22 JANUARY 2027**

PT. PRATHAMA USAHA
MANDIRI PERKASA


PT. PRATHAMA
USAHA MANDIRI PERKASA
ABIMAYU NOVA
SURVEYOR



PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

www.pump-generalsupply.com

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

MEDICAL OXYGEN SERVICE REPORT

Vessel Name : PAN MARINE 19
Certificate No. : 001/PUMP/MO/1/2026
Date : 23 January 2026

Nationality : INDONESIA
Owner : PT. PAN MARITIME
WIRA PAWITRA

Description of Work :

1 : Inspection	4 : Serviced	7 : Check Contents
2 : Refilling	5 : Rejected	8 : New Supply
3 : Check Pressure	6 : Check Weight	9 : Hydrotest

NO	Type of Gas Cyld	Date of Manufacture	Serial Number	Capacity	Working Pressure	Workdone
1	O2	N/A	00521	2.0 Ltr	150 Bar	1

This Medical Oxygen requires service 12 month from the latest inspection.

**PT. PRATHAMA USAHA
MANDIRI PERKASA**



ABIMAYU NOVA
SURVEYOR



www.pump-generalsupply.com

PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI


SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

No. Reg. BTKP : 0621/BTKP/SPK-P/XII/2025

CERTIFICATE of Inspection

Year	Month	Day	Type and name of ship / unit :	FLAG :	Certificate No. :
2026	01	23	PAN MARINE 19	INDONESIA	001/PUMP/COS/I/26
PLACE OF SERVICE BANTEN			Classification Society : BKI	Name of Owner: PT. PAN MARITIME WIRA PAWITRA	

*We Hereby Certify That The Fire Extinguisher Set Detailed Below Have Been Inspected, Serviced, Refilled
In Our Service Station/On Board The Vessel
And Tested According To Requirement From IMO Regulation, SOLAS And Manufacturer.*



FIRE EXTINGUISHER



CO2 SYSTEM

This Certificate is valid when service sheets are attached and been signed stamped by PT. PRATHAMA USAHA MANDIRI PERKASA

Date Inspection : 23 JANUARY 2026

Next Inspection : 22 JANUARY 2027


**PT. PRATHAMA USAHA
MANDIRI PERKASA**



**ABIMAYU NOVA
SURVEYOR**

Approved By,

KABID STATUS HUKUM DAN SERTIFIKASI KAPAL



**RAWAT P GULTOM, S.T., M.Si
NIP. 19710312 199803 1 001**



PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

www.pump-generalsupply.com

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

INSPECTION CERTIFICATE CO2 SYSTEM

Year 2026	Month 01	Day 23	Type and name of ship / unit : PAN MARINE 19	FLAG : INDONESIA	Certificate No. : 001/PUMP/COS/I/2026
PLACE OF SERVICE BANTEN PORT			Classification Society : BKI	Name of ship / owner PT. PAN MARITIME WIRA PAWITRA	

*We Hereby Certify That The Systems And Equipment Specified Below Have Been Inspected, Serviced, Refilled
In Our Service Station/On Board The Vessel
And Tested According To Requirement From IMO Regulation, SOLAS And Manufacturer.*

<u>Description of type :</u>			<u>Description of working codes :</u>	
DP : Dry Powder	FAB : Foam AB		1 = Inspection	6 = New Extingh
W : Water Gass	FAF : Foam AFFF		2 = Refilling	7 = Repainted
CO2 : Carbon Dioxide	FAP : Foam Application		3 = Service	8 = Hydrostatic test
BCF : Halon 1211	FP : Foam Protein		4 = Check Weight	9 = Repaired
			5 = Check Content	10 = Reject

No.	Type Of Fire Extinghuiser	Working Code	Volume	Quantity	Remark
1	Co2 System	1	45.0 Kgs	5 Cylinder	Good Condition
2	Pilot System	1	1.78 Kgs	1 Cylinder	Good Condition
			Total	6 Cylinder	Good Condition

Date Inspection : 23 JANUARY 2026

Next Inspection : 22 JANUARY 2027

**PT. PRATHAMA USAHA
MANDIRI PERKASA**


**PT. PRATHAMA
USAHA MANDIRI PERKASA**
ABIMAYU NOVA
SURVEYOR

Cilegon Office : Kampung Tengkurak No. 4 RT.04/RW.02, Desa Warnakarta, Kecamatan Bojonegara, Kabupaten Serang, Provinsi Banten, Indonesia
Main Office : Jl. Gajah Mada, Ruko Graha Tirta Indah Blok C No. 1, Tiban, Patam Lestari, Sekupang, Batam, Kepulauan Riau, 29427, Indonesia
Branch : Tj. Balai Karimun, Pekanbaru, Surabaya, Bali | **Website :** www.pump-generalsupply.com
Mobile Phone : +62 877 7407 7759 | **Email :** inquiry@pump-generalsupply.com / indah@pump-generalsupply.com



PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

www.pump-generalsupply.com

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

CO2 SYSTEM SERVICE REPORT

Year 2026	Month 01	Day 23	Type and name of ship / unit : PAN MARINE 19	IMO No. : 9709582	Certificate No. : 001/PUMP/COS/1/2026
--------------	-------------	-----------	---	----------------------	--

Description of type :

DP : Dry Powder
W : Water Gass
CO2 : Carbon Dioxide
BCF : Halon 1211
FAB : Foam AB
FAF : Foam AFFF
FAP : Foam Application
N2 : Nitrogen

Description of working codes :

1 = Inspection
2 = Refilling
3 = Service
4 = Check Weight
5 = Check Content
6 = New Extinguisher
7 = Rejected
8 = Hydrostatic Tes
9 = Repaired
10 = Repainted

No.	Type	Cylinder No.	Tare Weight (Kg)	Gross Weight (Kg)	Capacity (Kg)	Location	Working Code
1	Co ²	M8201158	82,1	127,1	45,0	CO2 Room	1
2	Co ²	M8201159	80,9	125,9	45,0	CO2 Room	1
3	Co ²	M8201160	81,3	126,3	45,0	CO2 Room	1
4	Co ²	M8201161	81,3	126,3	45,0	CO2 Room	1
5	Co ²	M8201162	81,9	126,9	45,0	CO2 Room	1

CO2 PYLOT SYSTEM

No.	Type	Cylinder No.	Tare Weight (Kg)	Gross Weight (Kg)	Capacity (Kg)	Location	Working Code
1	Pilot	J1096	2,20	3,98	1,50	CO2 Room	1

PT. PRATHAMA USAHA MANDIRI PERKASA


PT. PRATHAMA USAHA MANDIRI PERKASA
ABIMAYU NOVA
SURVEYOR



PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

www.pump-generalsupply.com

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

CO2 SYSTEM SERVICE REPORT

Year	Month	Day	Name of vessel	IMO Number :	Certificate No. :
2026	01	23	PAN MARINE 19	9709582	001/PUMP/COS/I/2026

Description of System / Technical Information :

TYPE / MAKE _____ N/A _____ CONSISTING OF _____ 5 _____ CYLINDERS
EACH OF CAPACITY _____ 45.0 _____ KG _____ AND _____ 1 _____ PILOT CYLS, EACH OF CAPACITY _____ 1.50 Kgs
NOS OF DISTRIBUTION LINES _____ 5 _____ LAST PRESSURE TEST DATE OF CYLINDERS _____ N/A
COVERING _____ ENGINE ROOM

Description of Inspection / Tests :	Complete inspection	☒	Carried Out	Not Carried Out	Not Applicable	See Comments
	Contents check only	☒				
1 Release system and distribution valves secured			X			
2 Contents in cylinders checked by manual weighing			X			
3 Contents in cylinders checked by liquid level indicator, cyl. temp. 30 ⁰ C				X		
4 ☐ Cylinders refilled only ☐ refilled and hydrotested				X		
5 ☒ All cylinder valves visually inspected ☒ leak tested			X			
6 All cylinder frames and connections checked for tightness			X			
7 ☒ Manifold and distribution valves inspected ☐ tested			X			
8 ☒ Main valve and distribution valves inspected ☒ tested ☒ for proper operation			X			
9 ☒ Total flooding release system inspected ☒ tested			X			
10 Release stations inspected			X			
11 ☒ Alarm ☒ fan stop ☒ tested			X			
12 ☒ Distribution lines and nozzles inspected ☒ tested ☒ blown through			X			
13 Smoke detection system tested				X		
14 Doors, hinges, locks inspected			X			
15 All instruction plates on installation inspected			X			
16 Installation reconnected, sealed and left in operational order, inspection date labels attached			X			
17						
18						
19						
20						

Comments :

* Valid until 22 January 2027

* CO2 SYSTEM IN GOOD CONDITION

PT. PRATHAMA USAHA MANDIRI PERKASA

ABIMAYU NOVA
SURVEYOR



www.pump-generalsupply.com

PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

Certificate No. 001/PUMP/HRU/II/2026.1

HYDROSTATIC RELEASE UNIT CERTIFICATE

This is to certify that Hydrostatic Release Unit detailed below has been in compliance with requirement from SOLAS and the manufacturer and in accordance with IMO Resolution :

Identification

Brand : SAFE T MADE
Mark/Type : HRU-LR2
Serial No : 1702006

Remark

New Supply
Next Inspection : 22 January 2027

Hydrostatic Release Unit in Good Condition

Verification

Hydrostatic Release in requires inspect 1 years from the latest date in accordance with SOLAS regulation

Flag States of Ship : INDONESIA
Name Of Ship / Owner : PAN MARINE 19

Sign and Stamp

HARRY GUNAWAN. S
SURVEYOR



www.pump-generalsupply.com

PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

Certificate No. 001/PUMP/HRU/I/2026.2

HYDROSTATIC RELEASE UNIT CERTIFICATE

This is to certify that Hydrostatic Release Unit detailed below has been in compliance with requirement from SOLAS and the manufacturer and in accordance with IMO Resolution :

Identification

Brand : SAFE T MADE
Mark/Type : HRU-LR2
Serial No : 1702023

Remark

New Supply
Next Inspection : 22 January 2027

Hydrostatic Release Unit in Good Condition

Verification

Hydrostatic Release in requires inspect 1 years from the latest date in accordance with SOLAS regulation

Flag States of Ship : INDONESIA
Name Of Ship / Owner : PAN MARINE 19

Sign and Stamp

HARRY GUNAWAN. S
SURVEYOR



www.pump-generalsupply.com

PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

Certificate No. 001/PUMP/HRU/I/2026.3

HYDROSTATIC RELEASE UNIT CERTIFICATE

This is to certify that Hydrostatic Release Unit detailed below has been in compliance with requirement from SOLAS and the manufacturer and in accordance with IMO Resolution :

Identification

Brand : SAFE T MADE
Mark/Type : HRU-LR2
Serial No : 1702068

Remark

New Supply
Next Inspection : 22 January 2027

Hydrostatic Release Unit in Good Condition

Verification

Hydrostatic Release in requires inspect 1 years from the latest date in accordance with SOLAS regulation

Flag States of Ship : INDONESIA
Name Of Ship / Owner : PAN MARINE 19

Sign and Stamp


HARRY GUNAWAN. S
SURVEYOR



www.pump-generalsupply.com

PT. PRATHAMA USAHA MANDIRI PERKASA

GROUP COMPANY OF PT. BATAM MARINE INDOBAHARI

SERVICE STATION - LSA & FFA | SUPPLY SAFETY EQUIPMENT | LOAD TESTING, LIFTING GEAR INSPECTION & NDT SERVICES |
MARINE INSPECTION, BUNKER & FREE GAS SURVEY SERVICES | MARINE & INDUSTRIAL GENERAL SUPPLY

Certificate No. 001/PUMP/HRU/II/2026.4

HYDROSTATIC RELEASE UNIT CERTIFICATE

This is to certify that Hydrostatic Release Unit detailed below has been in compliance with requirement from SOLAS and the manufacturer and in accordance with IMO Resolution :

Identification

Brand : SAFE T MADE
Mark/Type : HRU-LR2
Serial No : 1702181

Remark

New Supply
Next Inspection : 22 January 2027

Hydrostatic Release Unit in Good Condition

Verification

Hydrostatic Release in requires inspect 1 years from the latest date in accordance with SOLAS regulation

Flag States of Ship : INDONESIA
Name Of Ship / Owner : PAN MARINE 19

Sign and Stamp



HARRY GUNAWAN. S
SURVEYOR