



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara
Telp. (021) 440 8538 Fax. (021) 440 8538
E-mail : megajayaabadi@ymail.com

Certificate Inflatable Liferaft

Cert.No : 005/MJAP/ILR/I/26

• Customer	: PT. PAN MARITIME WIRA PAWITRA	• Name Of Ship	: CB. PAN MARINE 12
• Manufacturer	: JIANGSU HAINING	• Carrying Capacity	: 25 Persons
• Liferaft Type	: HNF - A 25	• Date Of Manufacture	: 02 - 2012
• Serial No.	: 12063	• Emergency Pack Type	: SOLAS A PACK
• CO ² Cylinder No.	Containing CO ²	Containing N ²	Total Wt
1. 613092	4,300 Kg	0,300 Kg	14,80 Kg
2. 613197	4,300 Kg	0,300 Kg	14,80 Kg

THIS IS TO CERTIFY that

1. The above - mentoined inflatable liferaft has been inspected, repaired and tested and found to be in compliance with the under - mentioned requirements, the liferaft in serviceable condition.
INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA (SOLAS) and
INTERNATIONAL LIFE - SAVING APPLIANCE (LSA) CODE
2. The technical condition of the equipment and appliances has been found to satisfaction, and the tested data report attached.
3. The technical condition of the above - mentioned inflatable liferaft has been found to satisfaction, and the log card has been endorsed accordingly.

• Date Of Issue : 06 Januari 2026
• Date Of next inspection : 05 Januari 2027



For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGA JAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

LIFERAFT SERVICE REPORT

In Accordance to IMO Resolution MSC.388(94) Amendment to Resolution A.761(18)

Certificate No.: 005/MJAP/I/26

GENERAL PARTICULARS	
Name Of Ship : CB. PAN MARINE 12	Nationality/Port of Registry : INDONESIA
Owner : PT. PAN MARITIME WIRA PAWITRA	Call Sign : YDB4152
IMO-No : 9656113	MMSI No : 525010182
Class : -	Date of Service : 06 JANUARI 2026
Kind Of Service	
☒ Annual	☒ 5 Yearly
	☒ Repair

REMARKS :

" First Aid Kit, Anti Seasickness, Painting & Marking Label "

DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK
CONTAINER SHELL		Installation Valve, Hose	OK	Leak Stoppers	OK
Label/Markings	RN	"T/Y" Place Connector	OK	Sponges	OK
Handling Beckets	OK	Protection Pads	OK	Bailers	OK
Gasket/Strap Packing List	OK	CO2 Cylinder (s)	OK	Spare Sea Anchor	OK
Painter Line	OK	Operating Cable & Condulet	OK	Torch, Signaling	OK
ID Container	RN	Operating Head	OK	Spare Batteries	OK
Valise Fabric/Plastic	RN	SURVEY OF INTERIOR		Whistle	OK
Eyelets	OK	Buoyancies Fabric	OK	Fishing Kit	OK
Painter Line Pockets	OK	Safety Relief Valves	NA	Can Openers	OK
Bursting Band	RN	Grabline & Patches/Loops	OK	Paddles	OK
Strapping	RN	Thwart, Fabric	NA	Spare Bulb For Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valves	OK	Drinking Vessel	OK
Buoyancies, Fabric	OK	Arches, Fabric	OK	Seasickness Bag	OK
Inlet Valves	OK	Center Column Fabric	NA	Signal Mirror	OK
Deflation Plugs/Valves	OK	Light Battery	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Topping Up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridle / Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (S)	RN	• EMERGENCY PACK •	
Outer Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration	25 Pcs
Retro Reflective Tape	OK	Inner Floor, Fabric	OK	Expired Date	12/2026
Seam and Taping	OK	Topping Up Valves	NA	Drinking Water	75 Pcs
Rain Water Catchment	OK	Deflation Up Valves	NA	Expired Date	12/2026
Exterior Lighting System	OK	Emergency Pack Loops	OK	Smoke Signal	2 Pcs
Arch Deflation Valve	OK	Aerial Sockets/Tie-Tapes	OK	Expired Date	12/2026
Entrance Sleeves	OK	Floor Reeds	OK	Parachute Signal	4 Pcs
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Expired Date	12/2026
Retaining Straps	OK	Knife Sheath	OK	Red Hand Flare	6 Pcs
Stabilizing Pockets	OK	Sea Anchor	OK	Expired Date	12/2026
Cylinder Pockets	OK	ACCESSORY BAG	OK	First Aid Kit	1 Pcs
Painter Lashing/Storage	OK	Bellow Of Pump	OK	Expired Date	01/2028
(DKF) Loud Test Davit	NA	Light Stick	NA	Anti Seasickness	150 Pcs
Launch And Raft		Repair Kit	OK	Expired Date	04/2030

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "

** Working Code : (RP = Repair), (RN = Renewed), (OK = Good), (EXP = Expired), (SP = Supply), (CH = Charge) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Sempur Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

Certificate No.: 005/MJAP/I/26

RAFT AND CYLINDER TEST

RAFT AND CYLINDER TEST									
PREASURE TEST	Start			Finish			Preasure	Safety Valves	
	Time	Temp (°C)	Pressure (mmHg)	Time	Temp (°C)	Pressure (mmHg)	Droe (mmHg)	Blow Off (mmhg)	Reseat (mmhg)
Upper Bouyance	10.00	30	131	11.00	30	130	2	161	131
Lower Bouyance	10.00	30	131	11.00	30	130	2	167	131
Floor	-	-	-	-	-	-	-	-	-
Canopy	-	-	-	-	-	-	-	-	-
GAS CYLINDER TEST	Cylinder Number		Manufacture Date		Charge Date	Weight of Cylinder Kg	Weight of CO² Kg	Weight of N² Kg	Total Weight Kg
Cylinder No.1	613092		-		-	-	4,300	0,300	14,80
Cylinder No.2	613197		-		-	-	4,300	0,300	14,80
DAVID LAUNCHABLE RAFT	Remarks	RES:A.761(18)		Remarks		DATE			
Load Test Date:	-	WP-TEST		YES		6/1/2026			
Suspension Straps/Patches	-	FS-TEST		-		-			
Shackle	-	NAP-TEST		-		-			
Steering Line With Patches	-	GI-TEST		-		-			
Bowsing Line With Patches	-	RAFT		Serial No.		12063		Man of date : 02 - 2012	
Container Line Incl. Pocket	-			Type		HNF - A25		Capacity : 25 Persons	
Pocket for Steering/Bowsing Lines	-			Merk		JIANGSU HAINING			
"RAFT IN GOOD CONDOTION"									

Frequency of test

SERVICING INTERVALS	TEST METHODS
End of first year	Wp Test
End of second year	Wp Test
End of third year	Wp Test
End of fourth year	Wp Test
End of fifth year	GI Test
End of sixth year	Wp Test
End of seventh year	Wp Test
End of eighth year	Wp Test
End of ninth year	Wp Test
End of tenth year	GI Test + FS
Eleventh to fourteenth year	GI Test + FS
fifteenth year	NAP test + FS
Sixteenth to nineteenth year	GI test + NAP + FS
Twentieth year	NAP test + FS
Twenty-first to twenty-fourth year	GI test + NAP + FS
Twenty fifth year onwards	GI test + NAP + FS

Working Code :

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam

Mengetahui,

At: KEPALA KANTOR KSOP UTAMA TANJUNG PRIOK
KABID PERKAPALAN DAN KEPELAUTAN



Surveyor	: AGUS FERİYANSYAH
Next Inspection Date	: 05 JANUARI 2027

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Certificate Inflatable Liferaft

Cert.No : 006/MJAP/ILR/1/26

• Customer	: PT. PAN MARITIME WIRA PAWITRA	• Name Of Ship	: CB. PAN MARINE 12
• Manufacturer	: JIANGSU HAINING	• Carrying Capacity	: 25 Persons
• Liferaft Type	: HNF - A 25	• Date Of Manufacture	: 02 - 2012
• Serial No.	: 12064	• Emergency Pack Type	: SOLAS A PACK
• CO ² Cylinder No.	Containing CO ²	Containing N ²	Total Wt
1. 620549	4,300 Kg	0,300 Kg	14,80 Kg
2. 613164	4,300 Kg	0,300 Kg	14,80 Kg

THIS IS TO CERTIFY that

1. The above - mentoined inflatable liferaft has been inspected, repaired and tested and found to be in compliance with the under - mentioned requirements, the liferaft in serviceable condition.
INTERNATIONAL CONVENTION FOR THE SAFETY OL LIFE AT SEA (SOLAS) and
INTERNATIONAL LIFE - SAVING APPLIANCE (LSA) CODE
2. The technical condition of the equipment and appliances has been found to satisfaction,
and the tested data report attached.
3. The technical condition of the above - mentioned inflatable liferaft has been found to satisfaction,
end the log card has been endorsed accordingly.

• Date Of Issue : 06 Januari 2026
• Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGA JAYA ABADI PERKASA



HELMY CANDRA, ST.,M.MT.
Pemanta (IV/a)

NIP. 197901162007121001



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

LIFERAFT SERVICE REPORT

In Accordance to IMO Resolution MSC.388(94) Amandment to Resolution A.761(18)

Certificate No.: 006/MJAP/I/26

GENERAL PARTICULARS

Name Of Ship	: CB. PAN MARINE 12	Nationality/Port of Registry	: INDONESIA
Owner	: PT. PAN MARITIME WIRA PAWITRA	Call Sign	: YDB4152
IMO-No	: 9656113	MMSI No	: 525010182
Class	: -	Date of Service	: 06 JANUARI 2026

Kind Of Service

☒ Annual
 ☒ 5 Yearly
 ☒ Repair

REMARKS :

" Food Ration, Drinking Water, First Aid Kit, Anti Seasickness, Painting & Marking Label "

DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK
CONTAINER SHELL		Installation Valve, Hose	OK	Leak Stoppers	OK
Label/Markings	RN	"T/Y" Place Connector	OK	Sponges	OK
Handling Beackets	OK	Protection Pads	OK	Bailers	OK
Gasket/Strap Packing List	OK	CO2 Cylinder (s)	OK	Spare Sea Anchor	OK
Painter Line	OK	Operating Cable & Condukt	OK	Torch, Signaling	OK
ID Container	RN	Operating Head	OK	Spare Batteries	OK
Valise Fabric/Plastic	RN	SURVEY OF INTERIOR		Whistle	OK
Eyelets	OK	Buoyancies Fabric	OK	Fishing Kit	OK
Painter Line Pockets	OK	Safety Relief Valves	NA	Can Openers	OK
Bursting Band	RN	Grabline & Patches/Loops	OK	Paddles	OK
Strarpping	RN	Thwart,Fabric	NA	Spare Bulb For Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valves	OK	Drinking Vessel	OK
Buoyancies,Fabric	OK	Arches, Fabric	OK	Seasickness Bag	OK
Inlet Valves	OK	Center Column Fabric	NA	Signal Mirror	OK
Deflation Plugs/Valves	OK	Light Battery	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Topping Up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridie / Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (S)	RN	• EMERGENCY PACK •	
Outer Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration	25 Pcs
Retro Reflective Tape	OK	Inner Floor, Fabric	OK	Expired Date	01/2029
Seam and Taping	OK	Topping Up Valves	NA	Drinking Watter	75 Pcs
Rain Water Catchment	OK	Deflation Up Valves	NA	Expired Date	01/2029
Exterior Linghting System	OK	Emergency Pack Loops	OK	Smoke Signal	2 Pcs
Arch Deflation Valve	OK	Aerial Sockets/Tie-Tapes	OK	Expired Date	12/2026
Entrance Sleeves	OK	Floor Reeds	OK	Parachute Signal	4 Pcs
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Expired Date	12/2026
Retaining Straps	OK	Knife Sheath	OK	Red Hand Flare	6 Pcs
Stabilizing Pockets	OK	Sea Anchor	OK	Expired Date	12/2026
Cylinder Pockets	OK	ACCESSORY BAG	OK	First Aid Kit	1 Pcs
Painter Lashing/Storage	OK	Bellow Of Pump	OK	Expired Date	01/2028
(DKF) Loud Test Davit	NA	Light Stick	NA	Anti Seasickness	150 Pcs
Launch And Raft		Repair Kit	OK	Expired Date	04/2030

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "

** Working Code : (RP = Repair) , (RN = Renewed) , (OK = Good) , (EXP = Expired) , (SP = Supply) , (CH = Charge) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

Certificate No.: 006/MJAP/I/26

RAFT AND CYLINDER TEST

RAFT AND CYLINDER TEST									
PREASURE TEST	Start			Finish			Preasure	Safety Valves	
	Time	Temp (°C)	Pressure (mmHg)	Time	Temp (°C)	Pressure (mmHg)	Droe (mmHg)	Blow Off (mmhg)	Reseat (mmhg)
Upper Bouyance	10.00	30	131	11.00	30	130	2	161	131
Lower Bouyance	10.00	30	131	11.00	30	130	2	167	131
Floor	-	-	-	-	-	-	-	-	-
Canopy	-	-	-	-	-	-	-	-	-
GAS CYLINDER TEST	Cylinder Number		Manufacture Date		Charge Date	Weight of Cylinder Kg	Weight of CO² Kg	Weight of N² Kg	Total Weight Kg
Cylinder No.1	620549		-		-	-	4,300	0,300	14,80
Cylinder No.2	613164		-		-	-	4,300	0,300	14,80
DAVID LAUNCHABLE RAFT	Remarks	RES:A.76I(18)		Remarks		DATE			
Load Test Date:	-	WP-TEST		YES		6/1/2026			
Suspension Straps/Patches	-	FS-TEST		-		-			
Shackle	-	NAP-TEST		-		-			
Steering Line With Patches	-	GI-TEST		-		-			
Bowsing Line With Patches	-	RAFT		Serial No.		12064		Man of date : 02 - 2012	
Container Line Incl. Pocket	-			Type		HNF - A25		Capacity : 25 Persons	
Pocket for Steering/Bowsing Lines	-			Merk		JIANGSU HAINING			
"RAFT IN GOOD CONDOTION"									

Frequency of test

SERVICING INTERVALS	TEST METHODS
End of first year	Wp Test
End of second year	Wp Test
End of third year	Wp Test
End of fourth year	Wp Test
End of fifth year	GI Test
End of sixth year	Wp Test
End of seventh year	Wp Test
End of eighth year	Wp Test
End of ninth year	Wp Test
End of tenth year	GI Test + FS
Eleventh to fourteenth year	GI Test + FS
fifteenth year	NAP test + FS
Sixteenth to nineteenth year	GI test + NAP + FS
Twentieth year	NAP test + FS
Twenty-first to twenty-fourth year	GI test + NAP + FS
Twenty fifth year onwards	GI test + NAP + FS

Working Code :

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam

Mengetahui,



Surveyor : AGUS FERIYANSYAH
Next Inspection Date : 05 JANUARI 2027

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Certificate Inflatable Liferaft

Cert.No : 007/MJAP/ILR/I/26

• Customer	: PT. PAN MARITIME WIRA PAWITRA	• Name Of Ship	: CB. PAN MARINE 12
• Manufacturer	: JIANGSU HAINING	• Carrying Capacity	: 25 Persons
• Liferaft Type	: HNF - A 25	• Date Of Manufacture	: 02 - 2012
• Serial No.	: 12069	• Emergency Pack Type	: SOLAS A PACK
• CO ² Cylinder No.	Containing CO ²	Containing N ²	Total Wt
1. 613015	4,300 Kg	0,300 Kg	14,58 Kg
2. 613096	4,300 Kg	0,300 Kg	14,61 Kg

THIS IS TO CERTIFY that

1. The above - mentoined inflatable liferaft has been inspected, repaired and tested and found to be in compliance with the under - mentioned requirements, the liferaft in serviceable condition.
INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA (SOLAS) and
INTERNATIONAL LIFE - SAVING APPLIANCE (LSA) CODE
2. The technical condition of the equipment and appliances has been found to satisfaction, and the tested data report attached.
3. The technical condition of the above - mentioned inflatable liferaft has been found to satisfaction, and the log card has been endorsed accordingly.

• Date Of Issue : 06 Januari 2026
• Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGA JAYA ABADI PERKASA





PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538
Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

LIFERAFT SERVICE REPORT

In Accordance to IMO Resolution MSC.388(94) Amandment to Resolution A.761(18)

Certificate No.: 007/MJAP/I/26

GENERAL PARTICULARS

Name Of Ship	: CB. PAN MARINE 12	Nationality/Port of Registry	: INDONESIA
Owner	: PT. PAN MARITIME WIRA PAWITRA	Call Sign	: YDB4152
IMO-No	: 9656113	MMSI No	: 525010182
Class	: -	Date of Service	: 06 JANUARI 2026

Kind Of Service

☒ Annual
 ☒ 5 Yearly
 ☒ Repair

REMARKS :

" Food Ration, Drinking Water, First Aid Kit, Anti Seasickness, Painting & Marking Label "

DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK
CONTAINER SHELL		Installation Valve, Hose	OK	Leak Stoppers	OK
Label/Markings	RN	"T/Y" Place Connector	OK	Sponges	OK
Handling Beckets	OK	Protection Pads	OK	Bailers	OK
Gasket/Strap Packing List	OK	CO2 Cylinder (s)	OK	Spare Sea Anchor	OK
Painter Line	OK	Operating Cable & Condukt	OK	Torch, Signaling	OK
ID Container	RN	Operating Head	OK	Spare Batteries	OK
Valise Fabric/Plastic	RN	SURVEY OF INTERIOR		Whistle	OK
Eyelets	OK	Buoyancies Fabric	OK	Fishing Kit	OK
Painter Line Pockets	OK	Safety Relief Valves	NA	Can Openers	OK
Bursting Band	RN	Grabline & Patches/Loops	OK	Paddles	OK
Strapping	RN	Thwart, Fabric	NA	Spare Bulb For Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valves	OK	Drinking Vessel	OK
Buoyancies, Fabric	OK	Arches, Fabric	OK	Seasickness Bag	OK
Inlet Valves	OK	Center Column Fabric	NA	Signal Mirror	OK
Deflation Plugs/Valves	OK	Light Battery	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Topping Up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridle / Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (S)	RN	• EMERGENCY PACK •	
Outer Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration	25 Pcs
Retro Reflective Tape	OK	Inner Floor, Fabric	OK	Expired Date	01/2029
Seam and Taping	OK	Topping Up Valves	NA	Drinking Water	75 Pcs
Rain Water Catchment	OK	Deflation Up Valves	NA	Expired Date	01/2029
Exterior Lighting System	OK	Emergency Pack Loops	OK	Smoke Signal	2 Pcs
Arch Deflation Valve	OK	Aerial Sockets/Tie-Tapes	OK	Expired Date	12/2026
Entrance Sleeves	OK	Floor Reeds	OK	Parachute Signal	4 Pcs
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Expired Date	12/2026
Retaining Straps	OK	Knife Sheath	OK	Red Hand Flare	6 Pcs
Stabilizing Pockets	OK	Sea Anchor	OK	Expired Date	12/2026
Cylinder Pockets	OK	ACCESSORY BAG	OK	First Aid Kit	1 Pcs
Painter Lashing/Storage	OK	Bellow Of Pump	OK	Expired Date	01/2028
(DKF) Loud Test Davit	NA	Light Stick	NA	Anti Seasickness	150 Pcs
Launch And Raft		Repair Kit	OK	Expired Date	04/2030

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "

** Working Code : (RP = Repair) , (RN = Renewed) , (OK = Good) , (EXP = Expired) , (SP = Supply) , (CH = Charge) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

Certificate No.: 007/MJAP/I/26

RAFT AND CYLINDER TEST

RAFT AND CYLINDER TEST									
PREASURE TEST	Start			Finish			Preasure	Safety Valves	
	Time	Temp (°C)	Pressure (mmHg)	Time	Temp (°C)	Pressure (mmHg)	Droe (mmHg)	Blow Off (mmhg)	Reseat (mmhg)
Upper Bouyance	10.00	30	131	11.00	30	130	2	161	131
Lower Bouyance	10.00	30	131	11.00	30	130	2	167	131
Floor	-	-	-	-	-	-	-	-	-
Canopy	-	-	-	-	-	-	-	-	-
GAS CYLINDER TEST	Cylinder Number		Manufacture Date		Charge Date	Weight of Cylinder Kg	Weight of CO² Kg	Weight of N² Kg	Total Weight Kg
Cylinder No.1	613015		-		-	-	4,300	0,300	14,58
Cylinder No.2	613096		-		-	-	4,300	0,300	14,61
DAVID LAUNCHABLE RAFT	Remarks	RES:A.761(18)		Remarks		DATE			
Load Test Date:	-	WP-TEST		YES		6/1/2026			
Suspension Straps/Patches	-	FS-TEST		-		-			
Shackle	-	NAP-TEST		-		-			
Steering Line With Patches	-	GI-TEST		-		-			
Bowsing Line With Patches	-	RAFT		Serial No.		12069		Man of date : 02 - 2012	
Container Line Incl. Pocket	-			Type		HNF - A25		Capacity : 25 Persons	
Pocket for Steering/Bowsing Lines	-			Merk		JIANGSU HAINING			
"RAFT IN GOOD CONDOTION"									

Frequency of test

SERVICING INTERVALS	TEST METHODS
End of first year	Wp Test
End of second year	Wp Test
End of third year	Wp Test
End of fourth year	Wp Test
End of fifth year	GI Test
End of sixth year	Wp Test
End of seventh year	Wp Test
End of eighth year	Wp Test
End of ninth year	Wp Test
End of tenth year	GI Test + FS
Eleventh to fourteenth year	GI Test + FS
fifteenth year	NAP test + FS
Sixteenth to nineteenth year	GI test + NAP + FS
Twentieth year	NAP test + FS
Twenty-first to twenty-fourth year	GI test + NAP + FS
Twenty fifth year onwards	GI test + NAP + FS

Working Code :

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam

Mengetahui,

An KEPALA KANTOR KSOP UTAMA TANJUNG PRIOK
KANTOR PERKAPALAN DAN KEPেলাUTAN

Pembina
NIP. 1912007121001



Surveyor : AGUS FERİYANSYAH
Next Inspection Date : 05 JANUARI 2027

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Certificate Inflatable Liferaft

Cert.No : 008/MJAP/ILR/I/26

• Customer	: PT. PAN MARITIME WIRA PAWITRA	• Name Of Ship	: CB. PAN MARINE 12
• Manufacturer	: JIANGSU HAINING	• Carrying Capacity	: 25 Persons
• Liferaft Type	: HNF - A 25	• Date Of Manufacture	: 02 - 2012
• Serial No.	: 12070	• Emergency Pack Type	: SOLAS A PACK
• CO ² Cylinder No.	Containing CO ²	Containing N ²	Total Wt
1. 613095	4,300 Kg	0,300 Kg	15,68 Kg
2. 620515	4,300 Kg	0,300 Kg	14,64 Kg

THIS IS TO CERTIFY that

1. The above - mentoined inflatable liferaft has been inspected, repaired and tested and found to be in compliance with the under - mentioned requirements, the liferaft in serviceable condition.
INTERNATIONAL CONVENTION FOR THE SAFETY OL LIFE AT SEA (SOLAS) and
INTERNATIONAL LIFE - SAVING APPLIANCE (LSA) CODE
2. The technical condition of the equipment and appliances has been found to satisfaction, and the tested data report attached.
3. The technical condition of the above - mentioned inflatable liferaft has been found to satisfaction, end the log card has been endorsed accordingly.

• Date Of Issue : 06 Januari 2026
• Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGA JAYA ABADI PERKASA





PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@gmail.com

LIFERAFT SERVICE REPORT

In Accordance to IMO Resolution MSC.388(94) Amandment to Resolution A.761(18)

Certificate No.: 008/MJAP/I/26

GENERAL PARTICULARS			
Name Of Ship	: CB. PAN MARINE 12	Nationality/Port of Registry	: INDONESIA
Owner	: PT. PAN MARITIME WIRA PAWITRA	Call Sign	: YDB4152
IMO-No	: 9656113	MMSI No	: 525010182
Class	: -	Date of Service	: 06 JANUARI 2026
Kind Of Service			
☒ Annual ☒ 5 Yearly ☒ Repair			

REMARKS :

" Food Ration, Drinking Water, First Aid Kit, Anti Seasickness, Painting & Marking Label "

DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK
CONTAINER SHELL		Installation Valve, Hose	OK	Leak Stoppers	OK
Label/Markings	RN	"T/Y" Place Connector	OK	Sponges	OK
Handling Beckets	OK	Protection Pads	OK	Bailers	OK
Gasket/Strap Packing List	OK	CO2 Cylinder (s)	OK	Spare Sea Anchor	OK
Painter Line	OK	Operating Cable & Condukt	OK	Torch, Signaling	OK
ID Container	RN	Operating Head	OK	Spare Batteries	OK
Valise Fabric/Plastic	RN	SURVEY OF INTERIOR		Whistle	OK
Eyelets	OK	Buoyancies Fabric	OK	Fishing Kit	OK
Painter Line Pockets	OK	Safety Relief Valves	NA	Can Openers	OK
Bursting Band	RN	Grabline & Patches/Loops	OK	Paddles	OK
Strapping	RN	Thwart, Fabric	NA	Spare Bulb For Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valves	OK	Drinking Vessel	OK
Buoyancies, Fabric	OK	Arches, Fabric	OK	Seasickness Bag	OK
Inlet Valves	OK	Center Column Fabric	NA	Signal Mirror	OK
Deflation Plugs/Valves	OK	Light Battery	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Topping Up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridle / Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (S)	RN	• EMERGENCY PACK •	
Outer Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration	25 Pcs
Retro Reflective Tape	OK	Inner Floor, Fabric	OK	Expired Date	01/2029
Seam and Taping	OK	Topping Up Valves	NA	Drinking Water	75 Pcs
Rain Water Catchment	OK	Deflation Up Valves	NA	Expired Date	01/2029
Exterior Lighting System	OK	Emergency Pack Loops	OK	Smoke Signal	2 Pcs
Arch Deflation Valve	OK	Aerial Sockets/Tie-Tapes	OK	Expired Date	12/2026
Entrance Sleeves	OK	Floor Reeds	OK	Parachute Signal	4 Pcs
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Expired Date	12/2026
Retaining Straps	OK	Knife Sheath	OK	Red Hand Flare	6 Pcs
Stabilizing Pockets	OK	Sea Anchor	OK	Expired Date	12/2026
Cylinder Pockets	OK	ACCESSORY BAG	OK	First Aid Kit	1 Pcs
Painter Lashing/Storage	OK	Bellow Of Pump	OK	Expired Date	01/2028
(DKF) Loud Test Davit	NA	Light Stick	NA	Anti Seasickness	150 Pcs
Launch And Raft		Repair Kit	OK	Expired Date	04/2030

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "

** Working Code : (RP = Repair), (RN = Renewed), (OK = Good), (EXP = Expired), (SP = Supply), (CH = Charge) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Sempur Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@gmail.com

Certificate No.: 008/MJAP/I/26

RAFT AND CYLINDER TEST

RAFT AND CYLINDER TEST									
PREASURE TEST	Start			Finish			Preasure	Safety Valves	
	Time	Temp (°C)	Preasure (mmHg)	Time	Temp (°C)	Preasure (mmHg)	Droe (mmHg)	Blow Off (mmhg)	Reseat (mmhg)
Upper Bouyance	10.00	30	131	11.00	30	130	2	161	131
Lower Bouyance	10.00	30	131	11.00	30	130	2	167	131
Floor	-	-	-	-	-	-	-	-	-
Canopy	-	-	-	-	-	-	-	-	-
GAS CYLINDER TEST	Cylinder Number		Manufacture Date		Charge Date	Weight of Cylinder Kg	Weight of CO² Kg	Weight of N² Kg	Total Weight Kg
Cylinder No.1	613095		-		-	-	4,300	0,300	15,68
Cylinder No.2	620515		-		-	-	4,300	0,300	14,64
DAVID LAUNCHABLE RAFT	Remarks	RES:A.761(18)		Remarks		DATE			
Load Test Date:	-	WP-TEST		YES		6/1/2026			
Suspension Straps/Patches	-	FS-TEST		-		-			
Shackle	-	NAP-TEST		-		-			
Steering Line With Patches	-	GI-TEST		-		-			
Bowsing Line With Patches	-	RAFT		Serial No.		12070		Man of date : 02 - 2012	
Container Line Incl. Pocket	-			Type		HNF - A25		Capacity : 25 Persons	
Pocket for Steering/Bowsing Lines	-			Merk		JIANGSU HAENING			
"RAFT IN GOOD CONDOTION"									


Frequency of test

SERVICING INTERVALS	TEST METHODS
End of first year	Wp Test
End of second year	Wp Test
End of third year	Wp Test
End of fourth year	Wp Test
End of fifth year	GI Test
End of sixth year	Wp Test
End of seventh year	Wp Test
End of eighth year	Wp Test
End of ninth year	Wp Test
End of tenth year	GI Test + FS
Eleventh to fourteenth year	GI Test + FS
fifteenth year	NAP test + FS
Sixteenth to nineteenth year	GI test + NAP + FS
Twentieth year	NAP test + FS
Twenty-first to twenty-fourth year	GI test + NAP + FS
Twenty fifth year onwards	GI test + NAP + FS

Working Code :

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam

Mengetahui,



Surveyor : AGUS FERİYANSYAH
Next Inspection Date : 05 JANUARI 2027

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Certificate Inflatable Liferaft

Cert.No : 009/MJAP/ILR/I/26

• Customer	: PT. PAN MARITIME WIRA PAWITRA	• Name Of Ship	: CB. PAN MARINE 12
• Manufacturer	: JIANGSU HAINING	• Carrying Capacity	: 25 Persons
• Liferaft Type	: HNF - A 25	• Date Of Manufacture	: 02 - 2012
• Serial No.	: 12076	• Emergency Pack Type	: SOLAS A PACK
• CO ² Cylinder No.	Containing CO ²	Containing N ²	Total Wt
1. 613103	4,300 Kg	0,300 Kg	14,58 Kg
2. 613069	4,300 Kg	0,300 Kg	14,61 Kg

THIS IS TO CERTIFY that

1. The above - mentoined inflatable liferaft has been inspected, repaired and tested and found to be in compliance with the under - mentioned requirements, the liferaft in serviceable condition.
INTERNATIONAL CONVENTION FOR THE SAFETY OL LIFE AT SEA (SOLAS) and
INTERNATIONAL LIFE - SAVING APPLIANCE (LSA) CODE
2. The technical condition of the equipment and appliances has been found to satisfaction, and the tested data report attached.
3. The technical condition of the above - mentioned inflatable liferaft has been found to satisfaction, end the log card has been endorsed accordingly.

• Date Of Issue : 06 Januari 2026
• Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGA JAYA ABADI PERKASA





PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

LIFERAFT SERVICE REPORT

In Accordance to IMO Resolution MSC.388(94) Amandment to Resolution A.761(18)

Certificate No.: 009/MJAP/I/26

GENERAL PARTICULARS			
Name Of Ship	: CB. PAN MARINE 12	Nationality/Port of Registry	: INDONESIA
Owner	: PT. PAN MARITIME WIRA PAWITRA	Call Sign	: YDB4152
IMO-No	: 9656113	MMSI No	: 525010182
Class	: -	Date of Service	: 06 JANUARI 2026
Kind Of Service			
☒ Annual ☒ 5 Yearly ☒ Repair			

REMARKS :

" First Aid Kit, Anti Seasickness, Painting & Marking Label "

DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK
CONTAINER SHELL		Installation Valve, Hose	OK	Leak Stoppers	OK
Label/Markings	RN	"T/Y" Place Connector	OK	Sponges	OK
Handling Beckets	OK	Protection Pads	OK	Bailers	OK
Gasket/Strap Packing List	OK	CO2 Cylinder (s)	OK	Spare Sea Anchor	OK
Painter Line	OK	Operating Cable & Conduit	OK	Torch, Signaling	OK
ID Container	RN	Operating Head	OK	Spare Batteries	OK
Valise Fabric/Plastic	RN	SURVEY OF INTERIOR		Whistle	OK
Eyelets	OK	Buoyancies Fabric	OK	Fishing Kit	OK
Painter Line Pockets	OK	Safety Relief Valves	NA	Can Openers	OK
Bursting Band	RN	Grabline & Patches/Loops	OK	Paddles	OK
Strapping	RN	Thwart,Fabric	NA	Spare Bulb For Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valves	OK	Drinking Vessel	OK
Buoyancies,Fabric	OK	Arches, Fabric	OK	Seasickness Bag	OK
Inlet Valves	OK	Center Column Fabric	NA	Signal Mirror	OK
Deflation Plugs/Valves	OK	Light Battery	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Topping Up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridle / Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (S)	RN	• EMERGENCY PACK •	
Outer Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration	25 Pcs
Retro Reflective Tape	OK	Inner Floor, Fabric	OK	Expired Date	12/2026
Seam and Taping	OK	Topping Up Valves	NA	Drinking Watter	75 Pcs
Rain Water Catchment	OK	Deflation Up Valves	NA	Expired Date	12/2026
Exterior Linghting System	OK	Emergency Pack Loops	OK	Smoke Signal	2 Pcs
Arch Deflation Valve	OK	Aerial Sockets/Tie-Tapes	OK	Expired Date	12/2026
Entrance Sleeves	OK	Floor Reeds	OK	Parachute Signal	4 Pcs
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Expired Date	12/2026
Retaining Straps	OK	Knife Sheath	OK	Red Hand Flare	6 Pcs
Stabilizing Pockets	OK	Sea Anchor	OK	Expired Date	12/2026
Cylinder Pockets	OK	ACCESSORY BAG	OK	First Aid Kit	1 Pcs
Painter Lashing/Storage	OK	Bellow Of Pump	OK	Expired Date	01/2028
(DKF) Loud Test Davit	NA	Light Stick	NA	Anti Seasickness	150 Pcs
Launch And Raft		Repair Kit	OK	Expired Date	04/2030

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "

** Working Code : (RP = Repair) , (RN = Renewed) , (OK = Good) , (EXP = Expired) , (SP = Supply) , (CH = Charge) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

Certificate No.: 009/MJAP/I/26

RAFT AND CYLINDER TEST

RAFT AND CYLINDER TEST									
PREASURE TEST	Start			Finish			Preasure	Safety Valves	
	Time	Temp (°C)	Pressure (mmHg)	Time	Temp (°C)	Pressure (mmHg)	Droe (mmHg)	Blow Off (mmhg)	Reseat (mmhg)
Upper Bouyance	10.00	30	131	11.00	30	130	2	161	131
Lower Bouyance	10.00	30	131	11.00	30	130	2	167	131
Floor	-	-	-	-	-	-	-	-	-
Canopy	-	-	-	-	-	-	-	-	-
GAS CYLINDER TEST	Cylinder Number		Manufacture Date		Charge Date	Weight of Cylinder Kg	Weight of CO² Kg	Weight of N² Kg	Total Weight Kg
Cylinder No.1	613103		-		-	-	4,300	0,300	14,58
Cylinder No.2	613069		-		-	-	4,300	0,300	14,61
DAVID LAUNCHABLE RAFT	Remarks	RES:A.761(18)		Remarks		DATE			
Load Test Date:	-	WP-TEST		YES		6/1/2026			
Suspension Straps/Patches	-	FS-TEST		-		-			
Shackle	-	NAP-TEST		-		-			
Steering Line With Patches	-	GI-TEST		-		-			
Bowsing Line With Patches	-	RAFT		Serial No.		12076		Man of date : 02 - 2012	
Container Line Incl. Pocket	-			Type		HNF - A25		Capacity : 25 Persons	
Pocket for Steering/Bowsing Lines	-			Merk		JIANGSU HAINING			
"RAFT IN GOOD CONDOTION"									

"RAFT IN GOOD CONDOTION"

Frequency of test

SERVICING INTERVALS	TEST METHODS
End of first year	Wp Test
End of second year	Wp Test
End of third year	Wp Test
End of fourth year	Wp Test
End of fifth year	GI Test
End of sixth year	Wp Test
End of seventh year	Wp Test
End of eighth year	Wp Test
End of ninth year	Wp Test
End of tenth year	GI Test + FS
Eleventh to fourteenth year	GI Test + FS
fifteenth year	NAP test + FS
Sixteenth to nineteenth year	GI test + NAP + FS
Twentieth year	NAP test + FS
Twenty-first to twenty-fourth year	GI test + NAP + FS
Twenty fifth year onwards	GI test + NAP + FS

Working Code :

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam

Mengetahui,

Ad. KEPALA KANTOR KSOP UTAMA TANJUNG PRIOK
KAPALAN DAN KEPেলাUTAN



Surveyor : AGUS FERİYANSYAH
Next Inspection Date : 05 JANUARI 2027

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara
Telp. (021) 440 8538 Fax. (021) 440 8538
E-mail : megajayaabadi@ymail.com

Certificate Inflatable Liferaft

Cert.No : 010/MJAP/ILRI/26

• Customer	: PT. PAN MARITIME WIRA PAWITRA	• Name Of Ship	: CB. PAN MARINE 12
• Manufacturer	: JIANGSU HAINING	• Carrying Capacity	: 25 Persons
• Liferaft Type	: HNF - A 25	• Date Of Manufacture	: 02 - 2012
• Serial No.	: 12080	• Emergency Pack Type	: SOLAS A PACK
• CO ² Cylinder No.	Containing CO ²	Containing N ²	Total Wt
1. 620491	4,300 Kg	0,300 Kg	14,58 Kg
2. 613039	4,300 Kg	0,300 Kg	14,61 Kg

THIS IS TO CERTIFY that

1. The above - mentoined inflatable liferaft has been inspected, repaired and tested and found to be in compliance with the under - mentioned requirements, the liferaft in serviceable condition.
INTERNATIONAL CONVENTION FOR THE SAFETY OL LIFE AT SEA (SOLAS) and
INTERNATIONAL LIFE - SAVING APPLIANCE (LSA) CODE
2. The technical condition of the equipment and appliances has been found to satisfaction, and the tested data report attached.
3. The technical condition of the above - mentioned inflatable liferaft has been found to satisfaction, end the log card has been endorsed accordingly.

• Date Of Issue : 06 Januari 2026
• Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGA JAYA ABADI PERKASA





PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@gmail.com

LIFERAFT SERVICE REPORT

In Accordance to IMO Resolution MSC.388(94) Amandment to Resolution A.761(18)

Certificate No.: 010/MJAP/I/26

GENERAL PARTICULARS	
Name Of Ship : CB. PAN MARINE 12	Nationality/Port of Registry : INDONESIA
Owner : PT. PAN MARITIME WIRA PAWITRA	Call Sign : YDB4152
IMO-No : 9656113	MMSI No : 525010182
Class : -	Date of Service : 06 JANUARI 2026
Kind Of Service	
☒ Annual	☒ 5 Yearly
☒ Repair	

REMARKS :

" Food Ration, Drinking Water, First Aid Kit, Anti Seasickness, Painting & Marking Label "

DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK
CONTAINER SHELL		Installation Valve, Hose	OK	Leak Stoppers	OK
Label/Markings	RN	"T/Y" Place Connector	OK	Sponges	OK
Handling Beckets	OK	Protection Pads	OK	Bailers	OK
Gasket/Strap Packing List	OK	CO2 Cylinder (s)	OK	Spare Sea Anchor	OK
Painter Line	OK	Operating Cable & Conduit	OK	Torch, Signaling	OK
ID Container	RN	Operating Head	OK	Spare Batteries	OK
Valise Fabric/Plastic	RN	SURVEY OF INTERIOR		Whistle	OK
Eyelets	OK	Buoyancies Fabric	OK	Fishing Kit	OK
Painter Line Pockets	OK	Safety Relief Valves	NA	Can Openers	OK
Bursting Band	RN	Grabline & Patches/Loops	OK	Paddles	OK
Strarpping	RN	Thwart,Fabric	NA	Spare Bulb For Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valves	OK	Drinking Vessel	OK
Buoyancies,Fabric	OK	Arches, Fabric	OK	Seasickness Bag	OK
Inlet Valves	OK	Center Column Fabric	NA	Signal Mirror	OK
Deflation Plugs/Valves	OK	Light Battery	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Topping Up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridie / Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (S)	RN	* EMERGENCY PACK *	
Outher Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration 25 Pcs	
Retro Reflective Tape	OK	Inner Floor, Fabric	OK	Expired Date 01/2029	RN
Seam and Taping	OK	Topping Up Valves	NA	Drinking Watter 75 Pcs	
Rain Water Catchment	OK	Deflation Up Valves	NA	Expired Date 01/2029	RN
Exterior Linghting System	OK	Emergency Pack Loops	OK	Smoke Signal 2 Pcs	
Arch Deflation Valve	OK	Aerial Sockets/Tie-Tapes	OK	Expired Date 12/2026	OK
Entrance Sleeves	OK	Floor Reeds	OK	Parachute Signal 4 Pcs	
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Expired Date 12/2026	OK
Retaining Straps	OK	Knife Sheath	OK	Red Hand Flare 6 Pcs	
Stabilizing Pockets	OK	Sea Anchor	OK	Expired Date 12/2026	OK
Cylinder Pockets	OK	ACCESSORY BAG	OK	First Aid Kit 1 Pcs	
Painter Lashing/Storage	OK	Bellow Of Pump	OK	Expired Date 01/2028	RN
(DKF) Loud Test Davit		Light Stick	NA	Anti Seasickness 150 Pcs	
Launch And Raft	NA	Repair Kit	OK	Expired Date 04/2030	RN

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "

** Working Code : (RP = Repair) , (RN = Renewed) , (OK = Good) , (EXP = Expired) , (SP = Supply) , (CH = Charge) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@gmail.com

Certificate No.: 010/MJAP/I/26

RAFT AND CYLINDER TEST

RAFT AND CYLINDER TEST									
PREASURE TEST	Start			Finish			Preasure	Safety Valves	
	Time	Temp (°C)	Preasure (mmHg)	Time	Temp (°C)	Preasure (mmHg)	Droe (mmHg)	Blow Off (mmhg)	Reseat (mmhg)
Upper Bouyance	10.00	30	131	11.00	30	130	2	161	131
Lower Bouyance	10.00	30	131	11.00	30	130	2	167	131
Floor	-	-	-	-	-	-	-	-	-
Canopy	-	-	-	-	-	-	-	-	-
GAS CYLINDER TEST	Cylinder Number		Manufacture Date		Charge Date	Weight of Cylinder Kg	Weight of CO² Kg	Weight of N² Kg	Total Weight Kg
Cylinder No.1	620491		-		-	-	4,300	0,300	14,58
Cylinder No.2	613039		-		-	-	4,300	0,300	14,61
DAVID LAUNCHABLE RAFT	Remarks	RES:A.761(18)		Remarks		DATE			
Load Test Date:	-	WP-TEST		YES		6/1/2026			
Suspension Straps/Patches	-	FS-TEST		-		-			
Shackle	-	NAP-TEST		-		-			
Steering Line With Patches	-	GI-TEST		-		-			
Bowsing Line With Patches	-	RAFT		Serial No.		12080		Man of date : 02 - 2012	
Container Line Incl. Pocket	-			Type		HNF - A25		Capacity : 25 Persons	
Pocket for Steering/Bowsing Lines	-			Merk		JIANGSU HAINING			
"RAFT IN GOOD CONDOTION"									

Frequency of test

SERVICING INTERVALS	TEST METHODS
End of first year	Wp Test
End of second year	Wp Test
End of third year	Wp Test
End of fourth year	Wp Test
End of fifth year	GI Test
End of sixth year	Wp Test
End of seventh year	Wp Test
End of eighth year	Wp Test
End of ninth year	Wp Test
End of tenth year	GI Test + FS
Eleventh to fourteenth year	GI Test + FS
fifteenth year	NAP test + FS
Sixteenth to nineteenth year	GI test + NAP + FS
Twentieth year	NAP test + FS
Twenty-first to twenty-fourth year	GI test + NAP + FS
Twenty fifth year onwards	GI test + NAP + FS

Working Code :

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam

Mengetahui,

AB. KEPALA KANTOR KSOP UTAMA TANJUNG PRIOK
KANTOR PERKAPALAN DAN KEPELAUTAN

ST. M.Mr
Pembina
NIP. 197001122007121001



Surveyor : AGUS FERIYANSYAH
Next Inspection Date : 05 JANUARI 2027

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@gmail.com

Certificate Inflatable Liferaft

Cert.No : 011/MJAP/ILR/I/26

• Customer	: PT. PAN MARITIME WIRA PAWITRA	• Name Of Ship	: CB. PAN MARINE 12
• Manufacturer	: JIANGSU HAINING	• Carrying Capacity	: 25 Persons
• Liferaft Type	: HNF - A 25	• Date Of Manufacture	: 02 - 2012
• Serial No.	: 12081	• Emergency Pack Type	: SOLAS A PACK
• CO ² Cylinder No.	Containing CO ²	Containing N ²	Total Wt
1. 613044	4,300 Kg	0,300 Kg	14,80 Kg
2. 613069	4,300 Kg	0,300 Kg	14,80 Kg

THIS IS TO CERTIFY that

1. The above - mentoined inflatable liferaft has been inspected, repaired and tested and found to be in compliance with the under - mentioned requirements, the liferaft in serviceable condition.
INTERNATIONAL CONVENTION FOR THE SAFETY OL LIFE AT SEA (SOLAS) and
INTERNATIONAL LIFE - SAVING APPLIANCE (LSA) CODE
2. The technical condition of the equipment and appliances has been found to satisfaction, and the tested data report attached.
3. The technical condition of the above - mentioned inflatable liferaft has been found to satisfaction, end the log card has been endorsed accordingly.

• Date Of Issue : 06 Januari 2026
• Date Of next inspection : 05 Januari 2027



For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGA JAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@gmail.com

LIFERAFT SERVICE REPORT

In Accordance to IMO Resolution MSC.388(94) Amandment to Resolution A.761(18)

Certificate No.: 011/MJAP/1/26

GENERAL PARTICULARS			
Name Of Ship	: CB. PAN MARINE 12	Nationality/Port of Registry	: INDONESIA
Owner	: PT. PAN MARITIME WIRA PAWITRA	Call Sign	: YDB4152
IMO-No	: 9656113	MMSI No	: 525010182
Class	: -	Date of Service	: 06 JANUARI 2026
Kind Of Service			
☒ Annual ☒ 5 Yearly ☒ Repair			

REMARKS :

" Food Ration, Drinking Water, First Aid Kit, Anti Seasickness, Painting & Marking Label "

DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK
CONTAINER SHELL		Installation Valve, Hose	OK	Leak Stoppers	OK
Label/Markings	RN	"T/Y" Place Connector	OK	Sponges	OK
Handling Beckets	OK	Protection Pads	OK	Bailers	OK
Gasket/Strap Packing List	OK	CO2 Cylinder (s)	OK	Spare Sea Anchor	OK
Painter Line	OK	Operating Cable & Condukt	OK	Torch, Signaling	OK
ID Container	RN	Operating Head	OK	Spare Batteries	OK
Valise Fabric/Plastic	RN	SURVEY OF INTERIOR		Whistle	OK
Eyelets	OK	Buoyancies Fabric	OK	Fishing Kit	OK
Painter Line Pockets	OK	Safety Relief Valves	NA	Can Openers	OK
Bursting Band	RN	Grabline & Patches/Loops	OK	Paddles	OK
Strarpping	RN	Thwart,Fabric	NA	Spare Bulb For Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valves	OK	Drinking Vessel	OK
Buoyancies,Fabric	OK	Arches, Fabric	OK	Seasickness Bag	OK
Inlet Valves	OK	Center Column Fabric	NA	Signal Mirror	OK
Deflation Plugs/Valves	OK	Light Battery	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Topping Up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridie / Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (S)	RN	EMERGENCY PACK	
Outher Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration	25 Pcs
Retro Reflective Tape	OK	Inner Floor, Fabric	OK	Expired Date	01/2029
Seam and Taping	OK	Topping Up Valves	NA	Drinking Watter	75 Pcs
Rain Water Catchment	OK	Deflation Up Valves	NA	Expired Date	01/2029
Exterior Linghting System	OK	Emergency Pack Loops	OK	Smoke Signal	2 Pcs
Arch Deflation Valve	OK	Aerial Sockets/Tie-Tapes	OK	Expired Date	12/2026
Entrance Sleeves	OK	Floor Reeds	OK	Parachute Signal	4 Pcs
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Expired Date	12/2026
Retaining Straps	OK	Knife Sheath	OK	Red Hand Flare	6 Pcs
Stabilizing Pockets	OK	Sea Anchor	OK	Expired Date	12/2026
Cylinder Pockets	OK	ACCESSORY BAG	OK	First Aid Kit	1 Pcs
Painter Lashing/Storage	OK	Bellow Of Pump	OK	Expired Date	01/2028
(DKF) Loud Test Davit	NA	Light Stick	NA	Anti Seasickness	150 Pcs
Launch And Raft		Repair Kit	OK	Expired Date	04/2030

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "

** Working Code : (RP = Repair), (RN = Renewed), (OK = Good), (EXP = Expired), (SP = Supply), (CH = Charge) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538
Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

Certificate No.: 011/MJAP/I/26

RAFT AND CYLINDER TEST

RAFT AND CYLINDER TEST									
PREASURE TEST	Start			Finish			Preasure	Safety Valves	
	Time	Temp (°C)	Preasure (mmHg)	Time	Temp (°C)	Preasure (mmHg)	Droe (mmHg)	Blow Off (mmhg)	Reseat (mmhg)
Upper Bouyance	10.00	30	131	11.00	30	130	2	161	131
Lower Bouyance	10.00	30	131	11.00	30	130	2	167	131
Floor	-	-	-	-	-	-	-	-	-
Canopy	-	-	-	-	-	-	-	-	-
GAS CYLINDER TEST	Cylinder Number		Manufacture Date		Charge Date	Weight of Cylinder Kg	Weight of CO² Kg	Weight of N² Kg	Total Weight Kg
Cylinder No.1	613044		-		-	-	4,300	0,300	14,80
Cylinder No.2	613069		-		-	-	4,300	0,300	14,80
DAVID LAUNCHABLE RAFT	Remarks	RES:A.761(18)		Remarks		DATE			
Load Test Date:	-	WP-TEST		YES		6/1/2026			
Suspension Straps/Patches	-	FS-TEST		-		-			
Shackle	-	NAP-TEST		-		-			
Steering Line With Patches	-	GI-TEST		-		-			
Bowsing Line With Patches	-	RAFT		Serial No.		12081		Man of date : 02 - 2012	
Container Line Incl. Pocket	-			Type		HNF - A25		Capacity : 25 Persons	
Pocket for Steering/Bowsing Lines	-			Merk		JIANGSU HAINING			
"RAFT IN GOOD CONDOTION"									

Frequency of test

SERVICING INTERVALS	TEST METHODS
End of first year	Wp Test
End of second year	Wp Test
End of third year	Wp Test
End of fourth year	Wp Test
End of fifth year	GI Test
End of sixth year	Wp Test
End of seventh year	Wp Test
End of eighth year	Wp Test
End of ninth year	Wp Test
End of tenth year	GI Test + FS
Eleventh to fourteenth year	GI Test + FS
fifteenth year	NAP test + FS
Sixteenth to nineteenth year	GI test + NAP + FS
Twentieth year	NAP test + FS
Twenty-first to twenty-fourth year	GI test + NAP + FS
Twenty fifth year onwards	GI test + NAP + FS

Working Code :

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam

Mengetahui,

An. KEPALA KANTOR KSOP UTAMA TANJUNG PRIOK
KANTOR KEPALA PALAN DAN KEPALAUTAN



Surveyor	: AGUS FERIYANSYAH
Next Inspection Date	: 05 JANUARI 2027

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Certificate Inflatable Liferaft

Cert.No : 012/MJAP/ILR/I/26

• Customer	: PT. PAN MARITIME WIRA PAWITRA	• Name Of Ship	: CB. PAN MARINE 12
• Manufacturer	: VIKING	• Carrying Capacity	: 25 Persons
• Liferaft Type	: 25 - DK+	• Date Of Manufacture	: 01 - 2007
• Serial No.	: 10860113	• Emergency Pack Type	: SOLAS A PACK
• CO ² Cylinder No.	Containing CO ²	Containing N ²	Total Wt
1. 10004628	10,190 Kg	0,420 Kg	28,050 Kg

THIS IS TO CERTIFY that

1. The above - mentoined inflatable liferaft has been inspected, repaired and tested and found to be in compliance with the under - mentioned requirements, the liferaft in serviceable condition.
INTERNATIONAL CONVENTION FOR THE SAFETY OL LIFE AT SEA (SOLAS) and
INTERNATIONAL LIFE - SAVING APPLIANCE (LSA) CODE
2. The technical condition of the equipment and appliances has been found to satisfaction, and the tested data report attached.
3. The technical condition of the above - mentioned inflatable liferaft has been found to satisfaction, end the log card has been endorsed accordingly.

• Date Of Issue : 06 Januari 2026
• Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGA JAYA ABADI PERKASA





PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538
Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

LIFERAFT SERVICE REPORT

In Accordance to IMO Resolution MSC.388(94) Amandment to Resolution A.761(18)

Certificate No.: 012/MJAP/I/26

GENERAL PARTICULARS

Name Of Ship : CB. PAN MARINE 12	Nationality/Port of Registry : INDONESIA
Owner : PT. PAN MARITIME WIRA PAWITRA	Call Sign : YDB4152
IMO-No : 9656113	MMSI No : 525010182
Class : -	Date of Service : 06 JANUARI 2026
Kind Of Service	
☒ Annual ☒ 5 Yearly ☒ Repair	

REMARKS :

" Food Ration, Drinking Water, First Aid Kit, Anti Seasickness, Painting & Marking Label "

DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK
CONTAINER SHELL		Installation Valve, Hose	OK	Leak Stoppers	OK
Label/Markings	RN	"T/Y" Place Connector	OK	Sponges	OK
Handling Beckets	OK	Protection Pads	OK	Bailers	OK
Gasket/Strap Packing List	OK	CO2 Cylinder (s)	OK	Spare Sea Anchor	OK
Painter Line	OK	Operating Cable & Conduit	OK	Torch, Signaling	OK
ID Container	RN	Operating Head	OK	Spare Batteries	OK
Valise Fabric/Plastic	RN	SURVEY OF INTERIOR		Whistle	OK
Eyelets	OK	Buoyancies Fabric	OK	Fishing Kit	OK
Painter Line Pockets	OK	Safety Relief Valves	NA	Can Openers	OK
Bursting Band	RN	Grabline & Patches/Loops	OK	Paddles	OK
Strarpping	RN	Thwart,Fabric	NA	Spare Bulb For Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valves	OK	Drinking Vessel	OK
Buoyancies,Fabric	OK	Arches, Fabric	OK	Seasickness Bag	OK
Inlet Valves	OK	Center Column Fabric	NA	Signal Mirror	OK
Deflation Plugs/Valves	OK	Light Battery	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Topping Up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridie / Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (S)	RN	~* EMERGENCY PACK ~*	
Outher Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration 25 Pcs	
Retro Reflective Tape	OK	Inner Floor, Fabric	OK	Expired Date 01/2029	RN
Seam and Taping	OK	Topping Up Valves	NA	Drinking Watter 75 Pcs	
Rain Water Catchment	OK	Deflation Up Valves	NA	Expired Date 01/2029	RN
Exterior Linghting System	OK	Emergency Pack Loops	OK	Smoke Signal 2 Pcs	
Arch Deflation Valve	OK	Aerial Sockets/Tie-Tapes	OK	Expired Date 12/2026	OK
Entrance Sleeves	OK	Floor Reeds	OK	Parachute Signal 4 Pcs	
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Expired Date 12/2026	OK
Retaining Straps	OK	Knife Sheath	OK	Red Hand Flare 6 Pcs	
Stabilizing Pockets	OK	Sea Anchor	OK	Expired Date 12/2026	OK
Cylinder Pockets	OK	ACCESSORY BAG	OK	First Aid Kit 1 Pcs	
Painter Lashing/Storage	OK	Bellow Of Pump	OK	Expired Date 01/2028	RN
(DKF) Loud Test Davit	NA	Light Stick	NA	Anti Seasickness 150 Pcs	
Launch And Raft		Repair Kit	OK	Expired Date 04/2030	RN

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "

** Working Code : (RP = Repair), (RN = Renewed), (OK = Good), (EXP = Expired), (SP = Supply), (CH = Charge) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

Certificate No.: 012/MJAP/I/26

RAFT AND CYLINDER TEST

RAFT AND CYLINDER TEST									
PREASURE TEST	Start			Finish			Preasure	Safety Valves	
	Time	Temp (°C)	Pressure (mmHg)	Time	Temp (°C)	Pressure (mmHg)	Droe (mmHg)	Blow Off (mmhg)	Reseat (mmhg)
Upper Bouyance	10.00	30	131	11.00	30	130	2	161	131
Lower Bouyance	10.00	30	131	11.00	30	130	2	167	131
Floor	-	-	-	-	-	-	-	-	-
Canopy	-	-	-	-	-	-	-	-	-
GAS CYLINDER TEST	Cylinder Number		Manufacture Date		Charge Date	Weight of Cylinder Kg	Weight of CO² Kg	Weight of N² Kg	Total Weight Kg
Cylinder No.1	10004628		-		-	-	10,190	0,420	28,050
Cylinder No.2	-		-		-	-	-	-	-
DAVID LAUNCHABLE RAFT	Remarks	RES:A.761(18)		Remarks		DATE			
Load Test Date:	-	WP-TEST		YES		6/1/2026			
Suspension Straps/Patches	-	FS-TEST		-		-			
Shackle	-	NAP-TEST		-		-			
Steering Line With Patches	-	GI-TEST		-		-			
Bowsing Line With Patches	-	RAFT		Serial No.		10860113		Man of date : 01 - 2007	
Container Line Incl. Pocket	-			Type		25 - DK +		Capacity : 25 Persons	
Pocket for Steering/Bowsing Lines	-			Merk		VIKING			
"RAFT IN GOOD CONDOTION"									

Frequency of test

SERVICING INTERVALS	TEST METHODS
End of first year	Wp Test
End of second year	Wp Test
End of third year	Wp Test
End of fourth year	Wp Test
End of fifth year	GI Test
End of sixth year	Wp Test
End of seventh year	Wp Test
End of eighth year	Wp Test
End of ninth year	Wp Test
End of tenth year	GI Test + FS
Eleventh to fourteenth year	GI Test + FS
fifteenth year	NAP test + FS
Sixteenth to nineteenth year	GI test + NAP + FS
Twentieth year	NAP test + FS
Twenty-first to twenty-fourth year	GI test + NAP + FS
Twenty fifth year onwards	GI test + NAP + FS

Working Code :

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam

Mengetahui,

An. KEPALA KANTOR KSOP UTAMA TANJUNG PRIOK

KEMENTERIAN PERHUBUNGAN



Surveyor : AGUS FERIYANSYAH
Next Inspection Date : 05 JANUARI 2027

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Certificate Inflatable Liferaft

Cert.No : 013/MJAP/ILR/I/26

• Customer	: PT. PAN MARITIME WIRA PAWITRA	• Name Of Ship	: CB. PAN MARINE 12
• Manufacturer	: SHANGHAI YOULONG RUBBER	• Carrying Capacity	: 20 Persons
• Liferaft Type	: KHA - 20	• Date Of Manufacture	: 03 - 2006
• Serial No.	: 2431	• Emergency Pack Type	: SOLAS A PACK
• CO ² Cylinder No.	Containing CO ²	Containing N ²	Total Wt
1. 211773	3,600 Kg	0,250 Kg	13,08 Kg
2. 211725	3,600 Kg	0,250 Kg	13,05 Kg

THIS IS TO CERTIFY that

1. The above - mentoined inflatable liferaft has been inspected, repaired and tested and found to be in compliance with the under - mentioned requirements, the liferaft in serviceable condition.
INTERNATIONAL CONVENTION FOR THE SAFETY OL LIFE AT SEA (SOLAS) and
INTERNATIONAL LIFE - SAVING APPLIANCE (LSA) CODE
2. The technical condition of the equipment and appliances has been found to satisfaction, and the tested data report attached.
3. The technical condition of the above - mentioned inflatable liferaft has been found to satisfaction, end the log card has been endorsed accordingly.

• Date Of Issue : 06 Januari 2026
• Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGA JAYA ABADI PERKASA





PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

LIFERAFT SERVICE REPORT

In Accordance to IMO Resolution MSC.388(94) Amandment to Resolution A.761(18)

Certificate No.: 013/MJAP/I/26

GENERAL PARTICULARS			
Name Of Ship	: CB. PAN MARINE 12	Nationality/Port of Registry	: INDONESIA
Owner	: PT. PAN MARITIME WIRA PAWITRA	Call Sign	: YDB4152
IMO-No	: 9656113	MMSI No	: 525010182
Class	: -	Date of Service	: 06 JANUARI 2026
Kind Of Service			
☒ Annual ☒ 5 Yearly ☒ Repair			

REMARKS :

" First Aid Kit, Anti Seasickness, Painting & Marking Label "

DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK
CONTAINER SHELL		Installation Valve, Hose	OK	Leak Stoppers	OK
Label/Markings	RN	"T/Y" Place Connector	OK	Sponges	OK
Handling Beckets	OK	Protection Pads	OK	Bailers	OK
Gasket/Strap Packing List	OK	CO2 Cylinder (s)	OK	Spare Sea Anchor	OK
Painter Line	OK	Operating Cable & Conduit	OK	Torch, Signaling	OK
ID Container	RN	Operating Head	OK	Spare Batteries	OK
Valise Fabric/Plastic	RN	SURVEY OF INTERIOR		Whistle	OK
Eyelets	OK	Buoyancies Fabric	OK	Fishing Kit	OK
Painter Line Pockets	OK	Safety Relief Valves	NA	Can Openers	OK
Bursting Band	RN	Grabline & Patches/Loops	OK	Paddles	OK
Strapping	RN	Thwart, Fabric	NA	Spare Bulb For Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valves	OK	Drinking Vessel	OK
Buoyancies, Fabric	OK	Arches, Fabric	OK	Seasickness Bag	OK
Inlet Valves	OK	Center Column Fabric	NA	Signal Mirror	OK
Deflation Plugs/Valves	OK	Light Battery	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Topping Up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridle / Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (S)	RN	• EMERGENCY PACK •	
Outer Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration	20 Pcs
Retro Reflective Tape	OK	Inner Floor, Fabric	OK	Expired Date	12/2026
Seam and Taping	OK	Topping Up Valves	NA	Drinking Water	60 Pcs
Rain Water Catchment	OK	Deflation Up Valves	NA	Expired Date	12/2026
Exterior Lighting System	OK	Emergency Pack Loops	OK	Smoke Signal	2 Pcs
Arch Deflation Valve	OK	Aerial Sockets/Tie-Tapes	OK	Expired Date	12/2026
Entrance Sleeves	OK	Floor Reeds	OK	Parachute Signal	4 Pcs
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Expired Date	12/2026
Retaining Straps	OK	Knife Sheath	OK	Red Hand Flare	6 Pcs
Stabilizing Pockets	OK	Sea Anchor	OK	Expired Date	12/2026
Cylinder Pockets	OK	ACCESSORY BAG	OK	First Aid Kit	1 Pcs
Painter Lashing/Storage	OK	Bellow Of Pump	OK	Expired Date	01/2028
(DKF) Loud Test Davit	NA	Light Stick	NA	Anti Seasickness	120 Pcs
Launch And Raft		Repair Kit	OK	Expired Date	04/2030

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "

** Working Code : (RP = Repair), (RN = Renewed), (OK = Good), (EXP = Expired), (SP = Supply), (CH = Charge) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

Certificate No.: 013/MJAP/I/26

RAFT AND CYLINDER TEST

PREASURE TEST	Start			Finish			Preasure	Safety Valves	
	Time	Temp (°C)	Pressure (mmHg)	Time	Temp (°C)	Pressure (mmHg)	Droe (mmHg)	Blow Off (mmhg)	Reseat (mmhg)
Upper Bouyance	10.00	30	131	11.00	30	130	2	161	131
Lower Bouyance	10.00	30	131	11.00	30	130	2	167	131
Floor	-	-	-	-	-	-	-	-	-
Canopy	-	-	-	-	-	-	-	-	-
GAS CYLINDER TEST	Cylinder Number		Manufacture Date		Charge Date	Weight of Cylinder Kg	Weight of CO² Kg	Weight of N² Kg	Total Weight Kg
Cylinder No.1	211773		-		-	-	3,600	0,250	13,08
Cylinder No.2	211725		-		-	-	3,600	0,250	13,05
DAVID LAUNCHABLE RAFT	Remarks	RES:A.761(18)		Remarks		DATE			
Load Test Date:	-	WP-TEST		YES		6/1/2026			
Suspension Straps/Patches	-	FS-TEST		-		-			
Shackle	-	NAP-TEST		-		-			
Steering Line With Patches	-	GI-TEST		-		-			
Bowsing Line With Patches	-	RAFT		Serial No.		2431		Man of date : 03 - 2006	
Container Line Incl. Pocket	-			Type		KHA - 20		Capacity : 20 Persons	
Pocket for Steering/Bowsing Lines	-			Merk		SHANGHAI YOULONG RUBBER			
"RAFT IN GOOD CONDOTION"									

Frequency of test

SERVICING INTERVALS	TEST METHODS
End of first year	Wp Test
End of second year	Wp Test
End of third year	Wp Test
End of fourth year	Wp Test
End of fifth year	GI Test
End of sixth year	Wp Test
End of seventh year	Wp Test
End of eighth year	Wp Test
End of ninth year	Wp Test
End of tenth year	GI Test + FS
Eleventh to fourteenth year	GI Test + FS
fifteenth year	NAP test + FS
Sixteenth to nineteenth year	GI test + NAP + FS
Twentieth year	NAP test + FS
Twenty-first to twenty-fourth year	GI test + NAP + FS
Twenty fifth year onwards	GI test + NAP + FS

Working Code :

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam

Mengetahui,



Surveyor	: AGUS FERIYANSYAH
Next Inspection Date	: 05 JANUARI 2027

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Certificate Inflatable Liferaft

Cert.No : 014/MJAP/ILR/I/26

• Customer	: PT. PAN MARITIME WIRA PAWITRA	• Name Of Ship	: CB. PAN MARINE 12
• Manufacturer	: SHANGHAI STAR RUBBER	• Carrying Capacity	: 20 Persons
• Liferaft Type	: RAFT - A - 20	• Date Of Manufacture	: 07 - 2006
• Serial No.	: A 0620164	• Emergency Pack Type	: SOLAS A PACK
• CO ² Cylinder No.	Containing CO ²	Containing N ²	Total Wt
1. 203753	3,500 Kg	0,240 Kg	12,70 Kg
2. 203488	3,500 Kg	0,240 Kg	12,73 Kg

THIS IS TO CERTIFY that

1. The above - mentoined inflatable liferaft has been inspected, repaired and tested and found to be in compliance with the under - mentioned requirements, the liferaft in serviceable condition.
INTERNATIONAL CONVENTION FOR THE SAFETY OL LIFE AT SEA (SOLAS) and
INTERNATIONAL LIFE - SAVING APPLIANCE (LSA) CODE
2. The technical condition of the equipment and appliances has been found to satisfaction, and the tested data report attached.
3. The technical condition of the above - mentioned inflatable liferaft has been found to satisfaction, end the log card has been endorsed accordingly.

• Date Of Issue : 06 Januari 2026
• Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGA JAYA ABADI PERKASA





PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@gmail.com

LIFERAFT SERVICE REPORT

In Accordance to IMO Resolution MSC.388(94) Amandment to Resolution A.761(18)

Certificate No.: 014/MJAP/I/26

GENERAL PARTICULARS

Name Of Ship : CB. PAN MARINE 12	Nationality/Port of Registry : INDONESIA
Owner : PT. PAN MARITIME WIRA PAWITRA	Call Sign : YDB4152
IMO-No : 9656113	MMSI No : 525010182
Class : -	Date of Service : 06 JANUARI 2026
Kind Of Service	
☒ Annual	☒ 5 Yearly
☒ Repair	

REMARKS :

" Food Ration, Drinking Water, First Aid Kit, Anti Seasickness, Painting & Marking Label "

DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK	DESCRIPTION ITEM	CHECK
CONTAINER SHELL		Installation Valve, Hose	OK	Leak Stoppers	OK
Label/Markings	RN	"T/Y" Place Connector	OK	Sponges	OK
Handling Beckets	OK	Protection Pads	OK	Bailers	OK
Gasket/Strap Packing List	OK	CO2 Cylinder (s)	OK	Spare Sea Anchor	OK
Painter Line	OK	Operating Cable & Conduit	OK	Torch, Signaling	OK
ID Container	RN	Operating Head	OK	Spare Batteries	OK
Valise Fabric/Plastic	RN	SURVEY OF INTERIOR		Whistle	OK
Eyelets	OK	Buoynancies Fabric	OK	Fishing Kit	OK
Painter Line Pockets	OK	Safety Relief Valves	NA	Can Openers	OK
Bursting Band	RN	Grabline & Patches/Loops	OK	Paddles	OK
Strarpping	RN	Thwart,Fabric	NA	Spare Bulb For Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valves	OK	Drinking Vessel	OK
Buoynancies,Fabric	OK	Arches, Fabric	OK	Seasickness Bag	OK
Inlet Valves	OK	Center Column Fabric	NA	Signal Mirror	OK
Deflation Plugs/Valves	OK	Light Battery	OK	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	OK
Boarding Ramp	OK	Topping Up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridie / Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (S)	RN	* EMERGENCY PACK *	
Outher Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration 25 Pcs	
Retro Reflective Tape	OK	Inner Floor, Fabric	OK	Expired Date 01/2029	RN
Seam and Taping	OK	Topping Up Valves	NA	Drinking Watter 75 Pcs	
Rain Water Catchment	OK	Deflation Up Valves	NA	Expired Date 01/2029	RN
Exterior Linghting System	OK	Emergency Pack Loops	OK	Smoke Signal 2 Pcs	
Arch Deflation Valve	OK	Aerial Sockets/Tie-Tapes	OK	Expired Date 12/2026	OK
Entrance Sleeves	OK	Floor Reeds	OK	Parachute Signal 4 Pcs	
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Expired Date 12/2026	OK
Retaining Straps	OK	Knife Sheath	OK	Red Hand Flare 6 Pcs	
Stabilizing Pockets	OK	Sea Anchor	OK	Expired Date 12/2026	OK
Cylinder Pockets	OK	ACCESSORY BAG	OK	First Aid Kit 1 Pcs	
Painter Lashing/Storage	OK	Bellow Of Pump	OK	Expired Date 01/2028	RN
(DKF) Loud Test Davit	NA	Light Stick	NA	Anti Seasickness 150 Pcs	
Launch And Raft		Repair Kit	OK	Expired Date 05/2029	RN

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "

** Working Code : (RP = Repair) , (RN = Renewed) , (OK = Good) , (EXP = Expired) , (SP = Supply) , (CH = Charge) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

Certificate No.: 014/MJAP/I/26

RAFT AND CYLINDER TEST

RAFT AND CYLINDER TEST									
PREASURE TEST	Start			Finish			Preasure	Safety Valves	
	Time	Temp (°C)	Preasure (mmHg)	Time	Temp (°C)	Preasure (mmHg)	Droe (mmHg)	Blow Off (mmhg)	Rescat (mmhg)
Upper Bouyance	10.00	30	131	11.00	30	130	2	161	131
Lower Bouyance	10.00	30	131	11.00	30	130	2	167	131
Floor	-	-	-	-	-	-	-	-	-
Canopy	-	-	-	-	-	-	-	-	-
GAS CYLINDER TEST	Cylinder Number		Manufacture Date		Charge Date	Weight of Cylinder Kg	Weight of CO² Kg	Weight of N² Kg	Total Weight Kg
Cylinder No.1	203753		-		-	-	3,500	0,240	12,70
Cylinder No.2	203488		-		-	-	3,500	0,240	12,73
DAVID LAUNCHABLE RAFT	Remarks	RES:A.761(18)		Remarks		DATE			
Load Test Date:	-	WP-TEST		YES		6/1/2026			
Suspension Straps/Patches	-	FS-TEST		-		-			
Shackle	-	NAP-TEST		-		-			
Steering Line With Patches	-	GI-TEST		-		-			
Bowsing Line With Patches	-	RAFT		Serial No.		A 0620164		Man of date : 07 - 2006	
Container Line Incl. Pocket	-			Type		RAFT - A - 20		Capacity : 20 Persons	
Pocket for Steering/Bowsing Lines	-			Merk		SHANGHAI STAR RUBBER			
"RAFT IN GOOD CONDOTION"									

Frequency of test

SERVICING INTERVALS	TEST METHODS
End of first year	Wp Test
End of second year	Wp Test
End of third year	Wp Test
End of fourth year	Wp Test
End of fifth year	GI Test
End of sixth year	Wp Test
End of seventh year	Wp Test
End of eighth year	Wp Test
End of ninth year	Wp Test
End of tenth year	GI Test + FS
Eleventh to fourteenth year	GI Test + FS
fifteenth year	NAP test + FS
Sixteenth to nineteenth year	GI test + NAP + FS
Twentieth year	NAP test + FS
Twenty-first to twenty-fourth year	GI test + NAP + FS
Twenty fifth year onwards	GI test + NAP + FS

Working Code :

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam

Mengetahui,

An. KEPALA KANTOR KSOP UTAMA TANJUNG PRIOK

KEPADA YAHYAN DAN KEPALAUTAN



Surveyor	: AGUS FERIYANSYAH
Next Inspection Date	: 05 JANUARI 2027

" SERVICE CHARGE LIFERAFT INSPECTED, TESTED AND RAFT IN GOOD CONDITION "



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Re-Inspection Certificate Fire Extinguishers

Cert.No : 003/MJAP/PMK/II/26

- Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 06 Januari 2026
• Name Of Ship : CB. PAN MARINE 12

No.	Type	Volume	Quantity	Working Code
1.	DRY POWDER	4.5 Kg	3 Cyls	1, 2, 3
2.	DRY POWDER	6,0 Kg	2 Cyls	1, 2, 3
3.	CO2 PORTABLE	6.8 Kg	3 Cyls	1, 2, 3
4.	FOAM AFF	9,0 Ltr	7 Cyls	1, 2, 3
5.	DRY POWDER	45,0 Kg	1 Cyls	1, 2, 3

THIS IS TO CERTIFY that

1. The above mentioned fire extinguisher has been inspected, repaired, and retested in compliance with following scope of work :

- | | |
|---------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Weight / Content | 5) Condemned |
| 3) Recharged | 6) New Supply |

2. On completion, the fire extinguishers is are Re-assemble back to Operation Condition (Sealed with Pins and Control Labels).

3. The condition of the above fire extinguishers has been found to satisfaction and in good condition

- Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA





PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

FIRE EXTINGUISHERS

SERVICE REPORT

In Accordance to IMO Resolution A. 951 (23)

Certificate No.: 003/MJAP/PMK/I/26

GENERAL PARTICULARS	
Name Of Ship : CB. PAN MARINE 12	Nationality/Port of Registry : INDONESIA
Owner : PT. PAN MARITIME WIRA PAWITRA	Call Sign : YDB4152
IMO-No : 9656113	MMSI No : 525010182
Class : -	Date of Service : 06 Januari 2026
Kind Of Service	
☒ Annual	☒ 5 Yearly
☒ Repair	
REMARKS :	
" Inspection, Repaint, Repair & Refilling "	

FIRE EXTINGUISHERS TYPE

☐ Water	☒ CO2	☐ Foam AB	☒ Dry Powder	☒ AFFF	☐ EEBD / ELSA
--------------------------------	---	----------------------------------	--	--	--------------------------------------

DESCRIPTION OF			
NO.	CHECKLIST ITEM	CHECK	REMARKS
Annual Inspection			
1	Checked for proper location, charging pressure, and Condition; according to the ship's fire plan	Y	GOOD CONDITION
2	Checking safety clip and indicating device	Y	GOOD CONDITION
3	Checking the pressure indicating device	Y	GOOD CONDITION
4	Visual Inspection for corrosion, dent, and damage	Y	GOOD CONDITION
5	Checking the weight	Y	GOOD CONDITION
6	Checking for the hose and nozzles	Y	GOOD CONDITION
7	Checking of operation instruction	Y	GOOD CONDITION
Inspection at recharge			
1	Checking the water and foam charge	Y	GOOD CONDITION
2	Checking for powder charge	Y	GOOD CONDITION
3	Checking for gas cartridge	Y	GOOD CONDITION
Inspection after discharge (5 and 10 year intervals)			
1	Checking air passages and operating mechanism	Y	GOOD CONDITION
2	Operating mechanism	Y	GOOD CONDITION
3	Gas cartridge	Y	GOOD CONDITION
4	O ring washers and hose diaphragms	Y	GOOD CONDITION
5	Checking powder body	Y	GOOD CONDITION
Inspection after recharge			
1	Water and foam	Y	GOOD CONDITION
2	Reassemble	Y	GOOD CONDITION
3	Maintenance label	Y	GOOD CONDITION
4	Mounting of extinguishers	Y	GOOD CONDITION
5	Report	Y	GOOD CONDITION

** Working Code : (Y = Yes) , (N = No) & (NA = Not Applicable) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Re-Inspection Certificate CO2 SYSTEM

Cert.No : 001/MJAP/CO2/II/26

• Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 06 Januari 2026
• Name Of Ship : CB. PAN MARINE 12

No.	Cylinder Serial No.	Last Hydro Test Date	Tare Weight (Kg)	Gross Weight (Kg)	Volume (Kg)	Type Of Cylinder	Working Code
1.	371062	02 - 2019	84.7	124.6	45	CO2	1.2
2.	371058	02 - 2019	86,0	127.2	45	CO2	1.2
3.	370187	02 - 2019	85.7	124.5	45	CO2	1.2
4.	371140	02 - 2019	86.5	127.1	45	CO2	1.2
5.	371002	02 - 2019	84.3	125.8	45	CO2	1.2
6.	371019	02 - 2019	86.2	127.6	45	CO2	1.2

THIS IS TO CERTIFY that

1. The above mentioned CO2 System has been inspected, refilled, and retested in compliance with following scope of work :

- | | |
|---------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Weight / Content | 5) Condemned |
| 3) Refilling | 6) New Supply |

2. On completion, the CO2 System is are Re-assemble back to Operation Condition and satisfaction in good condition.

• Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

**Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA**





PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax. (021) 440 8538 E-mail : megajayaabadi@ymail.com

CO2 SERVICE REPORT

In Accordance to IMO Resolution A. 951 (23)

Certificate No.: 001/MJAP/CO2/I/26

GENERAL PARTICULARS					
Name Of Ship : CB. PAN MARINE 12			Nationality/Port of Registry : INDONESIA		
Owner : PT. PAN MARITIME WIRA PAWITRA			Call Sign : YDB4152		
IMO-No : 9656113			MMSI No : 525016182		
Class : -			Date of Service : 06 Januari 2026		
DESCRIPTION OF					
Technical Description					
NO.	TEST	VALUE	VOLUME		
1	Manufacture				
2	Number of Cyls	6	Cyls		
3	Cylinder Capacity	45,0	Kg		
4	Number of Pilot Cyls	1	Cyls		
5	Pilot Cylinder Capacity	1,1	Kg		
6	Number of dist Lines	-	Line		
7	Covering	ENGINE ROOM			
Description of Inspection					
NO.	DESCRIPTION	CARRIED OUT	NOT CARRIED OUT	NOT APPL	COMM.
1	Release system and distance valve secured	X			
2	Contents in cylinders checked by manual weighting	X			
3	☒ Cylinder refilled only ☒ Refilled and hydrotest	X			
4	☒ All Cylinder Valve Visually Inspected ☒ Leak test		X		
5	All Cylinders frames and connections checked for tightness	X			
6	☒ Manifold distribution valve inspected ☒ Tested	X			
7	☒ Main valve distribution valves inspected ☒ Tested	X			
8	☒ Total flooding release system inspected ☒ Tested	X			
9	☒ Total flooding release system tested ☒ Tested	X			
10	Release stations inspected	X			
11	Alarm tested	X			
12	Fan stop tested	X			
13	Distribution lines and nozzles inspected	X			
14	Distribution lines and nozzles tested		X		
15	Distribution lines and nozzles blown through		X		
16	Smoke detention system tested according to service chart lines			X	
17	dansih REQ 5 years press test servo system (1,3 WP) distr lines holds (25 Bar) manifold (60 Bar)		X		
18	All doors hinges locks inspected	X			
19	All instructions plates on installation inspected	X			
20	System reconnected, sealed and left in operational order inspetion date labels	X			

** Working Code : (X = Yes) , (N = No) & (NA =Not Applicable) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@gmail.com

Re-Inspection Certificate *Emergency Escape Breathing Device*

Cert.No : 001/MJAP/EEBD/I/26

- Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 06 Januari 2026
• Name Of Ship : CB. PAN MARINE 12

No.	Cylinder Serial No.	Test Pressure	Working Pressure	Cylinder Capacity	Type Of Cylinder	Working Code
1.	400151	300 Bar	200 Bar	2,0 Ltr	AIR	1,2,3
2.	1106	300 Bar	200 Bar	2,0 Ltr	AIR	1,2,3

THIS IS TO CERTIFY that

1. The above mentioned Emergency Escape Breathing Device (EEBD) has been inspected, refilled, and retested in compliance with following scope of work :

- | | |
|-----------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Pressure / Content | 5) Condemned |
| 3) Refilling | 6) New Supply |

2. On completion, the Emergency Escape Breathing Device (EEBD) is are Re-assemble back to Operation Condition (Sealed with Pins and Control Labels) and satisfaction in good condition.

- Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Re-Inspection Certificate *Breathing Apparatus*

Cert.No : 001/MJAP/BA/II/26

- Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 06 Januari 2026
• Name Of Ship : CB. PAN MARINE 12

No.	Cylinder Serial No.	Test Pressure	Working Pressure	Cylinder Capacity	Type Of Cylinder	Working Code
1.	002856	300 Bar	200 Bar	4,0 Ltr	AIR	1,2,3
2.	34306	300 Bar	200 Bar	4,0 Ltr	AIR	1,2,3
3	001167	300 Bar	200 Bar	4,0 Ltr	AIR	1,2,3

THIS IS TO CERTIFY that

1. The above mentioned Breathing Apparatus has been inspected, refilled, and retested in compliance with following scope of work :

- | | |
|-----------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Pressure / Content | 5) Condemned |
| 3) Refilling | 6) New Supply |

2. On completion, the Breathing Apparatus is are Re-assemble back to Operation Condition (Sealed with Pins and Control Labels) and satisfaction in good condition.

- Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Re-Inspection Certificate *Medical Oxygen Device*

Cert.No : 001/MJAP/MO/II/26

- Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 06 Januari 2026
• Name Of Ship : CB. PAN MARINE 12

No.	Cylinder Serial No.	Test Pressure	Working Pressure	Cylinder Capacity	Type Of Cylinder	Working Code
1.	005121	300 Bar	200 Bar	4,0 Ltr	AIR	1,2,3

THIS IS TO CERTIFY that

1. The above mentioned Medical Oxygen Device (MO) has been inspected, refilled,
and retested in compliance with following scope of work :

- | | |
|-----------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Pressure / Content | 5) Condemned |
| 3) Refilling | 6) New Supply |

2. On completion, the Medical Oxygen Device (MO) is are Re-assemble back to
Operation Condition (Sealed with Pins and Control Labels) and satisfaction in good condition.

- Date Of next inspection : 05 Januari 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Certificate

No : 005 / MJAP / HRU / I / 26

Name of Ship
NamaKapal

: CB. PAN MARINE 12

Owner / Address
Pemilik / Alamat

: PT. PAN MARITIME WIRA PAWITRA

Hydrostatic Release Serial Nomor
Serial Number Hydrostatic

: 94056 2406 206

Type
Model

: H20R

Manufacturer
Buatan

: HAMMAR

Remarks
Catatan

: HYDROSTATIC RELEASE UNIT IN GOOD CONDITION

ExpiredDate
Batas Penggunaan

: JAN - 2027

ORIGINAL

For and on behalf of



FERIYANSYAH

Approved signatory for Chief Inspector
at PT. MEGA JAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Certificate

No : 006 / MJAP / HRU / I / 26

Name of Ship
NamaKapal

: CB. PAN MARINE 12

Owner / Address
Pemilik / Alamat

: PT. PAN MARITIME WIRA PAWITRA

Hydrostatic Release Serial Nomor
Serial Number Hydrostatic

: 94040 2409 206

Type
Model

: H20R

Manufacturer
Buatan

: HAMMAR

Remarks
Catatan

: HYDROSTATIC RELEASE UNIT IN GOOD CONDITION

ExpiredDate
Batas Penggunaan

: JAN - 2027

ORIGINAL

For and on behalf of



FERIYANSYAH

Approved signatory for Chief Inspector
at PT. MEGA JAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@gmail.com

Certificate

No : 007 / MJAP / HRU / I / 26

Name of Ship
NamaKapal

: CB. PAN MARINE 12

Owner / Address
Pemilik / Alamat

: PT. PAN MARITIME WIRA PAWITRA

Hydrostatic Release Serial Nomor
Serial Number Hydrostatic

: 94041 2409 206

Type
Model

: H20R

Manufacturer
Buatan

: HAMMAR

Remarks
Catatan

: HYDROSTATIC RELEASE UNIT IN GOOD CONDITION

ExpiredDate
Batas Penggunaan

: JAN - 2027

ORIGINAL

For and on behalf of



FERIYANSYAH

Approved signatory for Chief Inspector
at PT. MEGA JAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Certificate

No : 008 / MJAP / HRU / I / 26

Name of Ship
NamaKapal

: CB. PAN MARINE 12

Owner / Address
Pemilik / Alamat

: PT. PAN MARITIME WIRA PAWITRA

Hydrostatic Release Serial Nomor
Serial Number Hydrostatic

: 94055 2406 206

Type
Model

: H20R

Manufacturer
Buatan

: HAMMAR

Remarks
Catatan

: HYDROSTATIC RELEASE UNIT IN GOOD CONDITION

ExpiredDate
Batas Penggunaan

: JAN - 2027

ORIGINAL

For and on behalf of



FERIYANSYAH

Approved signatory for Chief Inspector
at PT. MEGA JAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@gmail.com

Certificate

No : 009 / MJAP / HRU / I / 26

Name of Ship
NamaKapal

: CB. PAN MARINE 12

Owner / Address
Pemilik / Alamat

: PT. PAN MARITIME WIRA PAWITRA

Hydrostatic Release Serial Nomor
Serial Number Hydrostatic

: 94070 2406 206

Type
Model

: H20R

Manufacturer
Buatan

: HAMMAR

Remarks
Catatan

: HYDROSTATIC RELEASE UNIT IN GOOD CONDITION

ExpiredDate
Batas Penggunaan

: JAN - 2027

ORIGINAL

For and on behalf of



FERIYANSYAH

Approved signatory for Chief Inspector
at PT. MEGA JAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

**GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER**

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara
Telp. (021) 440 8538 Fax. (021) 440 8538
E-mail : megajayaabadi@ymail.com

Certificate

No : 010 / MJAP / HRU / I / 26

Name of Ship
NamaKapal

: CB. PAN MARINE 12

Owner / Address
Pemilik / Alamat

: PT. PAN MARITIME WIRA PAWITRA

Hydrostatic Release Serial Nomor
Serial Number Hydrostatic

: 94074 2406 206

Type
Model

: H20R

Manufacturer
Buatan

: HAMMAR

Remarks
Catatan

: HYDROSTATIC RELEASE UNIT IN GOOD CONDITION

ExpiredDate
Batas Penggunaan

: JAN - 2027

ORIGINAL

For and on behalf of



FERIYANSYAH

Approved signatory for Chief Inspector
at PT. MEGA JAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Certificate

No : 011 / MJAP / HRU / I / 26

Name of Ship
NamaKapal

: CB. PAN MARINE 12

Owner / Address
Pemilik / Alamat

: PT. PAN MARITIME WIRA PAWITRA

Hydrostatic Release Serial Nomor
Serial Number Hydrostatic

: 94057 2406 206

Type
Model

: H20R

Manufacturer
Buatan

: HAMMAR

Remarks
Catatan

: HYDROSTATIC RELEASE UNIT IN GOOD CONDITION

ExpiredDate
Batas Penggunaan

: JAN - 2027

ORIGINAL

For and on behalf of



FERIYANSYAH

Approved signatory for Chief Inspector
at PT. MEGA JAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

**GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER**

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Certificate

No : 012 / MJAP / HRU / I / 26

Name of Ship
NamaKapal

: CB. PAN MARINE 12

Owner / Address
Pemilik / Alamat

: PT. PAN MARITIME WIRA PAWITRA

Hydrostatic Release Serial Nomor
Serial Number Hydrostatic

: 94054 2406 206

Type
Model

: H20R

Manufacturer
Buatan

: HAMMAR

Remarks
Catatan

: HYDROSTATIC RELEASE UNIT IN GOOD CONDITION

ExpiredDate
Batas Penggunaan

: JAN - 2027

ORIGINAL

For and on behalf of



FERIYANSYAH

Approved signatory for Chief Inspector
at PT. MEGA JAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara
Telp. (021) 440 8538 Fax. (021) 440 8538
E-mail : megajayaabadi@ymail.com

Certificate

No : 013 / MJAP / HRU / I / 26

Name of Ship
NamaKapal

: CB. PAN MARINE 12

Owner / Address
Pemilik / Alamat

: PT. PAN MARITIME WIRA PAWITRA

Hydrostatic Release Serial Nomor
Serial Number Hydrostatic

: 94071 2406 206

Type
Model

: H20R

Manufacturer
Buatan

: HAMMAR

Remarks
Catatan

: HYDROSTATIC RELEASE UNIT IN GOOD CONDITION

ExpiredDate
Batas Penggunaan

: JAN - 2027

ORIGINAL

For and on behalf of



FERIYANSYAH

Approved signatory for Chief Inspector
at PT. MEGA JAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@gmail.com

Certificate

No : 014 / MJAP / HRU / I / 26

Name of Ship
NamaKapal

: CB. PAN MARINE 12

Owner / Address
Pemilik / Alamat

: PT. PAN MARITIME WIRA PAWITRA

Hydrostatic Release Serial Nomor
Serial Number Hydrostatic

: 573604 809 333

Type
Model

: H20R

Manufacturer
Buatan

: HAMMAR

Remarks
Catatan

: HYDROSTATIC RELEASE UNIT IN GOOD CONDITION

ExpiredDate
Batas Penggunaan

: JAN - 2027

ORIGINAL

For and on behalf of



FERIYANSYAH

Approved signatory for Chief Inspector
at PT. MEGA JAYA ABADI PERKASA