



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@gmail.com

Re-Inspection Certificate Fire Extinguishers

Cert.No : 038/MJAP/PMK/VIII/23

- Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 28 Agustus 2023
• Name Of Ship : CB. PAN MARINE 8

No.	Type	Volume	Quantity	Working Code
1.	DRY POWDER	3,0 Kg	1 Cyls	1, 2, 3
2.	DRY POWDER	6,0 Kg	8 Cyls	1, 2, 3
3.	DRY POWDER	9,0 Kg	1 Cyls	1, 2, 3
4.	CO2 PORTABLE	5,0 Kg	4 Cyls	1, 2, 3
5.	FOAM AFFF	9,0 Ltr	5 Cyls	1, 2, 3
6.	FOAM AFFF	45,0 Ltr	1 Cyls	1, 2, 3

THIS IS TO CERTIFY that

1. The above mentioned fire extinguisher has been inspected, repaired, and retested in compliance with following scope of work :

- | | |
|---------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Weight / Content | 5) Condemned |
| 3) Recharged | 6) New Supply |

2. On completion, the fire extinguishers is are Re-assemble back to Operation Condition (Sealed with Pins and Control Labels).

3. The condition of the above fire extinguishers has been found to satisfaction and in good condition

- Date Of next inspection : 27 Agustus 2024



For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No. 11 Semper Timur - Jakarta Utara Telp. (021) 440 8538

Fax: (021) 440 8538 E-mail: megajayaabadi@gmail.com

FIRE EXTINGUISHERS

SERVICE REPORT

In Accordance to IMO Resolution A. 951 (23)

Certificate No.: 038/MJAP/PMK/VIII/23

GENERAL PARTICULARS			
Name Of Ship	CB. PAN MARINE 8	Nationality/Port of Registry	INDONESIA
Owner	PT. PAN MARITIME WIRA PAWITRA	Call Sign	YDA4696
IMO-No	9483592	MMSI No	525016204
Class		Date of Service	28 AGUSTUS 2023
Kind Of Service			
☒ Annual ☒ 5 Yearly ☒ Repair			
REMARKS :			
" Inspection, Repaint, Repair & Refilling "			

FIRE EXTINGUISHERS TYPE

☐ Water	☒ CO2	☐ Foam AB	☒ Dry Powder	☒ AFFF	☐ EEBD / ELSA
--------------------------------	---	----------------------------------	--	--	--------------------------------------

DESCRIPTION OF			
NO.	CHECKLIST ITEM	CHECK	REMARKS
Annual Inspection			
1	Checked for proper location, charging pressure, and Condition; according to the ship's fire plan	Y	GOOD CONDITION
2	Checking safety clip and indicating device	Y	GOOD CONDITION
3	Checking the pressure indicating device	Y	GOOD CONDITION
4	Visual Inspection for corrosion, dent, and damage	Y	GOOD CONDITION
5	Checking the weight	Y	GOOD CONDITION
6	Checking for the hose and nozzles	Y	GOOD CONDITION
7	Checking of operation instruction	Y	GOOD CONDITION
Inspection at recharge			
1	Checking the water and foam charge	Y	GOOD CONDITION
2	Checking for powder charge	Y	GOOD CONDITION
3	Checking for gas cartridge	Y	GOOD CONDITION
Inspection after discharge (5 and 10 year intervals)			
1	Checking air passages and operating mechanism	Y	GOOD CONDITION
2	Operating mechanism	Y	GOOD CONDITION
3	Gas cartridge	Y	GOOD CONDITION
4	O ring washers and hose diaphragms	Y	GOOD CONDITION
5	Checking powder body	Y	GOOD CONDITION
Inspection after recharge			
1	Water and foam	Y	GOOD CONDITION
2	Reassemble	Y	GOOD CONDITION
3	Maintenance label	Y	GOOD CONDITION
4	Mounting of extinguishers	Y	GOOD CONDITION
5	Report	Y	GOOD CONDITION

** Working Code : (Y = Yes) , (N = No) & (NA = Not Applicable) **



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara
Telp. (021) 440 8538 Fax. (021) 440 8538
E-mail : megajayaabadi@gmail.com

Re-Inspection Certificate CO2 SYSTEM

Cert.No : 007/MJAP/CO2/VIII/23

• Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 28 Agustus 2023
• Name Of Ship : CB. PAN MARINE 8

No.	Cylinder Serial No.	Last Hydro Test Date	Tare Weight (Kg)	Gross Weight (Kg)	Volume (Kg)	Type Of Cylinder	Working Code
1.	D7209058	08-2019	78,1	123,1	45,0	CO2	1, 2
2.	D7209061	08-2019	75,9	120,9	45,0	CO2	1, 2
3.	D7209075	08-2019	77,6	122,6	45,0	CO2	1, 2
4.	D7210004	08-2019	78,2	123,2	45,0	CO2	1, 2
5.	D7210054	08-2019	78,3	123,3	45,0	CO2	1, 2
6.	D7214191	08-2019	78,9	123,9	45,0	CO2	1, 2
7.	D7214190	08-2019	77,9	122,9	45,0	CO2	1, 2
8.	D7214194	08-2019	77,9	122,9	45,0	CO2	1, 2
9.	D7048049	-	2,67	3,67	1,0	PILOT	1, 2
10.	UN1013	-	2,67	3,67	1,0	PILOT	1, 2

THIS IS TO CERTIFY that

1. The above mentioned CO2 System has been inspected, refilled, and retested in compliance with following scope of work :

- | | |
|---------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Weight / Content | 5) Condemned |
| 3) Refilling | 6) New Supply |

2. On completion, the CO2 System is are Re-assemble back to Operation Condition and satisfaction in good condition.

• Date Of next inspection : 27 Agustus 2024



For and on behalf of



FERIYANSYAH
Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara
Telp. (021) 440 8538 Fax. (021) 440 8538
E-mail : megajayaabadi@ymail.com

Re-Inspection Certificate Breathing Apparatus

Cert.No : 011/MJAP/SCBA/VIII/23

- Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 28 Agustus 2023
• Name Of Ship : CB. PAN MARINE 8

No.	Cylinder Serial No.	Test Pressure	Working Pressure	Cylinder Capacity	Type Of Cylinder	Working Code
1.	1451	300 Bar	200 Bar	4,0 Ltr	AIR	1, 2, 3
2.	0028	300 Bar	200 Bar	4,0 Ltr	AIR	1, 2, 3
3.	1831	300 Bar	200 Bar	4,0 Ltr	AIR	1, 2, 3
4.	1604	300 Bar	200 Bar	4,0 Ltr	AIR	1, 2, 3
5.	19350	300 Bar	200 Bar	4,0 Ltr	AIR	1, 2, 3

THIS IS TO CERTIFY that

1. The above mentioned Emergency Escape Breathing Device (EEBD) has been inspected, refilled, and retested in compliance with following scope of work :

- | | |
|-----------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Pressure / Content | 5) Condemned |
| 3) Refilling | 6) New Supply |

2. On completion, the Emergency Escape Breathing Device (EEBD) is are Re-assemble back to Operation Condition (Sealed with Pins and Control Labels) and satisfaction in good condition.

- Date Of next inspection : 27 Agustus 2024

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara
Telp. (021) 440 8538 Fax. (021) 440 8538
E-mail : megajayaabadi@ymail.com

Re-Inspection Certificate Emergency Escape Breathing Device

Cert.No : 009/MJAP/EEBD/VIII/23

- Customer : PT. PAN MARITIME WIRA PAWITRA
- Date : 28 Agustus 2023
- Name Of Ship : CB. PAN MARINE 8

No.	Cylinder Serial No.	Test Pressure	Working Pressure	Cylinder Capacity	Type Of Cylinder	Working Code
1.	7921	300 Bar	200 Bar	2,0 Ltr	AIR	1, 2, 3
2.	7364	300 Bar	200 Bar	2,0 Ltr	AIR	1, 2, 3
3.	SHC 095	300 Bar	200 Bar	2,0 Ltr	AIR	1, 2, 3
4.	SHC 006	300 Bar	200 Bar	2,0 Ltr	AIR	1, 2, 3

THIS IS TO CERTIFY that

1. The above mentioned Emergency Escape Breathing Device (EEBD) has been inspected, refilled, and retested in compliance with following scope of work :

- | | |
|-----------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Pressure / Content | 5) Condemned |
| 3) Refilling | 6) New Supply |

2. On completion, the Emergency Escape Breathing Device (EEBD) is are Re-assemble back to Operation Condition (Sealed with Pins and Control Labels) and satisfaction in good condition.

- Date Of next inspection : 27 Juli 2024
- Date Of next inspection : 27 Agustus 2024

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara
Telp. (021) 440 8538 Fax. (021) 440 8538
E-mail : megajayaabadi@gmail.com

Re-Inspection Certificate Medical Oxygen Device

Cert.No : 006/MJAP/MO/VIII/23

- Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 28 Agustus 2023
• Name Of Ship : CB. PAN MARINE 8

No.	Cylinder Serial No.	Test Pressure	Working Pressure	Cylinder Capacity	Type Of Cylinder	Working Code
1.	228817	350 Bar	300 Bar	6,0 Ltr	AIR	1,2,3
2.	228873	350 Bar	300 Bar	6,0 Ltr	AIR	1,2,3

THIS IS TO CERTIFY that

1. The above mentioned Medical Oxygen Device (MO) has been inspected, refilled,
and retested in compliance with following scope of work :

- | | |
|-----------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Pressure / Content | 5) Condemned |
| 3) Refilling | 6) New Supply |

2. On completion, the Medical Oxygen Device (MO) is are Re-assemble back to
Operation Condition (Sealed with Pins and Control Labels) and satisfaction in good condition.

- Date Of next inspection : 30 Agustus 2024

For and on behalf of



FERİYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA