



CV. ROSE MARINE

Re-Inspection inflatable Liferaft, fire Extinguisher, Epird, Saer And General Supplier

JL. IKAN DUYUNG No. 10 Surabaya Telp : 08101552584, 081331221531

E-mail : sby.ahmad@yahoo.co.id
cv.rosemarine.admn@gmail.com

Re - inspection Certificate

INFLATABLE LIFERAFT

No : 176/ILR-RM/XI/2025

Nama Kapal : CB. PAN MARINE 11

Name Of Ship

Tanggal : NOVEMBER 3rd, 2025

Date

Pemilik dan Alamat : PT. PAN MARITIME WIRA PAWITRA

Owner And Address Indonesia

Merk : CSM

Mark

Tipe : RAFT-A20

Type

No Seri : A0620172

Serial No

Tahun pembuatan : JULY 2006

Date Of Manufacture

Dengan Perubahan : FIRST AID KIT, ANTI SEASICKNESS, SPARE BATTERY.

With Modification

Orang (Jumlah) : 20 PERSONS

Number Of Persons

Botol Co2 Nomor : 211674

Co2 Bottle Number 211605

Berat Co2 : 3,600

Weight Co2 3,600

Kgs N2 : 0,250

Kgs N2 0,250

Kgs

Kgs

Berat Total : 14,000

Total Weight 14,100

Kgs

Kgs

Catatan :

Remarks

RAFT IN GOOD CONDITION

Dengan ini menyatakan bahwa Inflatable Liferaft atau Rakit Penolong tersebut diatas telah diperiksa dan dites sesuai dengan standard Pabrik dan telah memenuhi persyaratan International S.O.L.A.S "74" (Safety of at Sea '1974') dengan Amandements S.O.L.A.S "83" serta sesuai dengan IMO A 761 (18), dan sesuai dengan keterangan diatas.

This is to Certify that the above named Liferaft has been Inspected, serviced and tested in according to the Requirement of the manufacture, and complying fully to the International Safety of at Sea "1974" conforms to S.O.L.A.S '83' Amandements resolution : A 761 (18), and the Log Card filled in Accordance it this.

Pemeriksaan Berikutnya : NOVEMBER 3rd 2026

The Next Inspection



CV. ROSE MARINE

(SUWONDO)
SURVEYOR



CV. ROSE MARINE

Re-Inspection Inflatable Liferaft, Fire Extinguisher, Epirb, SART and General Supply

Jl. Ikan Duyung No. 10 Surabaya Tlp. 081331221531

E-mail : shy.ahmad@yahoo.co.id, cv.rosemarine.admn@gmail.com



LIFERAFT SERVICE REPORT

in Accordance to IMO Resolution MSC.388(94) Amendment to Resolution A.761(18)

Certificate No : 176/ILR-RM/XI/2025

GENERAL PARTICULARS	
Name of Ship : CB. PAN MARINE - 11	Nationality / Port of Registry : SUMENEP
IMO-No : 9441817	Call Sign : YB4613
Class : N/A	MMSI No : 525016178
Gross Tonnage : 161	Date of Service : NOVEMBER 3rd, 2025
Kind of Service ☒ Annual ☐ 5 Yearly ☐ Repair	
Remarks: Renew Spare Battery, First Aid Kit, Anti Seasickness.	

Liferaft Mark : CSM	Type of Liferaft : RAFT-A20
Serial Number : A0620172	Capacity : 20 PERSONS
MFG Date : JULY 2006	Customer : PT. PAN MARITIME WIRA PAWITRA

CHECKLIST ITEM	OK/RN/NA	CHECKLIST ITEM	OK/RN/NA	CHECKLIST ITEM	OK/RN/NA
* CONTAINER SHELL		"T/V" Place Connector	-	Leak Stoppers	OK
Labels/Markings	RN	Protection Pads	OK	Sponges	OK
Handling Beackets	OK	CO2 Cylinder (s)	OK	Bailers	OK
* Gasket/Strap/Packing List	OK	Operating Cable & Conduit	OK	Spare Sea Anchor	OK
Painter Line	OK	Operating Head	OK	Torch, Signaling	OK
ID Container	RN			Spare Batteries (4)	RN
* Valise Fabric/ Plastic	RN	* SURVEY OF INTERIOR	OK	Whistle	OK
Eyelets	OK	Buoyancies Fabric	OK	Fishing Kit	OK
Painter Line Pockets	OK	Safety Relief Valves	OK	Can Opener (s)	OK
Bursting Band	RN	Grabline & Patches/Loops	OK	Paddles	OK
Strapping	OK	Towart, Fabric	OK	Spare Bulb for Torch	OK
		Deflation Plugs/Valves	OK	Drinking Vessel	OK
* SURVEY OF EXTERIOR	OK	Arches Fabric	OK	Seasickness Bags	OK
Buoyancies Fabric	OK	Center Column Fabric	OK	Signal Mirror	OK
Inlet Valves	OK	Light Battery	OK	Manual Survival Book	OK
Deflation Plug / Valves	OK	Interior Lighting System	OK	Rescue Signal Table	OK
Safety Relief Valve	OK	Topping Up Valves	OK	Thermal Protective Aids	OK
Boarding Ramp	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Boarding Ladders	OK	Rainwater Catchment	OK	Dye Marker	-
Towing Bridle/Patch	OK	Blowing Port (s)	OK		
Lifeline and Patches	OK	Aerial Sleeve	OK		
Outer Canopy Fabric	OK	Inner Floor Fabric	OK		
Retro Reflective Tape	OK	Topping Up Valves	-		
Seam and Taping	OK	Deflation Up Valves	-		
Rain Water Catchment	OK	Emergency Pack Loops/Patch	OK		
Exterior Lighting Systems	OK	Aerial Sockets/Tie-Tapes	OK		
Arch Deflation Valve	-	Floor Reeds	-		
Entrance Sleeves	OK	Rescue Line and Quoit	OK		
Outer Floor, Fabric	OK	Knife Sheath	OK		
Righting Strap	OK	Sea Anchor	OK		
Stabilizing Packs	-				
Cylinder Pockets (s)	-	* ACCESSORY BAG	OK		
Sea-Cell	11/2026	Bellows of Pump	OK		
Painter Lashing/Stowage	OK	Light Stick	OK		
(DKF) Load Test Davit Launch and Raft	-	Glue for Repair Kit	OK		
Installation Valve, Hose	OK	Repair Kit	OK		
RN-Renew, NA-Not Applicable					

RAFT AND CYLINDER TEST									
PRESSURE TEST	Time	Start		Finish		Pressure Drops (mmHg)	Safety Valves		Total W. Kg
		Temp. (°C)	Pressure (mmHg)	Time	Temp. (°C)		Pressure (mmHg)	Blow off (mmHg)	
Upper Bouyancy	11.00	30°	110	12.00	30°	108	3	100	98
Lower Bouyancy	11.00	30°	108	12.00	30°	106	2.	100	98
Floor	11.00	30°	110	12.00	30°	108	-	100	98
Canopy	11.00	30°	110	12.00	30°	108	-	100	98
GAS CYLINDER TEST		Cyl No	Mfg. Date	Change Date	Weight of Cyl. Kg	Weight of Co2. Kg	Weight of N2. Kg		
Cylinder No. 1		211674				3,600	0,250	14,000	
Cylinder No. 2		211605				3,600	0,250	14,100	
DAVIT LAUNCHING RAFT		REMARKS	RES: A. 761 (18)	REMARKS	DATE				
Load Test Date :			WP - TEST						
Suspension Straps / Patches			FS - TEST						
Shackle			NAP - TEST	√ PASS	November, 3rd 2025				
Steering Line with Patches			GI - TEST	√ PASS	November, 3rd 2025				
Bowling Line with Patches				√ PASS	November, 3rd 2021				
Container Line Incl. Pocket									
Pocket for Steering / Bowling Lines									
REMARKS:									
RAFT IN GOOD CONDITION									

Servicing Intervals	Test Methods
End of first year	WP test
End of second year	WP test
End of third year	WP test
End of fourth year	WP test
End of fifth year	GI test
End of sixth year	WP test
End of seventh year	WP test
End of eighth year	WP test
End of ninth year	WP test
End of tenth year	GI test + FS
Eleventh to fourteenth year	NAP test + FS
Fifteenth year	GI test + NAP + FS
Sixteenth to nineteenth year	NAP test + FS
Twentieth year	GI test + NAP + FS
Twenty-first to twenty-fourth year	NAP test + FS
Twenty-fifth year onwards	GI test + NAP + FS

Keterangan :

- NA - Necessary Additional Pressure Test
- WP - Working Pressure (compressed air)
- GI - Gas Inflation (fired gas)
- FS - Floor Seam



Surveyor : SUWONDO
Date Next of Inspection : NOVEMBER 3rd, 2026



CV. ROSE MARINE

Re-Inspection inflatable Liferaft, fire Extinguisher, Epird, Saer And General Supplier

JL. IKAN DUYUNG No. 10 Surabaya Telp : 08101552584, 081331221531

E-mail : sby.ahmad@yahoo.co.id
cv.rosemarine.admn@gmail.com

Re - inspection Certificate

INFLATABLE LIFERAFT

No : 178/ILR-RM/XI/2025

Nama Kapal : CB. PAN MARINE 11

Name Of Ship

Tanggal : NOVEMBER 3rd, 2025

Date

Pemilik dan Alamat : PT. PAN MARITIME WIRA PAWITRA

Owner And Address Indonesia

Merk : SHANGHAI YOULONG

Mark

Tipe : KHZ-50

Type

No Seri : 0024

Serial No

Tahun pembuatan : DECEMBER 2006

Date Of Manufacture

Dengan Perubahan : FIRST AID KIT, ANTI SEASICKNESS, SPARE BATTERY.

With Modification

Orang (Jumlah) : 50 PERSONS

Number Of Persons

Botol Co2 Nomor : 178818

Co2 Bottle Number 216236

Berat Co2 : 12,500 Kgs

Weight Co2 12,500 Kgs

N2 : 1,250 Kgs

N2 1,250 Kgs

Kgs

Kgs

Berat Total : 51,400 Kgs

Total Weight 51,300 Kgs

Catatan :

Remarks

RAFT IN GOOD CONDITION

Dengan ini menyatakan bahwa Inflatable Liferaft atau Rakit Penolong tersebut diatas telah diperiksa dan dites sesuai dengan standard Pabrik dan telah memenuhi persyaratan International S.O.L.A.S "74" (Safety of at Sea '1974') dengan Amandements S.O.L.A.S "83" serta sesuai dengan IMO A 761 (18), dan sesuai dengan keterangan diatas.

This is to Certify that the above named Liferaft has been Inspected, serviced and tested in according to the Requirement of the manufacture, and complying fully to the International Safety of at Sea "1974" conforms to S.O.L.A.S '83' Amandements resolution : A 761 (18), and the Log Card filled in Accordance it this.

Pemeriksaan Berikutnya : NOVEMBER 3rd 2026

The Next Inspection

Mengetahui



CV. ROSE MARINE

(SUWONDO)
SURVEYOR



CV. ROSE MARINE

Re-Inspection Inflatable Lifteraft, Fire Extinguisher, Epirb, SART and General Supply

Jl. Ikan Duyung No. 10 Surabaya Tlp. 081331221531
E-mail : sby.ahmad@yahoo.co.id, cv.rosemarine.admn@gmail.com



LIFERAFT SERVICE REPORT

In Accordance to IMO Resolution MSC.388(94) Amendment to Resolution A.761(18)

Certificate No : 178/ILR-RM/XI/2025

GENERAL PARTICULARS	
Name of Ship : CB. PAN MARINE - 11	Nationality / Port of Registry : SUMENEP
IMO-No : 9441817	Call Sign : YB4613
Class : N/A	MMSI No : 525016178
Gross Tonnage : 161	Date of Service : NOVEMBER 3rd, 2025
Kind of Service : ☒ Annual ☐ 5 Yearly ☐ Repair	
Remarks: Renew Spare Battery, First Aid Kit, Anti Seasickness.	

Liferaft Mark : SHANGHAI YOUNG	Type of Liferaft : KHZ-50
Serial Number : 0024	Capacity : 50 PERSONS
MFG Date : DECEMBER 2006	Customer : PT. PAN MARITIME WIRA PAWITRA

CHECKLIST ITEM	OK/RN/NA	CHECKLIST ITEM	OK/RN/NA	CHECKLIST ITEM	OK/RN/NA
* CONTAINER SHELL		"T/V" Place Connector	-	Leak Stoppers	OK
Labels/Markings	RN	Protection Pads	OK	Sponges	OK
Handling Beackets	OK	CO2 Cylinder (s)	OK	Bailers	OK
* Gasket/Strap/Packing List	OK	Operating Cable & Conduit	OK	Spare Sea Anchor	OK
Painter Line	OK	Operating Head	OK	Torch, Signaling	OK
ID Container	RN			Spare Batteries (4)	RN
* Valise Fabric/ Plastic	RN	* SURVEY OF INTERIOR	OK	Whistle	OK
Eyelets	OK	Buoyancies Fabric	OK	Fishing Kit	OK
Painter Line Pockets	OK	Safety Relief Valves	OK	Can Opener (s)	OK
Bursting Band	RN	Grabline & Patches/Loops	OK	Paddles	OK
Strapping	OK	Towart, Fabric	OK	Spare Bulb for Torch	OK
		Deflation Plugs/Valves	OK	Drinking Vessel	OK
* SURVEY OF EXTERIOR	OK	Arches Fabric	OK	Seasickness Bags	OK
Buoyancies Fabric	OK	Center Column Fabric	OK	Signal Mirror	OK
Inlet Valves	OK	Light Battery	OK	Manual Survival Book	OK
Deflation Plug / Valves	OK	Interior Lighting System	OK	Rescue Signal Table	OK
Safety Relief Valve	OK	Topping Up Valves	OK	Thermal Protective Aids	OK
Boarding Ramp	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Boarding Ladders	OK	Rainwater Catchment	OK	Dye Marker	-
Towing Bridle/Patch	OK	Blowing Port (s)	OK		
Lifeline and Patches	OK	Aerial Sleeve	OK		
Outer Canopy Fabric	OK	Inner Floor Fabric	OK		
Retro Reflective Tape	OK	Topping Up Valves	-		
Seam and Taping	OK	Deflation Up Valves	-		
Rain Water Catchment	OK	Emergency Pack Loops/Patch	OK		
Exterior Lighting Systems	OK	Aerial Sockets/Tie-Tapes	OK		
Arch Deflation Valve	-	Floor Reeds	-		
Entrance Sleeves	OK	Rescue Line and Quoit	OK		
Outer Floor, Fabric	OK	Knife Sheath	OK		
Righting Strap	OK	Sea Anchor	OK		
Stabilizing Packs	-				
Cylinder Pockets (s)	-	* ACCESSORY BAG	OK		
Sea-Cell	11/2026	Bellows of Pump	OK		
Painter Lashing/Stowage	OK	Light Stick	OK		
(DKF) Load Test Davit Launch and Rafi	-	Glue for Repair Kit	OK		
Installation Valve, Hose	OK	Repair Kit	OK		

RN-Renew, NA-Not Applicable

RAFT AND CYLINDER TEST									
PRESSURE TEST	Start			Finish			Pressure Drops (mmHg)	Safety Valves	
	Time	Temp. (°C)	Pressure (mmHg)	Time	Temp. (°C)	Pressure (mmHg)		Blow off (mmHg)	Rescat (mmHg)
Upper Bouyancy	11.00	30°	110	12.00	30°	108	3	100	98
Lower Bouyancy	11.00	30°	108	12.00	30°	106	2	100	98
Floor	11.00	30°	110	12.00	30°	108	-	100	98
Canopy	11.00	30°	110	12.00	30°	108	-	100	98
GAS CYLINDER TEST		Cyl No	Mfg. Date		Change Date	Weight of Cyl. Kg	Weight of Co2. Kg	Weight of N2. Kg	Total W. Kg
Cylinder No. 1		178818					12,500	1,250	51,400
Cylinder No. 2		216236					12,500	1,250	51,300
DAVIT LAUNCHING RAFT		REMARKS	RES: A. 761 (18)		REMARKS		DATE		
Load Test Date :			WP - TEST						
Suspension Straps / Patches			FS - TEST		✓ PASS		November, 3rd 2025		
Shackle			NAP - TEST		✓ PASS		November, 3rd 2025		
Steering Line with Patches			GI - TEST		✓ PASS		November, 3rd 2021		
Bowsing Line with Patches									
Container Line Ind. Pocket									
Pocket for Steering / Bowsing Lines									
REMARKS:									
RAFT IN GOOD CONDITION									

Frequency of test	
Servicing Intervals	Test Methods
End of first year	WP test
End of second year	WP test
End of third year	WP test
End of fourth year	WP test
End of fifth year	GI test
End of sixth year	WP test
End of seventh year	WP test
End of eighth year	WP test
End of ninth year	WP test
End of tenth year	GI test + FS
Eleventh to fourteenth year	NAP test + FS
Fifteenth year	GI test + NAP + FS
Sixteenth to nineteenth year	NAP test + FS
Twentieth year	GI test + NAP + FS
Twenty-first to twenty-fourth year	NAP test + FS
Twenty fifth year onwards	GI test + NAP + FS

Keterangan :
- NA - Necessary Additional Pressure Test
- WP - Working Pressure (compressed air)
- GI - Gas Inflation (fitted gas)
- FS - Floor Seam



Surveyor :
SUWONDO

Date Next of Inspection :
NOVEMBER 3rd, 2026



CV.ROSE MARINE

Re-Inspection Inflatable Liferaft, Fire Extinguisher, Epirb, SART and General Supply
Jl. Ikan Duyung No. 10 Surabaya Tlp. 081331221531
E-mail : sly.ahmad@yahoo.co.id, cv.rosemarine.admn@gmail.com



Re-inspection Certificate

FIRE EXTINGUISHER

No : 357/FE-RM/XI/2025

Nama Kapal : CB. PAN MARINE 11
Name of Ship
Pemilik dan Alamat : PT. PAN MARITIME WIRA PAWITRA
Owner And addres Indonesia
Port of Service : SURABAYA

TYPE OF SERVICE PERFORMED

Co2 SYSTEM		BREATHING APPARATUS	
FIRE EXTINGUISHER	X	EEBD	

Dengan ini menyatakan bahwa Alat Pemadam Kebakaran di bawah ini telah diperiksa, diservice dan diisi ulang sesuai dengan Inspector Keselamatan Pelayaran dan Standard Pabrik.


This is to certify that Fire Extinguisher has been Inspected, Serviced and Refilled according to requirement from ship's authorities and factory.

We quarranted for one year, since this certificate Issued, accordingly :

The Next Inspection : NOVEMBER 3rd, 2026
Pemeriksaan Berikutnya

Surabaya, NOVEMBER 3rd, 2025
CV. ROSE MARINE




(SUWONDO)
SURVEYOR



CV.ROSE MARINE

Re-Inspection Inflatable Liferaft, Fire Extinguisher, Epirb, SART and General Supply
Jl. Ikan Duyung No. 10 Surabaya Tlp. 081331221631
E-mail : slzy.ahmad@yahoo.co.id, cv.rosemarine.admn@gmail.com



SURVEY REPORT PORTABLE FIRE EXTINGUISHER

No : 357/FE-RM/XI/2024

Nama Kapal : CB. PAN MARINE 11

Name of Ship

Pemilik dan Alamat : PT. PAN MARITIME WIRA PAWITRA

Owner And addres Indonesia

Description of working code

1. Inspection	3. Hydrotatic Test	5. Repainted	7. New Supply
2. Refilling	4. Labeling	6. Repaired	

Item	MODEL	VOLUME	QUANTITY	REMARKS
1.	FOAM AFFF	45,0 Ltr	1 Cyl	1,4
2.	FOAM AFFF	9,0 Ltr	8 Cyl	2,4,5
3.	DRY POWDER	6,0 Kgs	1 Cyl	2,4,5
4.	DRY POWDER	4,5 Kgs	3 Cyl	2,4,5
5.	Co2	5,0 Kgs	2 Cyl	2,4,5
6.				
7.				
8.				
9.				
10.				
11.				
12.				
13.				
14.				
15.				
16.				
17.				
18.				
19.				
20.				

The Next Inspection : NOVEMBER 3rd, 2026
Pemeriksaan Berikutnya

Sumenep, NOVEMBER 3rd, 2025

CV. ROSE MARINE



(SUWONDO)
SURVEYOR



CV. ROSE MARINE

Re-Inspection Inflatable Liferaft, Fire Extinguisher, Epirb, SART and General Supply
Jl. Ikan Duyung No. 10 Surabaya Tlp. 081331221631
E-mail : sby.ahmad@yahoo.co.id, cv.rosemarine.admn@gmail.com



Re-inspection Certificate

SCBA - EEBD

No : 359/BA-EEBD-RM/XI/2025

Nama Kapal : CB. PAN MARINE 11
Name of Ship
Pemilik dan Alamat : PT. PAN MARITIME WIRA PAWITRA
Owner And address Indonesia
Port of Service : SUMENEP

TYPE OF SERVICE PERFORMED

Co2 SYSTEM		BREATHING APPARATUS	X
FIRE EXTINGUISHER		EEBD	X

Dengan ini menyatakan bahwa Alat Pemadam Kebakaran di bawah ini telah diperiksa, diservice dan diisi ulang sesuai dengan Inspector Keselamatan Pelayaran dan Standard Pabrik.

This is to certify that Fire Extinguisher has been Inspected, Serviced and Refilled according to requirement from ship's authorities and factory.

We quarranted for one year, since this certificate Issued, accordingly :

The Next Inspection : NOVEMBER 3rd, 2026
Pemeriksaan Berikutnya

Sumenep, NOVEMBER 3rd, 2025
CV. ROSE MARINE



(SUWONDO)
SURVEYOR



CV. ROSE MARINE

Re-Inspection Inflatable Liferaft, Fire Extinguisher, Epirb, SART and General Supply
Jl. Ikan Duyung No. 10 Surabaya Tlp. 081331221531
E-mail : sby.ahmad@yahoo.co.id, cv.rosemarine.admn@gmail.com



SURVEY REPORT PORTABLE SCBA-EEBD

No : 359/BA-EEBD/RM/XI/2025

Nama Kapal : CB. PAN MARINE 11

Name of Ship

Pemilik dan Alamat : PT. PAN MARITIME WIRA PAWITRA

Owner And address Indonesia

Description of working code

1. Inspection

3. Hydrotatic Test

5. Repainted

7. New Supply

2. Refilling

4. Labeling

6. Repaired

Item	MODEL	VOLUME	QUANTITY	REMARKS
1.	EEBD	150,0 Bar	2 Cyl	2,4,5
2.	SCBA	150,0 Bar	2 Cyl	2,4,5
3.	SCBA	200,0 Bar	1 Cyl	2,4,5
4.				
5.				
6.				
7.				
8.				
9.				
10.				
11.				
12.				
13.				
14.				
15.				
16.				
17.				
18.				
19.				
20.				

The Next Inspection

: NOVEMBER 3rd, 2026

Pemeriksaan Berikutnya

Sumenep, NOVEMBER 3rd, 2025

CV. ROSE MARINE

Mengetahui

An. Kepala Kantor Wilayah
dan Dinas Pelabuhan Kelas IV Kalianget



(Signature of Suwondo)

**(SUWONDO)
SURVEYOR**