



PT. MULIA SAFETY SERVICE



Head Office : Bumi Wanamukti H1/19, Sambiroto, Tembalang, Semarang 50276

Branch : Batam - Banten - Jakarta - Tegal - Semarang - Jepara - Surabaya - Makassar - Ambon - Luwuk
Telp/Fax : 02925150543 - Call & WA : 0811274443 - Email : cs@muliaservice.id, www.muliaservice.id



CERTIFICATE OF RE-INSPECTION

Certificate No.: 404/ILR/MSS-TGU/IX/2025

This is to certify that the liferaft detailed below has been surveyed, controlled and tested in compliance with requirement from :
and the manufacturer and in accordance with IMO Resolution : A.761 (18)

Inflatable Liferaft

Identification :	Type : KHA-15	Capacity : 15 PERSONS	Serial No. : 10826	Date Of Manufacture : DEC 2018
	Merk : SHANGHAI YOULONG RUBBER	Length of painter : 25 m/inside 1 m/outside	Max. Stowage Height : 18 m	

Cylinders :	Serial Number :	Contents CO ₂ :	Contents N ₂ :	Latest Hyd. Test :
	043393	8.640 KG	1.850 KG	-
	043926	8.640 KG	1.850 KG	-

Equipment :	Unit :	Type :	Serial No :	Expiry Date :
	Emergency Pack :	SOLAS "A" PACK	10826	05 - 2028
	EPIRB :	-	-	-
	HRU test :	-	-	-
	Radar Reflector :	N/A	N/A	N/A
	First Aid Kit :	BOX	N/A	09 - 2026

Tests :	NAP-test :	Gas inflation test :	Floor Seam test :	Load test davit launched :
	Yes/No: NO	Yes/No: NO	Yes/No: NO	Yes/No: NO
	Latest Test* : -	Latest Test* : -	Latest Test* : -	Latest Test* : -

*Latest test date (month / year)

Verification :	Date Of Service : SEPT 04, 2025	Service station name and No : PT. MULIA SAFETY SERVICE	Next Service Date : SEPT 04, 2026
----------------	---	--	---

National Marine authority ID No.	Remarks/modification : INFLATABLE LIFERAFT IN GOOD CONDITION
-------------------------------------	--

This inflatable liferaft requires servicing 12 month from the latest inspection date in accordance with the SOLAS regulation.

Name of ship : KM. BAHTERA SEVA - III
Name Of Ship/Owner : BANK RAKYAT INDONESIA
IMO Number : 9897626
International call signal : YB 7703





PT. MULIA SAFETY SERVICE

Head Office : Bumi Wanamukti H1/19, Sambiroto, Tembalang, Semarang 50276

Branch : Tanjung Uban - Banten - Jakarta - Tegal - Semarang - Surabaya - Makassar - Ambon - Luwuk

Telp/Fax : 02925150543 - Call & WA : 0811274443 - Email : cs@muliaservice.id, www.muliaservice.id



LIFERAFT SERVICE REPORT

in Accordance to IMO Resolution MSC.388(94) Amendment to Resolution A.761(18)

Certificate No. 404/ILR/MSS-TGU/IX/2025

GENERAL PARTICULARS	
Name of Ship	: KM. BAHTERA SEVA - III
Port of Registry	: INDONESIA / MAKASSAR
IMO-No.	: 9897626
Call Sign	: YB 7703
Class	: BKI
MMSI No	: 525500394
Gross Tonnage	: 150
Date of Service	: SEPTEMBER 04, 2025
Kind of Service	
☒ Annual ☐ 5 Yearly ☐ Repair	
Remarks:	
LIFERAFT IN GOOD CONDITION	

Liferaft Mark :	SHANGHAI YOULONG RUBBER	TYPE of Liferaft :	KHA-15
Serial Number :	10826	Capacity :	15 PERSONS
MFG Date :	DECEMBER 2018	Customer :	BANK RAKYAT INDONESIA

CHECKLIST ITEM	OK/ RN/ NA	CHECKLIST ITEM	OK/ RN/ NA	CHECKLIST ITEM	OK/ RN/ NA
* CONTAINER SHELL	-	Inflation Valve, Hose	NA	Repair Kit	OK
Labels/Marking	RN	"T/Y" Piece Connector	OK	Leak Stoppers	OK
Handling Beckets	RN	Protection Pads	OK	Sponges	OK
* Gasket/Strap/Packing List	OK	CO2 Cylinder (s)	OK	Bailers	OK
Painter Line	OK	Operating Cable & Conduit	OK	Spare Sea Anchor	OK
ID Container	NA	Operating Head	OK	Torch, Signaling	OK
* Valise Fabric/ Plastic	NA			Spare Batteries	RN
Eyelets	OK	SURVEY OF INTERIOR		Whistle	OK
Painter Line Pockets	OK	Bouyancies, Fabric	OK	Fishing Kit	OK
Bursting Band	OK	Safety Relief Valves	OK	Can Opener (s)	OK
Strapping	RN	Grabline & patches/loops	OK	Paddles	OK
		Thwart, Fabric	OK	Spare Bulb for Torch	OK
SURVEY OF EXTERIOR		Deflation Plugs/Valve	OK	Drinking Vessel	OK
Bouyancies Fabric	OK	Arches, Fabric	OK	Seasickness Bags	OK
Inlet Valves	OK	Center Column, Fabric	OK	Signal Mirror	OK
Deflation Plugs/ Valves	OK	Light Battery	RN	Manual Survival Book	OK
Safety Relief Valve	OK	Interior Lighting System	OK	Rescue Signal Table	NA
Boarding Ramp	OK	Topping up Valves	OK	Thermal Protective Aids	OK
Boarding Ladders	OK	Inner Canopy, Fabric	OK	Radar Reflector	OK
Towing Bridie/ Patch	OK	Rainwater Catchment	OK	Dye Marker	NA
Lifeline and Patches	OK	Blowing Port (s)	OK	EMERGENCY PACK	
Outer Canopy Fabric	OK	Aerial Sleeve	OK	Food Ration (15 Pack)	OK
Recto Reflective Tape	OK	Inner Floor, Fabric	OK	Exp. Date 05 - 2028	OK
Seam and Taping	OK	Topping up Valves	OK	Drinking Water (45 Pack)	OK
Rain Water Catchment	OK	Deflation Up Valves	OK	Exp. Date 05 - 2028	OK
Exterior Lighting System	OK	Emergency pack Loops/Patch	OK	Smoke Signal (2 PCS)	OK
Arch Deflation Valve	OK	Aerial Socket/Tie-Tapes	OK	Exp. Date 08 - 2026	OK
Entrance Sleeves	OK	Floor Reds	OK	Parachute Signal (4 PCS)	OK
Outer Floor, Fabric	OK	Rescue Line and Quoit	OK	Exp. Date 08 - 2026	OK
Righting Strap	OK	Knife Sheath	OK	Red hand Flares (6 PCS)	OK
Stabilishing Pockets	OK	Sea Anchor	OK	Exp. Date 08 - 2026	OK
Cylinder Pockets (s)	OK	ACCESSORY BAG		First Aid Kit (1 PCS)	OK
Sea - Cell	OK	Bellows or Pump	OK	Exp. Date 09 - 2026	RN
Painter Lashing/Stowage	OK	Light Stick	NA	Anti Seasickness (90 TAB)	OK

(DKF) Load Test Davit Launch and Raft	NA	Glue for Repair Kit	OK	Exp. Date 09 - 2026	RN
RN = Renew, NA = Not Applicable					

RAFT AND CYLINDER TEST									
PRESSURE TEST	Start			Finish			Pressure	Safety Valves	
	Time	Temp (°C)	Pressure (mmHg)	Time	Temp (°C)	Pressure (mmHg)	Drop (mmHg)	Blow off (mmHg)	Reseat (mmHg)
Upper Buoyancy	09.15	29 °C	103	10.15	29 °C	102	1	114	103
Lower Buoyancy	09.30	29 °C	104	10.30	29 °C	103	1	110	104
Floor	-								
Canopy	-								
GAS CYLINDER TEST	Cyl No:	Mfg. Date	Change Date	Weight Of Cyl. Kg	Weight Of CO2 Kg	Weight Of N2 Kg	Total W. kg		
Cylinder No. 1	043992	-	-	-	8.640	1.850	12.680		
Cylinder No. 2	043925	-	-	-	8.640	1.850	12.680		
DAVID LAUNCHABLE RAFT		REMARK	Res A 761 (18)		REMARK		DATE		
Load Test Date:		-	WP - TEST		YES		09 - 2025		
Suspension Strap/Patches		-	FS - TEST		NO		-		
Shackle		-	NAP - TEST		NO		-		
Steering Line with Patches		-	GI - TEST		NO		-		
Bowsing Line with Patches		-							
Container Line Incl. Pocket		-							
Pocket for Steering/Bowsing Line		-							
Remarks:									

Frequency of test

Servicing Intervals	Test Methods
End of first year	WP test
End of second year	WP test
End of third year	WP test
End of fourth year	WP test
End of fifth year	GI test
End of sixth year	WP test
End of seventh year	WP test
End of eighth year	WP test
End of ninth year	WP test
End of tenth year	GI test + FS
End of fourteenth year	NAP test + FS
Fifteenth year	GI test + NAP + FS
Sixteenth to nineteenth year	NAP test + FS
Twentieth year	GI test + NAP + FS
Twenty-first to twenty-fourth year	NAP test + FS
Twenty fifth year onwards	GI test + NAP + FS

Keterangan:

- NA = Necessary additional pressure test
- WP = Working pressure (compressed air)
- GI = Gas Inflation (fitted gas)
- FS = Floor Seam



(tanda tangan surveyor dan stempel perusahaan)

Surveyor

Next Inspection Date : SEPTEMBER 04, 2026

Catatan:

- Syahbandar berhak tidak menandatangani *service report* ini apabila *service station* tidak melampirkan **SPK aktif** terkait liferaft yang diterbitkan oleh BTKP